

CARSMITH PTE LTD

Bartley Biz Centre, 13 Kaki Bukit Road 4, #01-20 Singapore 417807

Tel: +65 9091 0000 / Email @ claims@carsmith.biz

Car Number: GBK576Z

Date: 15/11/2021

Model : Toyota Hiace

Damaged Area: (Rear Portion)

Parts / Material :

1	Rear bumper	\$ 1,158.40	de
2	Rear bumper side retainer @ SGD 132.00	\$ RH 264.00	LH de
3	Rear bumper bracket @ 98.00	\$ 196.00	X
4	Rear bumper centre inner step bracket	\$ 276.80	bt
5	Rear bumper corner N/S	\$ 195.20	de
6	Rear taillamp N/S	\$ 994.80	ana
7	Rear tailgate	\$ 2,150.40	bt
8	Rear tailgate logo	\$ 94.20	ner
9	Rear tailgate emblem sticker (Hiace)	\$ 75.60	ner
10	Rear tailgate emblem sticker (Wordings w/1200KG)	\$ 76.40	ner
11	Rear tailgate glass inner sponge seal	\$ 98.60	ner
12	Rear tailgate inner trimboard	\$ 245.70	X
13	Rear tailgate inner lock	\$ 482.50	bt
14	Rear tailgate inner lock garnish	\$ 72.40	ana
15	Rear tailgate weather strip	\$ 395.80	cut
16	Rear end panel top garnish trim	\$ 245.20	bt
17	Rear end panel inner	\$ 685.40	Kp
18	Rear end panel outer	\$ 672.30	bt
19	Rear end panel	\$ 1,274.00	X
20	Rear end panel top garnish	\$ 417.00	X
21	Rear spare tyre carrier	\$ 326.80	bt

Parts : \$ 10,397.50

Less Parts 25% : \$ 2,599.37

Total Parts : \$ 7,798.12

Special Net Items :

Sundries	\$ 50.00	X
Rear tailgate sticker (70 km)	\$ 45.00	ner
Rear tailgate sticker (8 pax)	\$ 45.00	ner
Rear tailgate glass sealant	\$ 80.00	60ne
Rear end panel sealant	\$ 60.00	40ne
Rear bumper clips	\$ 50.00	30ne
Reverse sensor	\$ 250.00	202nu

Total S/N Parts : \$ 580.00

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas (@ SGD 300.00 per day)	\$ 1,400.00 700
To Putty, Spray Paint on Affected Accident Areas (@ SGD 300.00 per panel)	\$ 1,400.00 800
To Check & Re-Connect all electrical wiring	\$ 50.00 30
To Transfer Tailgate Attachment, Trims, Garnish to Facilitate Repairs	\$ 150.00 60
To Remove & Install Rear Tailgate Glass	\$ 150.00 120
To Re-position, Drill & Align Reverse Sensor	\$ 150.00 30
To Transfer Rear Compartment Trims, Garnish to Facilitate Repairs	\$ 150.00 60
To Conduct Water Seepage Test	\$ 150.00 30
To Rust Proof Affected Areas	\$ 200.00 30
Total Labour :	\$ 3,800.00

TOTAL PARTS :	\$ 7,798.12
TOTAL SPECIAL NET ITEM :	\$ 580.00
TOTAL LABOUR :	\$ 3,800.00
TOTAL REPAIR COST :	\$ 12,178.12

Tanfer 97495749
WP 15/11/21
US Resurvey after repair.
06 days
tanfer@lkhands.com

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: