

# CARSMITH PTE LTD

Bartley Biz Centre, 13 Kaki Bukit Road 4, #01-20 Singapore 417807

Tel: +65 9091 0000 / Email @ claims@carsmith.biz

Car Number: GBK576Z

Date: 15/11/2021

Model : Toyota Hiace

Damaged Area: (Rear Portion)

## Parts / Material :

1	Rear bumper	374.40	\$	1,158.40	de	
2	Rear bumper side retainer @ SGD 132.00	110	nm	\$RHX 264.00	LH de	
3	Rear bumper bracket @ 98.00		\$	196.00	Xnm	
4	Rear bumper centre inner step bracket	227.50	\$	276.80	bt	
5	Rear bumper corner N/S	104.70	\$	195.20	de	
6	Rear taillamp N/S	399.23	\$	994.80	cna	
7	Rear tailgate	1550	1	\$	2,150.40	bt
8	Rear tailgate logo	51.10	\$	94.20	ner	
9	Rear tailgate emblem sticker (Hiace)	35.70	\$	75.60	ner	
10	Rear tailgate emblem sticker (Wordings w/1200KG)	50	\$	76.40	ner	
11	Rear tailgate glass inner sponge seal		\$	98.60	ner	
12	Rear tailgate inner trimboard		\$	245.70	Xnm	
13	Rear tailgate inner lock	235	\$	482.50	bt	
14	Rear tailgate inner lock garnish	70.50	\$	72.40	cna	
15	Rear tailgate weather strip	217	\$	395.80	cna	
16	Rear end panel top garnish trim	156.10	\$	245.20	bt	
17	Rear end panel inner		\$	685.40	Rp	
18	Rear end panel outer	400.60	\$	672.30	bt	
19	Rear end panel		\$	1,274.00	Xnm	
20	Rear end panel top garnish		\$	417.00	Xnm	
21	Rear spare tyre carrier	4086.43	250	\$	326.80	bt Xnm

4086.43  
25% 30,6482  
Parts : \$ 10,397.50  
Less Parts 25% : \$ 2,599.37  
Total Parts : \$ 7,798.12

## Special Net Items :

Sundries		\$	50.00	Xnn
Rear tailgate sticker (70 km)	20	\$	45.00	de
Rear tailgate sticker (8 pax)	20	\$	45.00	de
Rear tailgate glass sealant		\$	80.00	60ne
Rear end panel sealant		\$	60.00	40ne
Rear bumper clips		\$	50.00	30ne
Reverse sensor		\$	250.00	202nn
Total S/N Parts :		\$	580.00	

370

**Labour :**

To Remove, Repair & Renew Rear Affected Accident Areas (@ SGD 300.00 per day)	\$	1,400.00	600
To Putty, Spray Paint on Affected Accident Areas (@ SGD 300.00 per panel)	\$	1,400.00	600
To Check & Re-Connect all electrical wiring	\$	50.00	30
To Transfer Tailgate Attachment, Trims, Garnish to Facilitate Repairs	\$	150.00	60
To Remove & Install Rear Tailgate Glass	\$	150.00	120
To Re-position, Drill & Align Reverse Sensor	\$	150.00	30
To Transfer Rear Compartment Trims, Garnish to Facilitate Repairs	\$	150.00	60
To Conduct Water Seepage Test	\$	150.00	30
To Rust Proof Affected Areas	\$	200.00	30
Total Labour :		\$	3,800.00

1560

TOTAL PARTS :	\$	7,798.12
TOTAL SPECIAL NET ITEM :	\$	580.00
TOTAL LABOUR :	\$	3,800.00
TOTAL REPAIR COST :	\$	12,178.12

Tanfer 97495749  
WP 15/11/21  
c/s Resurvey after repair.  
06 days  
tanferi@lkhands.com

3064.82  
370  
1760  
4994.82  
c/s \$4000  
06 days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: