

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 25 Nov 2021

Preliminary Advice

Insured Vehicle No : GBL4508P

TP Vehicle No : SJA4419B

Make : TOYOTA COROLLA

Date of Inspection : 16/11/21

Inspection At : CHENG HOE MOTOR PL

Accident Date : 12/11/2021

Assignment Date : 16/11/2021

Est. Duration of Repair : 6

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,912.50
Revised Amount	:S\$	4,096.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,096.88
Lump Sum Repair	:S\$	3,200.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	25,289.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,711.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .