

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

SJA 4419B
 TP/MSIG

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

ATTN: Motor Claim Department

FAX: 62257402

Estimate No: ES2191104/YISHUN

Date: 16 Nov 2021

Policy No: 5119878611

Veh Reg No: SJA4419B

Make/Model: TOYOTA TOYOTA
 COROLLA AXIO 1.5X A

Chassis No: NZE1416054660

Engine No: 1NZC780784

Reg. Date: 10/12/2007

WS Ref: TP/MSIG
 Claim Type: Third Party
 Accident Date: 12/11/2021
 TP Veh Reg No: GBL4508P

Not Authorised
11 Reg 83200h
Recovery After Pains
8 days

Estimate Repair Cost to Vehicle No :SJA4419B

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	565.20	1 PC	565.20	✓
2 REAR BUMPER LH BRACKET	59.80	1 PC	59.80	✓
3 REAR BUMPER LH SIDE RETAINER	81.76	1 PC	81.76	✓
4 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
5 REAR BOOT	817.53	1 PC	817.53	✓
6 REAR BOOT INNER LOCK	111.83	1 PC	111.83	✓
7 REAR BOOT INNER RUBBER	167.20	1 PC	167.20	50% in
8 REAR BOOT EMBLEM (AXIO)	45.10	1 PC	45.10	✓
9 REAR BOOT EMBLEM	40.10	1 PC	40.10	✓
10 REAR BOOT OUTER GARNISH WITH LOGO	216.50	1 PC	216.50	✓
11 REAR CENTRE PANEL	514.20	1 PC	514.20	✓
12 REAR CENTRE PANEL INNER TOP GARNISH	166.25	1 PC	166.25	✓
13 TAILLAMPS	365.10	2 PCS	730.20	0.5 each
			3,536.67	
		Less 25%	884.17	2,652.50
Special Net				
14 REVERSE SENSOR	200.00	1 SET	200.00	✓
15 REVERSE CAMERA	350.00	1 PC	350.00	✓
			550.00	550.00
Labour				
16 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR COMPARTMENT & REALIGN THE SAME	800.00	1 LA	800.00	700
17 PUTTY & RESPRAY ON REAR PANEL, BOOT, REAR BUMPER, HINGES, COMPARTMENT & REAR AFFECTED AREAS	850.00	1 LA	850.00	800
18 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,710.00	1,710.00

Total S\$ 4,912.50

Add GST @ 7% 343.88

Total Amount Payable S\$ 5,256.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE