

AG (L/Sum)

Juman!

COMFORTDELGRO ENGINEERING PTE LTD

Date: 15.11.2021

Time: 09:08:20

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305494243
REGN NO : SH 7982C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.12.2016
DATE/TIME IN : 13.11.2021 11:30
ACCIDENT DATE : 12.11.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0574-A	PANEL-FENDER LH+	1	663.00	20.00	530.40	bb	
0002 04-01-0103-0593-G	PANEL ASSY-FR DR LH#	1	2,256.40	20.00	1,805.12	Rp	
0003 04-01-0103-0658-G	CAP ASSY-WHEEL HUB	1	^{107.10} 217.20	20.00	173.76	ant	
0004 28-01-0103-0003-A	FRT DOOR LOGO SONATA CTPL	1 N	75.00	2.00-	75.00	ant	845.10
0005 04-01-0103-0639-G	BRACKET-FR BUMPER SIDE LH	1	44.80	20.00	35.84	X an	676.08
						SUB-TOTAL :	2,620.12

JOB NATURE

0000 PB	PANEL BEATING	600.00	350 280	
0001 SP	SPRAYPAINT CHARGE	600.00	500	800
0002 20-00	TUFF COAT ON AFFECTED PARTS.	20.00	X an	
0003 L	TRANSFER DOOR PARTD	120.00	X an	
			SUB-TOTAL : 1,340.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Daikin 97425749 # 2 days
WP
15/11/21 C 450
4/5 Resurvey after repair
transfer c/hair...
2 days