

Hup Ley Huat Motor Spray Painting Services

No.1 Kaki Bukit Ave 6 #01-35 AutoBay, Singapore 417883

TEL: 6746 0674 FAX: 6841 7639

Vehicle No : SJM 865 J

Make: Mitsubishi Lancer EX

Date: 08/03/2021

Spare parts

QTY	List Price	Price (S\$)
1	Rear Bumper	815
1	Rear Bumper Side Retainer LH	60.80
Spare Parts Subtotal		875.80

cut ~~500~~ 500 SN
nec
~~547.72~~ 54.72

Special Nett Items

Qty		
1	Rear bumper clip	50
2	Rear reverse sensor	250
		300

30 nec
200 cut

Labour charges

S/N		(S\$)
1	To tuff coat affected areas	100
2	To spray paint include polishing and waxing on the changed body parts, repair body portions where consistent to the accident	600
3	To provide labour charges, workmanship to realign body structure and damaged consistent to the accident	600
4	To remove and refit. Wiring for rear sensor	120
Labour charges: Subtotal		1420

30
250
250
X nn

1314.72
-20%

ESTIMATES PARTS AND LABOR GRAND TOTAL: 2595.80

= 1051

= 1050

F: LS1050
RD: 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: