


ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SLV 45684*
at Workshop m/s: *Trident Ave*
of: *02-42*
Insured: *SL 33155*
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: *£57k.*
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: *4* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *the chian* *489c*
Vehicle: IN / OUT

Date: _____ Person Contacted: *LTA 29642*

Date / Time Action / Instruction *22/9/21*

Veh No: *SLV 45684* Yr Regn: *29/12/17*
Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA*
Make: *Toyota Corolla Axio Hybrid* *1496*
Colour: *Blue* A/C: *Insured / Std / NI / NA*
Sp Reading: *277083* T/Radio: *Insured / Std / NI / NA*
Eng/No: _____
C/No: *NKE165714422*
Gen. Cond: *Good* / Fair / Poor / Burnt
Steering: *In order* / Jammed / Leaked / Burnt or
Brake: *In order* / Jammed / Leaked / Burnt or
Modi: *Nil* S/Rim / STD A/Rim or
Tyre Size: F: *185/60R15*
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Davanti*

Front: *6* mm Rear: *6* mm
R/Bal. *6* mm R/Bal. *6* mm
L/Bal. *6* mm L/Bal. *6* mm
D.O.A. *13/11/21* D.O.I. *16/11/21*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

30/11/21 c/s 2800 confirmed with the Qion.

Date/Time: File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) ☐ S + RS. ☐ SI

) Photos

) Others

TOTAL

Trident Auto Service Centre Pte Ltd
 8 Kaki Bukit Ave 4, #02-44
 Premier @ Kaki Bukit (Gate 1)
 Singapore 415875
 Tel: 63441918

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way, #09-16 AIG Building
 Singapore 079120

Date : 13/11/2021
Vehicle : SLV 4568U
Make/Model : TOYOTA AXIO HYBRID
ORD : 2017
Chassis : NKE1657144212
ODO : 277083
ACC Date : 13/11/2021

u/s \$2800
 Not Approved
 24h
 16/11/21
 HP 900966
 4 days
 the chean

Estimate			Amount S\$
S/N	Qty	Description & Specification	
<u>List Items</u>			
1	1	Rear boot lid	\$798.50 X
2	1	Rear boot hinges	\$145.80 X
3	1	Rear boot lock	\$185.15 X
4	1	Rear boot rubber	\$211.50 ✓
5	1	Rear boot "AXIO" emblem	\$68.50 —
6	1	Rear boot "CAROLLA" emblem	\$62.60 —
7	1	Rear boot "HYBRID" emblem	\$78.00 ✓
8	1	Rear left taillamp	\$481.30 X
9	1	Rear right taillamp	\$481.30 —
10	1	Rear end panel	\$608.80 —
11	1	Rear end panel inner garnish	\$177.73 —
12	1	Rear bumper	\$1,014.30 —
13	2	Rear bumper top brackets	\$175.80 1P2
14	2	Rear bumper reflectors	\$164.00 X
15	2	Rear bumper side retainers	\$143.80 —
16	1	Rear exhaust muffler	\$985.60 X
Total			\$5,782.68
Less 25%			\$1,445.67
List Total			\$4,337.01
<u>S/Nett Items</u>			
1	1 set	Rear bumper clip	\$80.00 50
2	1 set	Rear number plate with holder	\$60.00 X
3	1 set	Reverse sensor	\$350.00 200
S/Nett Total			\$490.00

- Labour**
- To replace Rear bumper, rear bootlid, end panel to repair and re-align on all accident affected areas
 - To putty and respray on accident portion
 - To check wiring
 - To apply anti-rust corrosion on affected areas

Labour Total \$1,580.00
Grand Total \$6,407.01

LKK Auto Consultants hence notify the Repairs of the following:

- To resurvey before repair spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be recovered and is subject to final approval from Insurance Company

Trident Auto Service Centre Pte Ltd

Acknowledged by Repairs
 Signature:
 Date:

680
 680
 20
 30
 2,275.23
 257
 1931.42
 S/N 250.00
 1330
 3511.42