



Re: Direct Settlement for SLV4568U & SLL3315S (LOD Submission)

 Trident Auto <tridentauto.claims@gmail.com>
To: Jaslin Kok (LKK Auto)

 Reply  Reply All  Forward 

Thu 16/12/2021 12:54 PM

 If there are problems with how this message is displayed, click here to view it in a web browser.
[Click here to download pictures.](#) To help protect your privacy, Outlook prevented automatic download of some pictures in this message.

 8. LOD.pdf
642 KB

Cost of Repair	\$2,800.00 (L/sum)
Loss of Use	\$400.00 (5 days x \$80)
LTA Search	\$7.45
Total	\$3,207.45

Enclosed the relevant documents of our client's claims.

Please look into this matter and revert for the liability clearance and settlement as soon as possible

Trident Auto Service Centre Pte Ltd

8 Kaki Bukit Ave 4, #02-44
Premier @ Kaki Bukit (Gate 1)
Singapore 415875
Tel: 63441918

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way, #09-16 AIG Building
Singapore 079120

Date : 13/11/2021
Vehicle : SLV4568U
Make/Model : TOYOTA AXIO HYBRID
ORD : 2017
Chassis : NKE1657144212
ODO : 277083
ACC Date : 13/11/2021

Final Invoice

S/N	Qty	Description & Specification	Amount
List Items			
4	1	Rear boot rubber	\$211.50
5	1	Rear boot "AXIO" emblem	\$68.50
6	1	Rear boot "CAROLLA" emblem	\$62.60
7	1	Rear boot "HYBRID" emblem	\$78.00
9	1	Rear right taillamp	\$481.30
10	1	Rear end panel	\$608.80
11	1	Rear end panel inner garnish	\$177.73
12	1	Rear bumper	\$655.10
13	1	Rear bumper top brackets	\$87.90
15	2	Rear bumper side retainers	\$143.80
Total			\$2,575.23
Less 25%			\$643.81
List Total			\$1,931.42
S/Nett Items			
1	1 set	Rear bumper clip	\$50.00
3	1 set	Reverse sensor	\$200.00
S/Nett Total			\$250.00
Labour			
1		To replace Rear bumper, rear bootlid, end panel to repair and re-align on all accident affected areas	\$600.00
2		To putty and respray on accident portion	\$680.00
3		To check wiring	\$20.00
4		To apply anti-rust corrosion on affected areas	\$30.00
Labour Total			\$1,330.00
Grand Total			\$3,511.42
L/S LESS 20%			\$702.28
L/S GRAND TOTAL			\$2,809.14
FINALIZE AMOUNT			\$2,800.00

Trident Auto Service Centre Pte Ltd



SLV4568U

TRIDENT AUTO SERVICE CENTRE PTE LTD

8 Kaki Bukit Ave 4, #02-44 Premier @ Kaki Bukit (Gate 1)
Singapore 415875

AUTHORIZATION TO ACT

I, SH AUTO RENTAL AND LEASING PTE LTD ("the third party claimant")
of 8, KAKI BUKIT AVE 4, #02-42 Premier @ Kaki Bukit (S) 415875
(address),
owner of SLV4568U (vehicle no.) hereby authorize Trident Auto Service Centre Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and / or rental and / or loss
of use ("claim") for my vehicle no. SLV4568U that was damaged pursuant to the accident
which occurred on 13/11/2021 (date) along ALIWAL STREET
(location) involving vehicle no. SLL33155 ("the accident").

I further authorize the workshop to sign the discharge voucher on my behalf to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle/s is concerned.

Dated this 15 day of 11 (month) 20 21 (year)




Signed by "the third party claimant"
Policyholder's Signature only
& Company Chop - (if registered under a company)




Signed by "the workshop"

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 15 Nov 2021 / 13:38:47

Receipt Date/Time : 15 Nov 2021 / 13:38:27

Tax Invoice/Receipt

Receipt No. : ITNET-00000-211115-002059

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLL3315S				
As at 13 Nov 2021/11:20:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLL3315S			
	Enquiry Fee	7.00	0.49	7.49
	20211115133731156844			
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	526471XXXXXX4869	eNETS Credit Card		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.