

# FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

## Repair Estimate

Date : 11/11/2021

Reference: SJQ865M

Make: Opel Insignia

To Whom It May Concern

Dear Sir,

RE: VEHICLE.: SJQ 865M

CHASSIS NO.: W0VZT6EB8J1089393

ENGINE NO.: B1173348HAKX0495

Name of insured.: JIMMY LEONARDI LEONG

Date of accident.: 09/11/2021

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

### Parts

No.	Qty	Part Description	Price (SGD)
1	1	Boot lid	2364.00x
2	1	Boot lid Emblem	555.00+
3	1	Boot lid lettering 'INSIGNIA'	167.00+
4	1	Boot lid lettering 'Turbo'	167.00+
5	1	RHR Bootlid Lamp	596.00+
6	1	LHR Bootlid Lamp	596.00+
7	1	RR TAILGATE LOCK	354.00+
8	1	RR TAILGATE LOCK CATCHER - Striker	139.00+
9	1	RR TAILGATE LOCK KEYLESS RECEIVER SENSOR	267.00+
10	1	RR BUMPER	1338.00x
11	1	RR BUMPER TOW COVER	148.00+
12	1	RR BUMPER SIDE RETAINER RH(inner) - Guide	130.00+
13	1	RR BUMPER SIDE RETAINER RH(outer) - Bracket	125.00+
14	1	RR BUMPER CENTER RETAINER	130.00+
15	1	RR BUMPER SIDE RETAINER LH(inner) - Guide	130.00+
16	1	RR BUMPER SIDE RETAINER LH(outer) - Bracket	125.00+
17	1	RR BUMPER LOW BRACKET RH	110.00+
18	1	RR BUMPER LOW BRACKET LH	110.00+
19	1	RR BUMPER REINFORCEMENT	519.00+
20	1	RR BUMPER LOW GARNISH	366.00+
21	4	RR BUMPER REVERSE SENSOR	1120.00+
22	2	RR BUMPER BLIND SPOT SENSOR	510.00+
23	1	RR BUMPER REVERSE SENSOR RUBBER SEAL	14.00+
24	1	RR BUMPER REVERSE SENSOR WIRE HARNESS	410.00+
25	1	RR BUMPER REFLECTOR RH	123.00+
26	1	RR BUMPER REFLECTOR LH	123.00+
27	1	RR BUMPER NUMBER PLATE LAMP	124.00+
28	1	RR BLIND SPOT CONTROL UNIT RH	572.00+
29	1	RR BLIND SPOT CONTROL UNIT BRACKET RH	122.00+
30	1	RR REVERSE CAMERA	531.00+
31	1	RR BUMPER BODY KIT RH	1335.00+
32	1	RR BUMPER BODY KIT LH	1335.00+
33	1	RR TAILLAMP RH	727.00+
34	1	RR TAILLAMP LH	727.00+

Parts Total: 16209.00

Less 10%: 1620.90

Total: 14588.10

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

**Labour**

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2500.00 <i>650</i>
<u>2</u>	Carry out spray painting on accident affected area	2300.00 <i>550</i>
<u>3</u>	To conduct anti rust of under carriage tuff coat	250.00 <i>+</i>
<u>4</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00 <i>+</i>
<u>5</u>	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	250.00 <i>+</i>
<u>6</u>	To remove and refix reverse sensor and conduct test	80.00 <i>✓</i>
<u>7</u>	To conduct transfer of parts from old bootlid to new bootlid	80.00 <i>+</i>
<u>8</u>	To conduct water leakage test after repairs of vehicle	80.00 <i>+</i>
<u>9</u>	Remove and replace reverse camera (Labour)	80.00 <i>+</i>
<u>10</u>	Remove and replace reverse sensor (Labour)	80.00 <i>+</i>

*1280***Labour Total : 5780.00****Others**

<u>No.</u>	<u>Qty</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	10	Rear Number plate & bracket <i>smld</i>	45.00 <i>✓</i>
2	6	Rear bumper clip (set) <i>2</i>	65.00 <i>+</i>
3	12	Inner bootlid Trim Clips <i>12</i>	71.50 <i>+</i>
4	1	Rear end panel insulation seal <i>1</i>	120.00 <i>+</i>

**Other Total: 301.50**

**Total : \$ 20,669.60**  
**7% Gst : \$ 1,446.87**  
**GRAND TOTAL: \$ 22,116.47**

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Adviser

Ronnie Tan

HP : 8298 8933 Fax: 6844 5185

**Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Adrian Li**P/P 12/11/21**02 Days**Total: 1325*



**1st Autoworks Pte Ltd**

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

**TAX INVOICE**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way  
#07-16, Singapore 079120

GST Ref. No: 20-0000274-Z

Vehicle No: SJQ 865M  
Chasis No : W0VZT6EB8J1089393  
Engine No: B1173348HAKX0495

Invoice No:

Invoice Date:

**DESCRIPTION****AMOUNT  
SGD****Labour****Rear**

<u>No.</u>	<u>Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	650.00
<u>2</u>	Carry out spray painting on accident affected area	550.00
<u>3</u>	To remove and refix reverse sensor and conduct test	80.00

Labour Total : 1280.00

**Other**

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	1 Rear Number plate & bracket	45.00

Other Total : 45.00

Total : \$1,325.00  
GST (7%) \$92.75  
**Grand Total: \$1,417.75**

Yours Faithfully,



Ronnie Tan  
Service Advisor  
Tel: 68441985 Fax: 68445185

**E & O E**

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1ST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.