

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

ALGAsia Insured's Veh No : SGK93R
Date of Accident : 11 November 2021

1 Defu Lane 6 Singapore 539365
Tel: 68585151 (24 Hours) Fax: 68580877
GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 13 November 2021

Estimate To Repair SMJ7106B - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7211312

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper <i>Dis</i>	\$ 549.00
02	8 ps	rear bumper clips @ \$3.50 <i>nee</i>	\$ 28.00
03	1 pc	rear bumper centre pad <i>Dis</i>	\$ 189.00
04	1 LC	rear bumper lower <i>cut</i>	\$ 179.00
05	1 pc	rear bumper reverse sensor <i>Shohh</i>	\$ 162.00
06	2 ps	rear bumper side retainer @ \$28.00 <i>11</i>	\$ 56.00
07	2 ps	rear bumper reflector @ \$116.00 <i>015 cre 115 an</i>	\$ 232.00
08	1 pc	rear bumper reinforcement <i>one</i>	\$ <i>341</i> 367.00
09	2 ps	rear bumper bracket @ \$84.00 <i>Best / 111</i>	\$ 168.00
10	2 ps	rear bumper lower bracket @ \$27.00 <i>11</i>	\$ 54.00
11	2 ps	rear bumper top bracket @ \$25.00 <i>11</i>	\$ 50.00
12	6 ps	rear bumper holder @ \$0.00 <i>11</i>	\$ 0.00
13	1 pc	tailgate lid <i>Body</i>	\$ 1,088.00
14	1 pc	tailgate lid lock <i>Shohh</i>	\$ 112.00
15	1 pc	tailgate lid inner garnish <i>11</i>	\$ 153.00
16	1 pc	tailgate lid weatherstrip <i>11</i>	\$ 115.00
17	1 pc	tailgate lid number plate garnish <i>11</i>	\$ 0.00
18	1 pc	tailgate lid number plate garnish chrome <i>11</i>	\$ 95.00
19	1 pc	tailgate lid number plate lamp <i>11</i>	\$ 85.00
20	1 pc	tailgate lid keyless switch <i>11</i>	\$ 115.00
21	1 pc	tailgate lid keyless switch antenna <i>11</i>	\$ 95.00
22	1 pc	tail lamp <i>11</i>	\$ 770.00
23	2 ps	tail lamp clips @ \$6.00 <i>11</i>	\$ 12.00
24	1 pc	rear end panel <i>Body</i>	\$ 611.00
25	1 pc	rear end panel top garnish <i>11</i>	\$ 123.00
26	1 pc	rear boot tools compartment <i>11</i>	\$ 515.00
27	1 pc	rear boot tools compartment floor board top <i>11</i>	\$ 279.00
28	2 ps	rear boot tools compartment floor board side @ \$129.00 <i>11</i>	\$ 258.00
29	1 pc	tailgate lid carens badge <i>nee</i>	\$ 28.00
30	1 pc	tailgate lid CRDi badge <i>nee</i>	\$ 31.00
31	1 pc	tailgate lid centre emblem badge <i>11</i>	\$ 35.00
			\$ 6,554.00
		Less 10 %	\$ 655.40
			\$ 5,898.60
		<u>SPECIAL NETT ITEMS</u>	
32	1 pc	rear licence plate <i>11</i>	\$ 50.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SGK93R
Date of Accident : 11 November 2021

Messrs BIS Motoring Pte Ltd

Date : 13 November 2021

Estimate To Repair SMJ7106B - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7211312

S/No	Quantity	Description	Amount
33	1 pc	<u>SPECIAL NETT ITEMS</u> rear windscreen sealant <i>1pc</i>	\$ 20.00
			\$ 70.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 100.00
02		To remove and refit rear windscreen glass.	\$ 140.00
03		To check electrical lighting concerned.	\$ 80.00
04		To rust-proofing of the affected areas.	\$ 250.00
05		To reinstall of rear bumper parking sensor.	\$ 80.00
06		To transfer of tyre, rim and on wheel balancing.	\$ 100.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
08		Putty and spray painting of the affected portion.	\$ 1,000.00
			\$ 2,750.00
		Total	\$ 8,718.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2- 3717
102
P- 3345.30
S-N- 20
L- 2110
5475.30
203
4380