

SAYLLON-GOBBSTY email: CMINTU @ OWILLOK. COM

19 JURONG PORT ROAD
WESTPOINT AUTOMOTIVE SOLUTIONS
SINGAPORE 619093

TO: AIG

ATTN: MOTOR CLAIMS DEPARTMENT

**OUR REF: GBK2316U** 

YOUR REF: GBK2316U

DATE: 30/10/2021

CREATED BY: SAMUEL KANG CONTACT NUMBER: 9722 2822 VEHICLE NUMBER: GBK2316U

MAKE AND MODEL: TOYOTA HIACE CHASSIS NUMBER: JTFRA3APX08008097

ENGINE NUMBER: 1GD8484785
YEAR OF MANUFACTURE:2019
DATE OF ACCIDENT: 23/10/2021

**CLAIM TYPE: TP** 

**LUMP SUM / PART BY PART** 

**ESTIMATE FOR VEHICLE NUMBER: GBK2316U** 

NO.	DESCRIPTION	QTY		LIST PRICE		
	PARTS					
1	REAR BUMPER SU	1	\$	410.70		
2	REAR SIDE BUMPER SU	1	\$	210.00		
3	REAR TAIL LAMP CA	1	\$	399.40		
4	REAR SIDE BUMPER SUPPORT .	1	\$	85.90		
5	REAR QUARTER PANEL OUTER reful	1	\$	489.40		
6	REAR QUARTER PANEL INNER 🗡	1	\$	780.10		
7	REAR QUARTER WHEEL HOUSING ASSY 🗡	1	\$	588.30		
8	BACK DOOR ORENING REINFORCEMENT	1	\$	789.10		
9	REAR INNER TRIM PANEL 🗡	2	\$	1,237.80		
10	REAR INNER TRIM 🗡	<b>1</b>	\$	1,050.40		
11	REAR SLIDING DOOR ASSY 🗡	2	\$	4,360.80		
12	REAR SIDE DOOR TRIM	1	\$	680.40		
13	REAR FLOOR PANEL	1	\$	1,180.50		
	4	SUBTOTAL:	\$	12,262.80		
	25%	less 20%:	\$	2,452.56		
	P	ARTS TOTAL:	\$	9,810.24		

## **SPECIAL NETT ITEMS**

	CDECIAL		
9	SUNDRIES No.	\$	80.00 20
8	COMPANY STICKER 1	\$	300.00 200
,	REAR FLOOR PANEL MOULDING X	\$	80.00
6	REAR FLOOR PANEL SEALANT	\$	100.00
_		Ş	80.00 🔀
5	REAR SIDE DOOR BRACKET/CLIPS   ✓	<b>7</b>	
4	REAR QUARTER PANEL SEALANT 🗡	Ċ	80.00 X
3	REAR TAIL LAMP CLIPS 🚣 🖊	\$	50.00 20
2	REAR SIDE BUMPER BRACKET/CLIPS 🗡	\$	50.00⊁
1	REAR BUMPER BRACKET CLIPS 1	\$	50.00 30

SPECIAL NETT TOTAL \$

870.00

	١	B	0	L	JF	1
835	172	t i	788			

		, ,
TO REPAIR, REPLACE & ALIGN REAR ACCIDENT DAMAGED AREAS	\$	1,500.00 600
TO PUTTY AND RESPRAY ALL AFFECTED PORTIONS	\$	1,200,00600
TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	\$	100.0030
TO RUST PROOF ACCIEDNT AFFECTED PORTIONS	\$	120.00 🗙
TO R&R REAR LUGGAGE COMPARTMENT	\$	20.00
TO R&R REAR REVERSE SENSORS AND CHECK FUNCTION	\$	120.00 60
TO CONDUCT WHEEL ALIGNMENT CHECK (BEFORE & AFTER)	\$	100.00
TO R&R REAR IINERTIOR TRIMS TO FACILITATE REPAIRS	\$	100.00 🗡
TO CHECK WATER SEEPAGE AFTER REPAIRS	\$	100.00 🗶
		,

LABOUR TOTAL: 3,360.00 **GRAND TOTAL:** \$ 4,304.30

**BEFORE 7% GST** 

SURVEYOR NAME: RASUL - HP 90010068

DATE OF 1ST SURVEY: 16/11/21 @ 1100

TIME OF 1ST SURVEY: DATE OF 2ND SURVEY: TIME OF 2ND SURVEY:

NUMBER OF REPAIR DAYS APPROVED: 4 days - 12 4/8
FINALISED AMOUNT:

Rosnry before after
paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: