

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Liu Chun Cheong

Date: 18 Nov 2021

Preliminary Advice

Vehicle No	: SFG9981B	Accident Date	: 11/11/2021
Make	: LEXUS RX270	Policy No.	: MPC20P00200400
Assignment Date	: 15/11/2021	Excess	: S\$0.00
Date of Inspection	: 17/11/2021	Est. Duration of Repair	: 5
Inspection At	: RICARDO AUTO CENTRE PTE LTD (HQ) 160 SIN MING DRIVE, #02-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,114.10
Revised Amount	:S\$	4,602.80
Check Items (Estimated)	:S\$	648.00
Total	:S\$	5,250.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	36,145.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,855.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check items) stated are subject to part prices and labour cost.