

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC20P00200400	Date of Loss:	11/11/2021
Vehicle Reg. No.:	SFG9981B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHONG WAI MENG	Contact No:	+6598522545
Make/Model:	LEXUS RX270, 2.7 (A)	Vehicle Reg. Date:	18/12/2010
Vehicle Colour:	Black	Chassis No:	JTJZA11A002002253
Engine No:	1AR0428671		
Odometer:	280000 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 6

Present Location: **RICARDO AUTO CENTRE PTE LTD (HQ)**

COST OF CLAIMS	Amount
Parts	3,939.10
Miscellaneous Items	45.00
Labour	2,130.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,114.10
+ GST 7.00% (S\$)	427.99
Nett Amount (S\$)	6,542.09

This claim is handled by: GRACE TAN KIAN ANN

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Nov 2021)
 Parts: M1-SUV LEXUS RX270 2.7 (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ricardo Auto Centre Pte Ltd/SFG9981B/15/11/2021 15:57
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET / BT	0.00	0.00	✓ *550.00 F
2	1		*BONNET SEAL X NN	0.00	0.00	*25.00 F
3	1		*RADIATOR GRILLE / BR	0.00	0.00	✓ *260.00 F
4	1		*FRONT BUMPER / RR	0.00	0.00	✓ *280.00 F
5	1		*FRONT BUMPER SPONGE / CRA	0.00	0.00	✓ *60.00 F
6	1		*FRONT BUMPER REINFORCEMENT / BT	0.00	0.00	✓ *220.00 F
7	2		*FRONT BUMPER SIDE RETAINER RH & LH / 1 PC / RR	0.00	0.00	40 *76.00 F
8	1		*FRONT BUMPER NUMBER PLATE BRACKET / RR	0.00	0.00	✓ *55.00 F
9	10		*FRONT BUMPER CLIPS / RR	0.00	0.00	10 *15.00 F
10	2		*HEADLAMP RH & LH / CRA	0.00	0.00	✓ *1,500.00 F
11	1		*SEAL, HOOD TO RADIATOR GRILLE / XNN	0.00	0.00	*25.00 F
12	10		*CLIPS, RADIATOR COVER / RR	0.00	0.00	12 *15.00 F
13	1		*FRONT SUPPORT PANEL X Repair	0.00	0.00	*500.00 F
Sub Total (S\$)						3,581.00 2987
+ Margin on L,N Items 10.00% (S\$)						358.10
Total Parts (S\$)						3,939.10 3285.7

F=Franchise part.

Ricardo Auto Centre Pte Ltd/SFG9981B/15/11/2021 15:57. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Bonnet lock / BT

Estimates on Miscellaneous Items

No Qty Particulars

<u>Miscellaneous Items</u>			Amount
1	1	FRONT NUMBER PLATE W/HOLDER / BT	45.00
Sub Total (\$\$)			45.00

Estimates on Labour

No Particulars

<u>Labour Items</u>		Lab.Type	Amount
1	TO FOCUS HEADLAMP	New	30.00
2	TO SERVICE AIRCON, RECHARGE AIRCON GAS	New	100.00
3	TO CUT, WELD & STRAIGHTEN FRONT PORTION OF CAR CAUSED BY ACCIDENT, ADJUST & REPLACE DAMAGE PARTS.	New	500 900.00
4	TO SPRAY PAINT ON REPAIRED AREAS	New	1,100.00
Gross Labour Cost (\$\$)			1380 2,130.00

Ricardo Auto Centre Pte Ltd/SFG9981B/15/11/2021 15:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

TOTAL 5172.7

4-5 Days.
part by part.
before paint photos.
Caro Q&A
Not Authorized.
17/11/21
Excess: TRA.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature.

Date:

(SUPPLEMENTARY)

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC20P00200400	Date of Loss:	11/11/2021
Vehicle Reg. No.:	SFG9981B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHONG WAI MENG	Contact No:	+6598522545
Make/Model:	LEXUS RX270, 2.7 (A)	Vehicle Reg. Date:	18/12/2010
Vehicle Colour:	Black	Chassis No:	JTJZA11A002002253
Engine No:	1AR0428671		
Odometer:	216588 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	RICARDO AUTO CENTRE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	297.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	297.00
+ GST 7.00% (S\$)	20.79
Nett Amount (S\$)	317.79
+ Previous Estimates (S\$)	6,542.09
Claim Total (S\$)	6,859.88

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2021)

Parts: M1-SUV LEXUS RX270 2.7 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ricardo Auto Centre Pte Ltd/SFG9981B/23/11/2021 10:10

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP ACTUATOR LH ✓ BR	0.00	0.00	*200.00 F
2	1		*FRONT BUMPER LOWER GRILLE ✓ BR	0.00	0.00	*70.00 F

F=Franchise part.

Sub Total (S\$)	270.00
+ Margin on L,N Items 10.00% (S\$)	27.00
Total Parts (S\$)	297.00

Ricardo Auto Centre Pte Ltd/SFG9981B/23/11/2021 10:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Ricardo Auto Centre Pte Ltd/SFG9981B/23/11/2021 10:10. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

(SUPPLEMENTARY)

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC20P00200400	Date of Loss:	11/11/2021
Vehicle Reg. No.:	SFG9981B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHONG WAI MENG	Contact No:	+6598522545
Make/Model:	LEXUS RX270, 2.7 (A)	Vehicle Reg. Date:	18/12/2010
Vehicle Colour:	Black	Chassis No:	JTJZA11A002002253
Engine No:	1AR0428671		
Odometer:	216588 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	RICARDO AUTO CENTRE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	165.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	165.00
+ GST 7.00% (S\$)	11.55
Nett Amount (S\$)	176.55
+ Previous Estimates (S\$)	6,859.88
Claim Total (S\$)	7,036.43

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Nov 2021)

Parts: M1-SUV LEXUS RX270 2.7 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ricardo Auto Centre Pte Ltd/SFG9981B/26/11/2021 11:54

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP HID BULB LH ✓ NW	0.00	0.00	*150.00 F
						Sub Total (S\$)
						150.00
						+ Margin on L,N Items 10.00% (S\$)
						15.00
						Total Parts (S\$)
						165.00

Ricardo Auto Centre Pte Ltd/SFG9981B/26/11/2021 11:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Ricardo Auto Centre Pte Ltd/SFG9981B/26/11/2021 11:54. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >