

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

12/11/2021

01-43

TP Chiam

Singapore 417883

Jaslin

Accident date : 11/11/2021

Estimated repair cost for vehicle no: SMP2857T TOYOTA CAMRY 2.5 AUTO

CHASSIS: MR053AK5004011978 (2016)

S/N	Qty	Items	U/price	Amount
1	1	REAR BOOTLID <i>Cracked</i>	\$1,031.70	\$1,031.70 ✓
2	1	REAR BOOTLID LOCK <i>Dented</i>	\$570.10	\$570.10 ✓ 291
3	1	REAR BOOTLID LOCK DETECTOR <i>Cracked</i>	\$230.90	\$230.90 ✓
4	1	REAR BOOTLID OUTER MOULDING <i>2 new</i>	\$378.90	\$378.90 +
5	1	REAR BOOTLID CHROME MOULDING <i>1 new</i>	\$378.90	\$378.90 +
6	2	REAR BOOTLID HINGE GARNISH <i>3 new</i>	\$320.80	\$641.60 +
7	1	REAR BOOTLID INNER TRIM <i>1 new</i>	\$789.10	\$789.10 +
8	1	REAR BUMPER <i>Dented</i>	\$589.40	\$589.40 ✓
9	1	REAR BUMPER REINFORCEMENT <i>Dented</i>	\$370.40	\$370.40 ✓
10	2	REAR BUMPER SIDE RETAINER <i>new</i>	\$189.10	\$378.20 - 98.
11	1	REAR BUMPER LOWER GARNISH <i>new torn</i>	\$372.60	\$372.60 ✓ 253
12	1	REAR END PANEL <i>Dented</i>	\$619.60	\$619.60 ✓
13	1	REAR END PANEL TOP GARNISH <i>cracked</i>	\$341.50	\$341.50 ✓ 295
14	4	REAR KEYLESS SENSOR <i>Dented 2 pieces dented</i>	\$210.50	\$842.00 - 420.421.
15	1	REAR KEYLESS SENSOR WIRE HARNESS <i>new</i>	\$180.60	\$180.60 +
16	1	REAR KEYLESS BUZZER <i>1 new</i>	\$280.90	\$280.90 + 487
17	2	REAR TAILLAMP <i>RA cut</i>	\$570.90	\$1,141.80 - 570.90
18	2	REAR TAILLAMP LOWER BRACKET	\$180.20	\$360.40 +
19	2	REAR FENDER INNER TRIM BOARD	\$829.40	\$1,658.80 +
20	1	REAR SPARE TYRE COMPARTMENT PANEL	\$708.90	\$708.90 +
21	2	REAR SPARE TYRE TOP BOARD	\$589.60	\$589.60 +
22	1	REAR EXHUAST MUFFLER	\$1,061.30	\$1,061.30 +
23	1	REAR EXHUAST MUFFLER SHIELD	\$278.90	\$278.90 +
24	2	REAR EXHUAST MUFFLER RUBBER MOUNTING <i>1 new</i>	\$61.20	\$122.40 +

Spare Tyre Panel Undercover *255* ✓
Dented

TOTAL : \$13,918.50
 LESS 25 % \$3,479.63
 SUB-TOTAL : \$10,438.88

4936.

3702

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR REVERSE CAMERA <i>MR MR</i>	\$ 800.00	\$ 800.00 <i>+</i>
2	1	REAR BUMPER CLIPS <i>MR</i>	\$ 80.00	\$ 80.00 <i>-30</i>
3	1	REAR FENDER INNER TRIM BOARD CLIPS <i>MR MR</i>	\$ 40.00	\$ 40.00 <i>+</i>
4	1	REAR END PANEL CLIPS <i>MR</i>	\$ 50.00	\$ 50.00 <i>-20</i>
5	2	REAR BOOTLID HINGE GARNISH CLIPS <i>MR MR</i>	\$ 30.00	\$ 30.00 <i>+</i>
6	1	REAR END PANEL SEALANT <i>MR</i>	\$ 100.00	\$ 100.00 <i>-60</i>
7	1	FRONT BUMPER CLIPS <i>MR MR</i>	\$ 80.00	\$ 80.00 <i>+</i>

110

TOTAL: \$1,180.00

TOTAL PARTS: \$11,618.88

Labour charges

1	LABOUR FOR PANEL BEATING	\$2,000.00 <i>900</i>
2	LABOUR FOR SPRAYPAINTING	<i>1950</i> \$1,500.00 <i>900</i>
3	LABOUR FOR REMOVE / RENEW & TRANSFER REAR BOOTLID FITTING	\$250.00 <i>60</i>
4	WIRING CHECK	\$80.00 <i>30</i>
5	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	\$300.00 <i>60</i>

Subtotal :- \$4,130.00

Total:- \$15,748.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian King
2/s 12/11/21
06 Pages

Total: 5762.

2/s: 4.6k.

4.6k