

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 21 Apr 2022

Preliminary Advice

Insured : GBK6882A

Vehicle No

TP Vehicle : FBR5171M
No

Accident Date : 13/11/2021

Make : YAMAHA AEROX 155A

Assignment Date : 15/11/2021

Date of : 16/11/2021

Est. Duration of : 3
Repair

Inspection

Inspection At : SG 98 MOTOR PTE LTD (HQ)
BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21
SINGAPORE 569622

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,813.50
Revised Amount	:S\$	1,757.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,757.00

Lump Sum Repair	:S\$	1,400.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair

:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.