

Date: 11-11-2021
Vehicle: SMD837C
Model: TOYOTA SIENTA
Chassis: NHP170-7108820
Reg.Year: 2018

Not Notified
11 Sep 3
Perunay After Paint
16-18 days

Third Party Insurer: CHINA TAIPING
Third Party Veh No: GBK5912D
Date of Accident: 11-11-2021
Estimator: ARY CHUA
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		Bu \$450.00
2	RHF HEADLAMP	1		\$990.00
3	LHF HEADLAMP	1	my CM	\$990.00
4	FRONT BONNET	1		R \$890.00
5	BONNET HINGE RH	1		Di \$70.00
6	BONNET HINGE LH	1		Di \$70.00
7	RETAINNER RH	1		Di \$68.00
8	RETAINNER LH	1		Di \$68.00
9	FRONT REINFORCEMENT BEAM	1		\$363.00
10	RADIATOR	1		\$1,080.00
11	A/C CONDENSER	1		\$1,020.00
12	RHF FENDER	1		R \$580.00
13	LHF FENDER	1		R \$580.00
14	FRONT CHROME GRILLE	1		CD \$480.00
15	TOYOTA FRONT LOGO EMBLEM	1		R \$180.00
16	FRONT BASE GARNISH	1		R \$520.00
17	REAR BUMPER	1		R \$654.00
18	REAR BUMPER INNER/LOWER BUMPER	1		R \$543.00
19	RHR CORNER INNER BUMPER	1		R \$383.00
20	LHR CORNER INNER BUMPER	1		R \$383.00
21	REAR TOYOTA EMBLEM	1		R \$168.00
22	RHR TAILGATE LAMP (INNER)	1		CM \$787.00
23	LHR TAILGATE LAMP (INNER)	1		CM \$787.00
24	RHR LAMP UNIT (OUTER)	1		CM \$678.00
25	LHR LAMP UNIT (OUTER)	1		CM \$678.00
26	REAR TAILGATE LID	1		R \$1,281.90
27	REAR WINDSCREEN SIENTA	1	Shatter	\$1,040.00
28	REAR WIPER MOTOR	1		\$685.00
29	REAR WIPER ARM	1		R \$140.00
30	REAR WIPER RUBBER BLADE	1		\$98.00
31	WEATHER STRIP	1		R/L \$168.00
32	REAR WINDSCREEN INNER RUBBER SET	1		\$88.00
33	REAR TOP LISCENCE SIENTA GARNISH	1	my R	\$456.00
34	REAR END PANEL	1		R \$876.00
35	FLOOR REAR PANEL	1		\$676.00
36	REAR TAILGATE LOCK UNIT	1		T \$382.00
37	REAR END PANEL GARNISH	1		\$442.00
38	REAR TAILGATE GARNISH	1		Di \$432.00

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 11-11-2021
Vehicle: SMD837C
Model: TOYOTA SIENTA
Chassis: NHP170-7108820
Reg. Year: 2018

Third Party Insurer: CHINA TAIPING
Third Party Veh No: GBK5912D
Date of Accident: 11-11-2021
Estimator: ARY CHUA
Surveyor:

39	REAR TAILGATE HINGE RH	1		\$123.00	?
40	REAR TAILGATE HINGE LH	1		\$123.00	?
41	REAR TAILGATE ABSORBER RH	1		\$298.00	?
42	REAR TAILGATE ABSORBER LH	1		\$298.00	?
43	SIENTA REAR HYBRID SYNERGY DRIVER EMBLE	1		Re \$66.00	✓
44	RHR INNER GARNISH	1	Dist	\$444.00	✓
45	LHR INNER GARNISH	1		\$456.00	?
46	FLOOR REAR MAT/GARNISH	1		\$345.00	?
47	3RD ROW SEAT FLOOR MAT	1		\$434.00	?
48	FLOOR REAR BATTERY COVER PLASTIC	1		\$240.00	?
49	3RD ROW SEAT CHAIR RH	1		Re \$1,080.00	X
SUB TOTAL				\$24,131.90	
LESS 20%				-\$4,826.38	
PARTS TOTAL				\$19,305.52	

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	COOLANT	2	\$60.00	Re \$120.00	500ml
2	REAR REVERSE SENSOR	2	\$160.00	\$320.00	200ml
3	BUMPER CLIPS	20	\$4.00	Re \$80.00	500ml
4	SEALANT	2	\$60.00	Re \$120.00	500ml
5	REAR FLOOR COVER BATTERY CLIPS	4	\$5.00	\$20.00	?
S/N TOTAL				\$660.00	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST, DISMANTLE ACCIDENT AREAS & ETC. \$3,600.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC. \$2,800.00

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT & REAR BOTH FENDER AREA, ABSORBER, STABILIZER BAR, UNDERCARRIAGE, FUEL TANK, CLEAR SHUTTLE GLASS & ETC. \$1,200.00

LABOUR CHARGES TO DISCONNECT & RECONNECT FRONT WIRING SYSTEM & ETC. TO EFFECT REPAIR AT FRONT ACCIDENT AREAS & ETC. \$500.00

LABOUR CHARGES TO DIAGNOSE FAULTY CODE & RESET MEMORY. \$400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

LABOUR TOTAL \$8,500.00

TOTAL \$28,465.52

Head office
8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1312 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554800
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)
81K To A'Ning Rd Singapore 408924
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Signature:

