

ASS. REG. BY:

REF:

CT2 / 210116491kr

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 876k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 16 days

Res.: Yes or No

Lum Sum: 1.8.12 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMD 837CYr Regn: 07, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Pientoc.c. 1496Colour: M. Silver

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 212583

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: Inter tracSunwide185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 7 mmL/Bal. 9 mmL/Bal. 7 mmD.O.A. 11/11/21D.O.I. 12/11/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 May have BZ30/11 8.23.2021 Carh 31/12/21

P/P \$23,210.61 (pls refer to VIEWS finalisation tab)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Date: 11-11-2021

Vehicle: SMD837C

Model: TOYOTA SIENTA

Chassis: NHP170-7108820

Reg. Year: 2018

Not Notified

Perjury After Paint

823,240.61 *16 days*

ESTIMATE

Third Party Insurer: CHINA TAIPING

Third Party Veh No: GBK5912D

Date of Accident: 11-11-2021

Estimator: ARY CHUA

Surveyor:

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	Bu	\$450.00
2	RHF HEADLAMP	1	mhc nt	\$990.00
3	LHF HEADLAMP	1	mhc nt	\$990.00
4	FRONT BONNET <i>845.10</i>	1	Bu	\$890.00
5	BONNET HINGE RH	1	Dis	\$70.00
6	BONNET HINGE LH	1	Dis	\$70.00
7	RETAINER RH	1	Dis	\$68.00
8	RETAINER LH	1	Dis	\$68.00
9	FRONT REINFORCEMENT BEAM	1	Bu	\$363.00
10	RADIATOR	1	Bu	\$1,080.00
11	A/C CONDENSER	1	Bu	\$1,020.00
12	RHF FENDER	1	R	\$580.00
13	LHF FENDER	1	R	\$580.00
14	FRONT CHROME GRILLE	1	CDA	\$480.00
15	TOYOTA FRONT LOGO EMBLEM <i>63</i>	1	Bu	\$180.00
16	FRONT BASE GARNISH <i>125</i>	1	Bu	\$520.00
17	REAR BUMPER	1	Bu	\$654.00
18	REAR BUMPER INNER/LOWER BUMPER	1	Bu	\$543.00
19	RHR CORNER INNER BUMPER	1	Del	\$383.00
20	LHR CORNER INNER BUMPER	1	Del	\$383.00
21	REAR TOYOTA EMBLEM	1	Bu	\$168.00
22	RHR TAILGATE LAMP (INNER) <i>281.55</i>	1	CDA	\$787.00
23	LHR TAILGATE LAMP (INNER) <i>281.55</i>	1	CDA	\$787.00
24	RHR LAMP UNIT (OUTER) <i>460.50</i>	1	CDA	\$678.00
25	LHR LAMP UNIT (OUTER) <i>460.50</i>	1	CDA	\$678.00
26	REAR TAILGATE LID <i>1086</i>	1	Bu	\$1,281.90
27	REAR WINDSCREEN SIENTA	1	Shatter	\$1,040.00
28	REAR WIPER MOTOR <i>652</i>	1	Tr	\$685.00
29	REAR WIPER ARM	1	Del	\$140.00
30	REAR WIPER RUBBER BLADE	1	W	\$98.00
31	WEATHER STRIP	1	Not/W	\$168.00
32	REAR WINDSCREEN INNER RUBBER SET	1	Bu	\$88.00
33	REAR TOP LISCENCE SIENTA GARNISH	1	mhc Bu	\$456.00
34	REAR END PANEL <i>689.75</i>	1	Bu	\$876.00
35	FLOOR REAR PANEL	1	Bu	\$676.00
36	REAR TAILGATE LOCK UNIT	1	Tr	\$382.00
37	REAR END PANEL GARNISH <i>266</i>	1	CDA	\$442.00
38	REAR TAILGATE GARNISH <i>260.50</i>	1	Dis	\$432.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 11-11-2021
Vehicle: SMD837C
Model: TOYOTA SIENTA
Chassis: NHP170-7108820
Reg.Year: 2018

Third Party Insurer: CHINA TAIPING
Third Party Veh No: GBK5912D
Date of Accident: 11-11-2021
Estimator: ARY CHUA
Surveyor:

39	REAR TAILGATE HINGE RH	1		Di't	\$123.00	2
40	REAR TAILGATE HINGE LH	1		Di't	\$123.00	2
41	REAR TAILGATE ABSORBER RH	1		Pu	\$298.00	2
42	REAR TAILGATE ABSORBER LH	1		Pu	\$298.00	2
43	SIENTA REAR HYBRID SYNERGY DRIVER EMBLE	1		nn	\$66.00	✓
44	RHR INNER GARNISH	1		Di't	\$444.00	✓
45	LHR INNER GARNISH	1		Pu	\$456.00	2
46	FLOOR REAR MAT/GARNISH	1		cm	\$345.00	2
47	3RD ROW SEAT FLOOR MAT	1		Pu	\$434.00	X
48	FLOOR REAR BATTERY COVER PLASTIC	1		cm	\$240.00	2
49	3RD ROW SEAT CHAIR RH	1		Pu	\$1,080.00	X
SUB TOTAL					\$24,131.90	
LESS 20% DIS					-\$4,826.38	
PARTS TOTAL					\$19,305.52	

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	COOLANT	2	\$60.00	nn	\$120.00 501n
2	REAR REVERSE SENSOR	2	\$160.00		\$320.00 2001n
3	BUMPER CLIPS	20	\$4.00	nn	\$80.00 501n
4	SEALANT	2	\$60.00	nn	\$120.00 401n
5	REAR FLOOR COVER BATTERY CLIPS	4	\$5.00	nn	\$20.00 X
1 set Front & Rear Number plate @ 150 → Pcd 901n					
SN TOTAL					\$660.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST, DISMANTLE ACCIDENT AREAS & ETC. \$3,600.00 2001

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC. \$2,800.00 24001

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT & REAR BOTH FENDER AREA, ABSORBER, STABILIZER BAR, UNDERCARRIAGE, FUEL TANK, CLEAR SHUTTLE GLASS & ETC. \$1,200.00 3801

LABOUR CHARGES TO DISCONNECT & RECONNECT FRONT WIRING SYSTEM & ETC. TO EFFECT REPAIR AT FRONT ACCIDENT AREAS & ETC. \$500.00 401

LABOUR CHARGES TO DIAGNOSE FAULTY CODE & RESET MEMORY. \$400.00 1501

LABOUR TOTAL \$8,500.00

TOTAL \$28,465.52

Head office
6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:
Date:

Date: 15-11-2021 RE-SURVEY
Vehicle No: SMD837C
Model: TOYOTA SIENTA
Chassis: NHP170-7108820
Reg.Year: 2018

Third Party Insurer: CHINA TAIPING
Third Party Veh No: GBK5912D
Date of Accident: 11-11-2021
Estimator: ARY CHUA
Surveyor: KENNETH LKKAUTO

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT SUPPORT PANEL/BULKHEAD <i>Pr?</i>	1	188.10	<i>Pr</i> \$898.00
2	HYBRID COOLER <i>8P0.60</i>	1		<i>Bt</i> \$878.00
3	FRONT SUPPORT TOP LH	1		\$183.00
4	FRONT SUPPORT MAIN BEAM PANEL LH	1		<i>Pr</i> \$584.00
5	FRONT AIR DUCT COVER RH	1		<i>CM</i> \$128.00
6	FRONT AIR DUCT COVER LH	1		<i>CM</i> \$128.00
7	FRONT BONNET LOCK	1		<i>Pr</i> \$228.00
8	FRONT FOAM BUMPER	1		<i>CM</i> \$168.00
9	FRONT UNDERCARRIAGE COVER	1		<i>Pr</i> \$479.00
10	TAILGATE HOLDER COVER	1		<i>Pr</i> \$65.00
11	REAR ANTENAL SENSOR	1		<i>Bt</i> \$175.00
12	LHR MULFRED	1		<i>Pr</i> \$151.00
13	RHR MULFRED	1		<i>Pr</i> \$151.00
14	RUBBER HOLDER REAR EXHAUST	2	\$55.00	<i>Pr</i> \$110.00
15	TAILGATE LAMP LICENSE PLATE	2	\$85.00	<i>Bt</i> \$170.00
16	REAR EXHAUST PIPE	1		<i>Pr</i> \$680.00
17	RHR LAMP END PANEL <i>285</i>	1		<i>Bt</i> \$555.00
18	LHR LAMP END PANEL <i>285</i>	1		<i>Pr</i> \$555.00
19	REAR FLOOR SUPPORT BEAM	1		<i>Bt</i> \$464.00
20	REAR TOP FENDER COVER LH	1		<i>CM</i> \$580.00
21	REAR TOP FENDER COVER RH	1		<i>CM</i> \$580.00
22	REAR AIR DUCK COVER LH	1		<i>Pr</i> \$164.00
23	REAR AIR DUCK COVER RH	1		<i>Pr</i> \$164.00
			SUB TOTAL PARTS	\$8,238.00
			LESS 25%	-\$2,059.50
			PARTS TOTAL	\$6,178.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR PANEL BASE HOLDER CLIP	8	\$7.50	<i>Pr</i> \$60.00
2	CAR BATTERY <i>100AH</i>	1	<i>200</i> \$380.00	<i>Pr</i> \$380.00
3	REAR REVERSE CAMERA <i>Pr?</i> <i>DM</i>	1	\$428.00	<i>320</i> \$428.00
			S/N TOTAL	\$868.00

SUPPLEMENTARY

LABOUR CHARGES:

LABOUR CHARGES FOR KNOCKING/STRAIGHTEN REPAIR ALL ACCIDENT AREAS & ETC
(INCLUDE FRONT SUPPORT PANEL BULKHEAD & REAR FLOOR PANEL)

\$400.00

LABOUR CHARGES FOR KNOCKING/STRAIGHTEN & REPAIR ALL ACCIDENT AREAS & ETC

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 15-11-2021 RE-SURVEY

Vehicle No: SMD837C

Model: TOYOTA SIENTA

Chassis: NHP170-7108820

Reg.Year: 2018

Third Party Insurer: CHINA TAIPING

Third Party Veh No: GBK5912D

Date of Accident: 11-11-2021

Estimator: ARY CHUA

Surveyor: KENNETH LKKAUTO

(INCLUDE BOTH FRONT & REAR FENDER)	\$800.00	X
SPRAY PAINT FOR ACCIDENT CONSISTANCE AFFECTED AREA X4 DOOR PANEL	\$400.00	X
INSTALL REAR WINDSCREEN GLASS & CLEAR ALL THE SHUTTLE GLASS	\$300.00	1200
REMOVE & INSTALL RADIATOR, COOLANT, A/C CONDENSER GAS RECHARGE MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION	\$300.00	1000
REMOVE & INSTALL INTERIOR LINING, ROOF, SEATS & REAR COMPARTMENT LINING	\$300.00	1200
REMOVE & INSTALL FUEL TANK & PIPE LINE FOR FLOOR PANEL	\$300.00	600
REMOVE & INSTALL REAR EXHAUST PIPE	~ \$200.00	X
LABOUR TOTAL		\$2,800.00
TOTAL		\$9,846.50

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	107N
Vehicle Details	
Vehicle No.:	SMD837C
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2021
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID 1.5G CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1NZ8381389
Chassis No.:	NHP1707108820
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$23,248.00
Original Registration Date:	31 Jul 2018
First Registration Date:	31 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$24,548.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2028
PARF Rebate Amount:	\$18,411.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,809.00
COE Rebate Amount:	\$21,966.00
Total Rebate Amount:	\$40,377.00

The information contained herein is correct as at 11 Nov 2021

OK