

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21011650/KEA3Q2**Date:** 02/09/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHD5993K**Insured Vehicle No :** SKW9737Y

Date of Loss: 10/11/2021

Nature of Claim: TP

Claim No: 0061208919SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD5993K**

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Engine No: 2ZR2B63913

Reg. Date: 01/11/2018 (Man. Year: 2018)

Chassis No: JTDKB3FU903075745

Colour: Metallic Pearl White/Red

Odometer: 245311 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Sailun 9 mm

Rear Left Side: Sailun 9 mm

Front Right Side: Sailun 9 mm

Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,961.85	1,472.82	3,489.03	70.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,790.00	760.00	4,030.00	84.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,751.85	2,232.82	7,519.03	77.10
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	9,751.85	1,800.00	7,951.85	81.54
+ GST 7.00/7.00% (S\$)	682.63	126.00	556.63	81.54
Nett Amount (S\$)	10,434.48	1,926.00	8,508.48	81.54
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$96.30/day) (S\$)		385.20		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,518.65		
Global Sum Settlement (S\$)		2,500.00		

INSPECTION

Date of Assignment: 12/11/2021

Date Inspected: 12/11/2021

Inspected At:

Trans-cab Auto Services Pte Ltd
2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Repair	925.60 FL	*- FL
2	1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME NO.2	Necessary	54.60 FL	*54.60 FL
3	1		*PLATE ,BACK DOOR NAME NO.1	Necessary	54.60 FL	*54.60 FL
4	1		*ORNAMENT SUB-ASSY ,BACK DOOR	Necessary	47.90 FL	*47.90 FL
5	1		*COVER ,BACK DOOR TRIM	Serviceable	24.90 FL	*- FL
6	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
7	1		*LENS AND BODY ,REAR LAMP ,RH (LOWER)	Scratched	502.00 FL	*502.00 FL
8	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH (UPPER)	Serviceable	443.30 FL	*- FL
9	1		*COVER ,REAR BUMPER	Buckled	442.60 FL	*442.60 FL
10	1		*COVER ,REAR BUMPER LOWER	Dented	15.40 FL	*15.40 FL
11	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Mtg Cracked	123.70 FL	*123.70 FL
12	1		*GUARD ,REAR BUMPER CENTER	Dented	576.30 FL	*576.30 FL
13	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
14	1		*COVER ,FLOOR UNDER NO.2 RH	Serviceable	241.90 FL	*- FL
15	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
16	1		*REAR BUMPER CLIP	Necessary	65.00 FS	*50.00 FS
17	1		*REAR TAIL LAMP CLIP	Not Necessary	65.00 FS	*- FS
18	1		*END PANEL INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
19	1		*CLIP (FOR REAR DOOR TRIM BOARD)	Not Necessary	65.00 FS	*- FS
20	1		*BOOT STICKER TRANS-CAB	Necessary	100.00 FS	*30.00 FS
21	1		*BOOT STICKER TEL.NO	Necessary	100.00 FS	*30.00 FS
22	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
23	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
24	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,070.80	1,927.10
- List Item Discount on L Items 25.00/25.00% (S\$)	1,108.95	454.28
Total Parts (S\$)	4,961.85	1,472.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	440.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,800.00	300.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			4,790.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >