

Not Authenik
L/Png B

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5993K

AAD2111-063

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 5993K

JTDKB3FU903075745

TOYOTA

PRIUS

10.11.2021

AIG

1/11/2018

12 NOV 2021

PART

LIST

1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	SCR	925.60	X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	na	54.60	—
1	PLATE, BACK DOOR NAME, NO.1	\$	na	54.60	—
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	na	47.90	—
1	COVER, BACK DOOR TRIM	\$	na	24.90	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	na	650.30	X
1	LENS AND BODY, REAR LAMP, RH (LOWER)	\$	na	502.00	—
1	LENS & BODY, REAR COMBINATION LAMP, LH (UPPER)	\$	na	443.30	X
1	COVER, REAR BUMPER	\$	na	442.60	—
1	COVER, REAR BUMPER, LOWER	\$	na	15.40	—
1	FILLER, REAR BUMPER EXTENSION, RH	\$	na	123.70	—
1	GUARD, REAR BUMPER, CENTER	\$	na	576.30	—
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	na	332.70	7
1	COVER, FLOOR UNDER, NO.2 RH	\$	na	241.90	X

TOTAL \$ 4,435.80

25% \$ 1,108.95

\$ 3,326.85

Special Nett

1SET PARKING AID	\$	na	700.00	X
1 REAR BUMPER CLIP	\$	na	65.00	505.00
1 REAR TAIL LAMP CLIP	\$	na	65.00	X
1 END PANEL INNER TRIM CLIP	\$	na	60.00	X
1 CLIP(FOR REAR DOOR TRIM BOARD)	\$	na	65.00	X

Trans-cab Auto Services Pte Ltd

AAD2111-063

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

SHD 5993K

- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL.NO
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	na	100.00	30sn
\$	na	100.00	30sn
\$	na	150.00	X
\$	na	200.00	X
\$	na	130.00	X
TOTAL		\$	1,635.00

TOTAL PARTS \$ 8,543.40**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	na	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,800.00	4401
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,800.00	3001
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	na	170.00	X

TOTAL \$ 4,790.00**Over All Total \$ 16,660.25****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting (PART-BY-PART) Repair Days
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

18 Days

2 1/2 days