

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5993K***Not Authorised*  
*11 Pm @ 1800h***AAD2111-063**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHD 5993K**

JTDKB3FU903075745

TOYOTA

PRIUS

10.11.2021

**AIG**

1/11/2018

| PART                                             | LIST                            |
|--------------------------------------------------|---------------------------------|
| 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE           | \$ <i>Sen</i> <i>R</i> 925.60 X |
| 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2     | \$ <i>Sen</i> 54.60 —           |
| 1 PLATE, BACK DOOR NAME, NO.1                    | \$ <i>Sen</i> 54.60 —           |
| 1 ORNAMENT SUB-ASSY, BACK DOOR                   | \$ <i>Sen</i> 47.90 —           |
| 1 COVER, BACK DOOR TRIM                          | \$ <i>Sen</i> 24.90 X           |
| 1 PANEL SUB-ASSY, BODY LOWER BACK                | \$ <i>R</i> 650.30 X            |
| 1 LENS AND BODY, REAR LAMP, RH (LOWER)           | \$ <i>Sen</i> 502.00 —          |
| 1 LENS & BODY, REAR COMBINATION LAMP, LH (UPPER) | \$ <i>Sen</i> 443.30 X          |
| 1 COVER, REAR BUMPER                             | \$ <i>Bun</i> 442.60 —          |
| 1 COVER, REAR BUMPER, LOWER                      | \$ <i>Sen</i> 15.40 —           |
| 1 FILLER, REAR BUMPER EXTENSION, RH              | \$ <i>Myent</i> 123.70 —        |
| 1 GUARD, REAR BUMPER, CENTER                     | \$ <i>Sen</i> 576.30 —          |
| 1 REINFORCEMENT SUB-ASSY, REAR BUMPER            | \$ <i>R</i> 332.70 X            |
| 1 COVER, FLOOR UNDER, NO.2 RH                    | \$ <i>Sen</i> 241.90 X          |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>4,435.80</b> |
| <b>25%</b>   | <b>\$</b> | <b>1,108.95</b> |
|              | <b>\$</b> | <b>3,326.85</b> |

**Special Nett**

|                                  |    |                               |
|----------------------------------|----|-------------------------------|
| 1SET PARKING AID                 | \$ | <i>Sen</i> 700.00 X           |
| 1 REAR BUMPER CLIP               | \$ | <i>Sen</i> 65.00 <i>SOSAL</i> |
| 1 REAR TAIL LAMP CLIP            | \$ | <i>Sen</i> 65.00 X            |
| 1 END PANEL INNER TRIM CLIP      | \$ | <i>Sen</i> 60.00 X            |
| 1 CLIP(FOR REAR DOOR TRIM BOARD) | \$ | <i>Sen</i> 65.00 X            |

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**AAD2111-063**

**SHD 5993K**

|                                |           |                              |
|--------------------------------|-----------|------------------------------|
| 1 BOOT STICKER TRANSCAB        | \$        | <i>nn</i> 100.00 <i>30sn</i> |
| 1 BOOT STICKER TEL.NO          | \$        | <i>nn</i> 100.00 <i>30sn</i> |
| 2 WINDSCREEN SEALANT           | \$        | <i>nn</i> 150.00 <i>X</i>    |
| 1 WINDSCREEN MOULDING          | \$        | <i>nn</i> 200.00 <i>X</i>    |
| 1 WINDSCREEN INNER SPONGE SEAL | \$        | <i>nn</i> 130.00 <i>X</i>    |
| <b>TOTAL</b>                   | <b>\$</b> | <b>1,635.00</b>              |
| <b>TOTAL PARTS</b>             | <b>\$</b> | <b>8,543.40</b>              |

**LABOUR**

|                                                                                                                           |           |                           |
|---------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|
| To Rust-Proofing and apply undercoat Of The Affected Areas.                                                               | \$        | <i>nn</i> 250.00 <i>X</i> |
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$        | 1,800.00 <i>440/</i>      |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$        | <i>nn</i> 380.00 <i>X</i> |
| To Check Electrical Lighting Concerned.                                                                                   | \$        | 170.00 <i>20/</i>         |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$        | 1,800.00 <i>300/</i>      |
| To check steering geometry and computer wheel alignment                                                                   | \$        | <i>nn</i> 220.00 <i>X</i> |
| To transfer of rear fender panel fittings, attachment and perform water seepage test.                                     | \$        | <i>nn</i> 170.00 <i>X</i> |
| <b>TOTAL</b>                                                                                                              | <b>\$</b> | <b>4,790.00</b>           |

**Over All Total \$ 16,660.25**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**(PART-BY-PART) Repair Days**

*10 Days*

*2 1/2 days*