



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2201530

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 18/03/2022
Reference CC4/LPC21011653/Uea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLF 8581M
Insured Veh. YN 8778S
Claim No. 21/21/21/VC00/025150
Policy No. Z/21/VC00/110692
Accident Date 12/11/2021
Inspection Date 16/11/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21011653/Uea3q2 Date: 18/03/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 8778S	Veh. Inspected	SLF 8581M	
Policy No.	Z/21/VC00/110692	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/025150	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	15/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104554692	Colour	GREY	
Odometer	40006 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	FALKEN	6 mm	
L/H Front Tyre	205/55 R16	FALKEN	6 mm	
R/H Rear Tyre	205/55 R16	FALKEN	6 mm	
L/H Rear Tyre	205/55 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/11/2021	Inspection Date	16/11/2021	
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 8581M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER RH	DENTED / BUCKLED	320.00	320.00
1	FRONT FENDER LINER RH	TORN	67.50	67.50
1	FRONT FENDER LINER CLIPS	NECESSARY	20.00	20.00
1	FRONT FENDER EMBLEM VVTI	NECESSARY	42.00	42.00
1	HEADLAMP RH }	CRACKED	425.50	425.50
1	HEADLAMP CHROME MOULDING RH }		107.25	-
1	HEADLAMP RH UPPER PANEL	BENT / TWISTED	280.50	280.50
1	FRONT GRILLE }	CRACKED	231.00	231.00
1	FRONT GRILLE CHROME MOULDING }		96.00	-
1	HEADLAMP LH	CRACKED	425.50	425.50
1	BRACE PANEL	TWISTED	52.00	52.00
1	FRONT GRILLE CLIPS	NOT NECESSARY	20.00	-
1	FRONT BUMPER	DISTORTED / TORN	280.50	280.50
1	FRONT BUMPER RETAINER RH	CRACKED	41.25	41.25
1	FRONT BUMPER CLIPS	NECESSARY	20.00	20.00
	LESS 25% DISCOUNT		-607.25	-551.44
			1,821.75	1,654.31
	<u>SPECIAL NETT ITEMS</u>			
1	ANTI RUSH SEALANT (SN)	NOT NECESSARY	80.00	-
			80.00	-
	<u>LABOUR</u>			
	TO REMOVE ,REFIT AND REPAIR AFFECTED ACCIDENT AREAS AND PARTS.		500.00	450.00
	SPRAY PAINTING FOR FRONT BUMPER AND FENDER .		600.00	500.00
	CHECK AND RECTIFY ELECTRICAL WIRING ,SOCKET INCLUDING ADJUSTING FOCUS AREA OF HEADLAMP.		40.00	20.00
			1,140.00	970.00
	GRAND TOTAL		3,041.75	2,624.31



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00
---	--	--	-----------------

Report Ref No. CC4/LPC21011653/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 8581M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 8581M

RE-INSPECTION

