

BW WORKSHOP SERVICES PTE LTD
 291 KAKI BUKIT AVE 1 SHUN LI
 INDUSTRIAL PARK
 Singapore 416080
 6289 8800
 workshop_admin@bw.com.sg
 GST Registration No. : 201504834E
 Company Registration No. 201504834E



Estimates

ADDRESS

INDIA INTERNATIONAL
 INSURANCE PTE LTD

ESTIMATES NO. 1399

DATE 30/03/2022

VIN NUMBER	MAKE & MODEL	MILEAGE			
ES82D / A200A0013049	TOYOTA RAIZE	-			
ACTIVITY	QTY	RATE	AMOUNT		
FINALISE ESTIMATE	1	626.25	626.25		
REAR BUMPER @ \$835	1	73.50	73.50		
REAR BUMPER SIDE RETAINER (LH) @ \$98	1	73.50	73.50		
REAR BUMPER SIDE RETAINER (RH) @ \$98	1	236.25	236.25		
REAR BUMPER DIFFUSER @ \$315	1	194.25	194.25		
REAR BUMPER COVER LH @ \$259 ***	1	194.25	194.25		
REAR BUMPER COVER RH @ \$259 ***	1	114.75	114.75		
TAILGATE OUTER GARNISH @ \$153	1	75.00	75.00		
REAR BUMPER REFLECTOR (LH) @ \$100	1	75.00	75.00		
REAR BUMPER REFLECTOR (RH) @ \$100	1	243.00	243.00		
REAR END PANEL OUTER @ \$324	1	650.25	650.25		
REAR END PANEL INNER @ \$867 ***	1	180.00	180.00		
REAR END PANEL INNER GARISH @ \$240 ***	1	900.00	900.00		
TAILGATE @ \$1200	1	324.00	324.00		
TAILGATE LOCK ACTUATOR @ \$432	1	195.00	195.00		
TAILGATE WEATHERSTRIP @ \$260	1	435.00	435.00		
TAILGATE INNER TRIM @ \$580 ***	1	112.50	112.50		
REAR WHEEL ARCH (RH) @ \$150	1	183.75	183.75		
REAR FENDER INNER SHIELD RH 65637 @ \$245 ***	1	101.25	101.25		
REAR LICENSE LAMP @ \$135	1	937.50	937.50		
REAR SPARE TYRE PANEL @ \$1250 ***	1	123.75	123.75		
REAR SPARE TYRE PANEL CLAMP @ \$165	1	525.00	525.00		
REAR SPARE TYRE BOARD @ \$700 ***	1				

NETS & Cash only.

Our Bank Details:-
 Name of Bank : UOB
 Account Name : BW Workshop Services Pte Ltd
 Account Number :356-305-177-7

ACTIVITY	QTY	RATE	AMOUNT
REAR FLOOR MAT @ \$440 ***	1	330.00	330.00
REAR FENDER INNER TRIM LH @ \$685 ***	1	513.75	513.75
REAR FENDER INNER TRIM RH @ \$580	1	435.00	435.00
REAR SEAT COVER LH @ \$189 ***	1	141.75	141.75
REAR SEAT COVER RH @ \$189 ***	1	141.75	141.75
FRONT GRILLE MOULDING @ \$198	1	148.50	148.50
FRONT BUMPER @ \$900	1	675.00	675.00
FRONT BUMPER SIDE RETAINER (LH) @ \$98	1	73.50	73.50
FRONT BUMPER SIDE RETAINER (RH) @ \$98	1	73.50	73.50
FRONT BUMPER GRILLE @ \$300	1	225.00	225.00
FRONT BUMPER LOWER LIP @ \$324	1	243.00	243.00
FRONT BUMPER CENTER BRACKET 52130 @ \$65	1	48.75	48.75
HEADLAMP (LH) @ \$1800	1	1,350.00	1,350.00
HEADLAMP (RH) @ \$1800	1	1,350.00	1,350.00
FRONT FOG LAMP COVER (LH) @ \$115	1	86.25	86.25
FRONT FOG LAMP COVER (RH) @ \$115	1	86.25	86.25
RADIATOR @ \$1080	1	810.00	810.00
RADIATOR FAN COWLING @ \$135	1	101.25	101.25
AIR CLEANER TOP AND LOWER ASSY (SET) @ \$450	1	337.50	337.50
INTERCOOLER @ \$1170	1	877.50	877.50
AIRCOND CONDENSOR @ \$1105	1	828.75	828.75
SUCTION HOSE 88712 @ \$850 ***	1	637.50	637.50
LIQUID PIPE 88735A @ \$650	1	487.50	487.50
HORN @ \$120	1	90.00	90.00
FRONT BONNET @ \$685	1	513.75	513.75
BONNET HINGE (LH) @ \$105	1	78.75	78.75
BONNET HINGE (RH) @ \$105	1	78.75	78.75
BONNET LOCK @ \$140	1	105.00	105.00
FRONT BONNET INSULATOR @ \$320	1	240.00	240.00
WIPER NOZZLE (RH) @ \$75 ***	1	56.25	56.25
BRAKE SWTICH 191210.0939B4 @ \$175 ***	1	131.25	131.25
FRONT FENDER (LH) @ \$350	1	262.50	262.50
FRONT FENDER (RH) @ \$350	1	262.50	262.50
FRONT WHEEL ARCH (LH) @ \$255	1	191.25	191.25
TOP BEAM @ \$210	1	157.50	157.50
FRONT SUPPORT PANEL TOP @ \$245	1	183.75	183.75
FRONT SUPPORT PANEL VERTICAL RH @ \$235	1	176.25	176.25
FRONT SUPPORT PANEL VERTICAL LH @ \$235	1	176.25	176.25
FRONT SUPPORT HOOD LOCK @ \$99	1	74.25	74.25
FRONT SUPPORT PANEL LOWER @ \$490 ***	1	367.50	367.50

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7

ACTIVITY	QTY	RATE	AMOUNT
FRONT BRACE PANEL LH @ \$279 ***	1	209.25	209.25
FRONT BRACE PANEL RH @ \$279 ***	1	209.25	209.25
FRONT CENTER BRACE PANEL @ \$650	1	487.50	487.50
FRONT SIDE GUIDE RH @ \$98	1	73.50	73.50
FRONT SIDE GUIDE LH @ \$98	1	73.50	73.50
FRONT CHASSIS BRACKET RH @ \$165 ***	1	123.75	123.75
AIR HOSE *** @ \$180	1	135.00	135.00 <i>me</i>
CONDENSER TOP GUIDE NO.1 *** @ \$100	1	75.00	75.00 <i>me</i>
CONDENSER TOP GUIDE NO.2 *** @ \$135	1	101.25	101.25 <i>me</i>
CONDENSER SIDE GUIDE LH *** @ \$76	1	57.00	57.00 <i>me</i>
CONDENSER SIDE GUIDE RH *** @ \$76	1	57.00	57.00 <i>me</i>
FRONT CHASSIS SIDE PLATE RH *** @ \$100	1	75.00	75.00 <i>me</i>
SPARE TYRE PANEL HOOK *** @ \$180	1	135.00	135.00 <i>BT</i>
TAILLAMP PANEL LH *** @ \$500	1	375.00	375.00 <i>BT</i>
TAILLAMP PANEL RH *** @ \$500	1	375.00	375.00 <i>BT</i>
AIR VENT *** @ \$80	2	60.00	120.00 <i>me</i>
FRONT DOOR (LH) ***REPAIR	1	0.00	0.00
FRONT DOOR (RH) ***REPAIR	1	0.00	0.00
REAR EXHAUST ***REPAIR	1	0.00	0.00
FRONT CHASSIS BRACKET LH ***REPAIR	1	0.00	0.00
			Subtotal: 22,403.25
FRONT TOYOTA LOGO -S/N	1	120.00	120.00
FRONT BUMPER CLIPS -S/N	10	3.00	30.00
FRONT TOWING COVER -S/N	1	70.00	70.00
COWLING CLIPS -S/N	10	3.00	30.00
REAR BUMPER CLIPS -S/N	10	3.00	30.00
REAR TOYOTA LOGO -S/N	1	120.00	120.00
"RAIZE" EMBLEM -S/N	1	120.00	120.00
CAR PLATE WITH COVER (FRONT & REAR) -S/N	1	80.00	80.00
REVERSE CAMERA -S/N	1	250.00	250.00
REVERSE SENSOR -S/N	1	250.00	250.00
90041-89021 CLIPS -S/N	<i>sup</i> 10	5.00	30 50.00
			Subtotal: 1,150.00
TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	20	200.00	2000 4,000.00
TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	20	200.00	2000 4,000.00
TO REMOVE AND REFIT REVERSE SENSOR	1	30.00	30.00
TO REMOVE AND REFIT REVERSE CAMERA	1	30.00	30.00
TO CONDUCT WHEEL ALIGNMENT TEST	1	60.00	60.00

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7

ACTIVITY	QTY	RATE	AMOUNT
TO TRANSFER TAILGATE'S FITTINGS	1	50.00	50.00
TO APPLY UNDERSEALING	1	40.00	40.00
TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	1	100.00	100.00
TO REMOVE AND REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	1	120.00	120.00
TO FOCUS TAILLAMPS . TO CHECK WIRING AND LIGHTING OPERATION	1	30.00	30.00
TO FOCUS HEADLAMP . TO CHECK WIRING AND LIGHTING OPERATION	1	30.00	30.00
TO TOW ACCIDENT VEHICLE TO WORKSHOP	1	60.00	60.00
			Subtotal: 8,550.00

Please feel free to contact us again if you have any queries on our quotation.

We look forward to hearing from you soon.

SUBTOTAL
GST TOTAL
TOTAL

32,103.25
0.00

SGD 32,103.25

F: 28083.25

RP: 14

Accepted By

Accepted Date

NETS & Cash only.

Our Bank Details:-
Name of Bank : UOB
Account Name : BW Workshop Services Pte Ltd
Account Number :356-305-177-7

BW WORKSHOP SERVICES PTE LTD
 291 KAKI BUKIT AVE 1 SHUN LI
 INDUSTRIAL PARK
 Singapore 416080
 6289 8800
 workshop_admin@bw.com.sg
 GST Registration No. : 201504834E
 Company Registration No. 201504834E

Estimates

ADDRESS

INDIA INTERNATIONAL
 INSURANCE PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATES NO. 1338

DATE 16/11/2021

Thuan @ LKK Auto - low
 82235769
 17/11/21 1400
 P/p after paint photo
 8 days wp

VIN NUMBER

ES82D / A200A0013049

MAKE & MODEL

TOYOTA RAIZE

MILEAGE

ACTIVITY	QTY	RATE	AMOUNT
REAR BUMPER @ \$835	1	626.25	Cut / 626.25
REAR BUMPER SIDE RETAINER (LH) @ \$98	1	73.50	Net / 73.50
REAR BUMPER SIDE RETAINER (RH) @ \$98	1	73.50	Net / 73.50
REAR BUMPER DIFFUSER @ \$315	1	236.25	Cut / 236.25
REAR BUMPER COVER LH @ \$259 ***	1	194.25	194.25 ^ / Cut
REAR BUMPER COVER RH @ \$259 ***	1	194.25	194.25 ^ / Cut
TAILGATE OUTER GARNISH @ \$153	1	114.75	scu / 114.75
REAR BUMPER REFLECTOR (LH) @ \$100	1	75.00	75.00 Y / Cra
REAR BUMPER REFLECTOR (RH) @ \$100	1	75.00	/ mis 75.00 /
REAR END PANEL OUTER @ \$324	1	243.00	DS / 243.00
REAR END PANEL INNER @ \$867 ***	1	650.25	650.25 ^ / DT
REAR END PANEL INNER GARISH @ \$240 ***	1	180.00	DS / 180.00
TAILGATE @ \$1200	1	900.00	Cra / 900.00
TAILGATE LOCK ACTUATOR @ \$432	1	324.00	DS / 324.00
TAILGATE WEATHERSTRIP @ \$260	1	195.00	195.00 ^ / Det
TAILGATE INNER TRIM @ \$580 ***	1	435.00	435.00 ^ / Cut
REAR EXHAUST @ \$750	1	562.50	562.50 ^ / XR
REAR WHEEL ARCH (RH) @ \$150	1	112.50	DS / 112.50
REAR FENDER INNER SHIELD RH 65637 @ \$245 ***	1	183.75	183.75 ^ / Cra
REAR LICENSE LAMP @ \$135	1	101.25	101.25 ^ / Cra
TAILLAMP (LH) @ \$505	1	378.75	378.75 ^ / XSC
TAILLAMP (RH) @ \$505	1	378.75	378.75 ^ / XSC
REAR BOOT LAMP (LH) @ \$235	1	176.25	176.25 ^ / XSC

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number : 356-305-177-7

ACTIVITY	QTY	RATE	AMOUNT
REAR BOOT LAMP (RH) @ \$235	1	176.25	176.25 ¹ XSVc
REAR SPARE TYRE PANEL @ \$1250 ***	1	937.50	937.50 ¹ BT
REAR SPARE TYRE PANEL CLAMP @ \$165	1	123.75	123.75 ¹ BT
REAR SPARE TYRE BOARD @ \$700 ***	1	525.00	525.00 ¹ BT
REAR FLOOR MAT @ \$440 ***	1	330.00	330.00 ¹ Cut
REAR FENDER INNER TRIM LH @ \$685 ***	1	513.75	513.75 ¹ Cut
REAR FENDER INNER TRIM RH @ \$580	1	435.00	435.00 ¹ Cut
REAR RH TRIM COVER RH @ \$145 ***	1	108.75	108.75 ¹ XSVc
REAR SEAT COVER LH @ \$189 ***	1	141.75	141.75 ¹ Cut
REAR SEAT COVER RH @ \$189 ***	1	141.75	141.75 ¹ Cut
FRONT GRILLE MOULDING @ \$198	1	148.50	Cut 148.50
FRONT BUMPER @ \$900	1	675.00	Cut 675.00
FRONT BUMPER SIDE RETAINER (LH) @ \$98	1	73.50	net 73.50
FRONT BUMPER SIDE RETAINER (RH) @ \$98	1	73.50	net 73.50
FRONT BUMPER GRILLE @ \$300	1	225.00	Cut 225.00
FRONT BUMPER LOWER LIP @ \$324	1	243.00	Cut 243.00
FRONT BUMPER CENTER BRACKET 52130 @ \$65	1	48.75	net 48.75
HEADLAMP (LH) @ \$1800	1	1,350.00	Scv 1,350.00
HEADLAMP (RH) @ \$1800	1	1,350.00	1,350.00 ¹ Cut
HEADLAMP BRACKET (LH) @ \$120	1	90.00	90.00 ¹ XSVc
HEADLAMP BRACKET (RH) @ \$120	1	90.00	90.00 ¹ XSVc
FRONT FOG LAMP COVER (LH) @ \$115	1	86.25	DSS 86.25
FRONT FOG LAMP COVER (RH) @ \$115	1	86.25	DSS 86.25
RADIATOR @ \$1080	1	810.00	810.00 ¹ BT
RADIATOR SPARE TANK @ \$190 ***	1	142.50	142.50 ¹ XSVc
RADIATOR FAN COWLING @ \$135	1	101.25	101.25 ¹ Cut
RADIATOR TOP HOSE 16571C @ \$90 ***	1	67.50	67.50 ¹ XSVc
AIR CLEANER TOP AND LOWER ASSY (SET) @ \$450	1	337.50	337.50 ¹ BT
AIR CLEANER AIR DUCK @ \$112	1	84.00	84.00 ¹ XSVc
TURBO ASSY @ \$6550 ***	1	4,912.50	4,912.50 ¹ XSVc
INTERCOOLER HOSE RH 17342D @ \$270 ***	1	202.50	202.50 ¹ XSVc
INTERCOOLER HOSE LH 17347C @ \$297 ***	1	222.75	222.75 ¹ XSVc
INTERCOOLER @ \$1170	1	877.50	877.50 ¹ BT
AIRCOND CONDENSOR @ \$1105	1	828.75	828.75 ¹ BT
SUCTION HOSE 88712 @ \$850 ***	1	637.50	637.50 ¹ BT
LIQUID PIPE 88735A @ \$650	1	487.50	487.50 ¹ BT
HORN @ \$120	1	90.00	90.00 ¹ Cut
FRONT BONNET @ \$685	1	513.75	DT 513.75
BONNET HINGE (LH) @ \$105	1	78.75	78.75 ¹ BT
BONNET HINGE (RH) @ \$105	1	78.75	78.75 ¹ BT

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7

ACTIVITY	QTY	RATE	AMOUNT
BONNET LOCK @ \$140	1	105.00	105.00
FRONT BONNET INSULATOR @ \$320	1	240.00	240.00
WIPER GARNISH (LH) @ \$75	1	56.25	56.25
WIPER GARNISH (RH) @ \$75	1	56.25	56.25
WIPER NOZZLE (RH) @ \$75 ***	1	56.25	56.25
BRAKE SWITCH 191210.0939B4 @ \$175 ***	1	131.25	131.25
FRONT FENDER (LH) @ \$350	1	262.50	262.50
FRONT FENDER (RH) @ \$350	1	262.50	262.50
FRONT WHEEL ARCH (LH) @ \$255	1	191.25	191.25
SIDE SKIRT (RH) @ \$558	1	418.50	418.50
TOP BEAM @ \$210	1	157.50	157.50
FRONT SUPPORT PANEL TOP @ \$245	1	183.75	183.75
FRONT SUPPORT PANEL VERTICAL RH @ \$235	1	176.25	176.25
FRONT SUPPORT PANEL VERTICAL LH @ \$235	1	176.25	176.25
FRONT SUPPORT HOOD LOCK @ \$99	1	74.25	74.25
FRONT SUPPORT PANEL LOWER @ \$490 ***	1	367.50	367.50
FRONT BRACE PANEL LH @ \$279 ***	1	209.25	209.25
FRONT BRACE PANEL RH @ \$279 ***	1	209.25	209.25
FRONT CENTER BRACE PANEL @ \$650	1	487.50	487.50
FRONT SIDE GUIDE RH @ \$98	1	73.50	73.50
FRONT SIDE GUIDE LH @ \$98	1	73.50	73.50
FRONT CHASSIS BRACKET LH @ \$165 ***	1	123.75	123.75
FRONT CHASSIS BRACKET RH @ \$165 ***	1	123.75	123.75
FRONT DOOR (LH) ***REPAIR	1	0.00	0.00
FRONT DOOR (RH) ***REPAIR	1	0.00	0.00
TAILLAMP PANEL (LH) ***REPAIR	1	0.00	0.00
TAILLAMP PANEL (RH) ***REPAIR	1	0.00	0.00
Subtotal: 29,145.75			
FRONT TOYOTA LOGO -S/N	1	120.00	120.00
FRONT BUMPER CLIPS -S/N	10	5.00	50.00
FRONT TOWING COVER -S/N	1	70.00	70.00
COWLING CLIPS -S/N	10	5.00	50.00
REAR BUMPER CLIPS -S/N	10	5.00	50.00
REAR TOYOTA LOGO -S/N	1	120.00	120.00
"RAIZE" EMBLEM -S/N	1	120.00	120.00
CAR PLATE WITH COVER (FRONT & REAR) -S/N	1	80.00	80.00
REVERSE CAMERA -S/N	1	250.00	250.00
REVERSE SENSOR -S/N	1	250.00	250.00
Subtotal: 1,160.00			
TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO	20	200.00	4,000.00

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7

ACTIVITY	QTY	RATE	AMOUNT
RENEW AFFECTED PARTS.			
TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	20	200.00	4,000.00 ' 2000
TO REMOVE AND REFIT REVERSE SENSOR	1	100.00	100.00 30
TO REMOVE AND REFIT REVERSE CAMERA	1	100.00	100.00 30
TO CONDUCT WHEEL ALIGNMENT TEST	1	120.00	120.00 60
TO TRANSFER TAILGATE'S FITTINGS	1	120.00	120.00 50
TO REMOVE AND RENEW EXHAUST SILENCER BOX	1	120.00	120.00 1. XNN
TO CHECK AND REALIGNMENT ON CHASSIS MEMBER	1	120.00	120.00 40 XNN
TO DISMANTLE AND CHECK FRONT & REAR UNDERCARRIAGES. TO REPLACE AFFECTED PORTIONS	1	200.00	200.00 XNN
TO APPLY UNDERSEALING	1	120.00	120.00 40
TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	1	100.00	100.00 ? /
TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS	1	200.00	200.00 ? XNN
TO REMOVE AND REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	1	120.00	120.00 /
TO FOCUS TAILLAMPS . TO CHECK WIRING AND LIGHTING OPERATION	1	80.00	80.00 30
TO FOCUS HEADLAMP . TO CHECK WIRING AND LIGHTING OPERATION	1	80.00	80.00 30
TO REMOVE AND REFIX FRONT BACK RECORDER	1	80.00	80.00 XNN
TO REMOVE AND REFIT REAR WIPER MOTOR AND MECHANISM	1	80.00	80.00 XNN
TO TOW ACCIDENT VEHICLE TO WORKSHOP	1	160.00	160.00 60
Subtotal: 9,900.00			

Please feel free to contact us again if you have any queries on our quotation.

We look forward to hearing from you soon.

SUBTOTAL
GST TOTAL
TOTAL

40,205.75
0.00

SGD 40,205.75

Accepted By

Accepted Date

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7