

ASS. REQ. BY:

REF:

LPC/

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN/OUT

Veh No: MS 5828P Yr Regn: 05/16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: NIS Note c.c. 1198Colour: M.P. White A/C: Insured / Std / NI / NASp. Reading: 86324 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JN17BA E12.80982879Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 195/60R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 13/11/21

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 15/11/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ GIA not ready

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_



# 方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.  
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Leong Lai Yin  
310A Ang Mo Kio Avenue 1  
#23-387  
Singapore 561310

NOT WITHHOLD  
11 Day @  
Paying After Paint  
6 days

Dear sir  
Estimate cost of repair to vehicle no. SLS5628P  
To supply

1. Front grille
2. Front bumper
3. Front bumper spoiler
4. Front bumper retainer x2
5. Front bonnet
6. Front bonnet hinge x2
7. head lamp 11-1
8. Front fender 11-1
9. Front fender garish
10. front door
11. Wheel rim P.1
12. Tyre
13. Lower arm
14. knuckle arm
15. Bearing
16. Shock absorber
17. Drive shaft
18. Streeling rack
19. Rocker panel garish

	276.70nett	7
Bu	494.30nett	✓
nd/cor	283.80nett	✓
MSD	80.80nett	✓
R	847.80nett	X
R	120.80nett	X
my Bu	1,776.10nett	✓
R	544.40nett	✓
MS	120.20nett	✓
R	919.60nett	X
no	1,434.50nett	✓
Pu	280.00	808.00
Ry	295.50snett	✓
Ry	328.60snett	✓
re	134.60snett	✓
	244.80snett	7
	881.80snett	7
	1,470.80snett	7
Bu	234.80snett	✓

Labour charges  
Towing  
Penal bating  
Painting  
To remove and refit undercarriages  
Total

100.00 501  
1,800.00 500  
1,200.00 800  
580.00 200  
14,449.90  
8601

Your faithfully

Albert poon

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





T/20211115/2015

1 of 3

Report No. T/20211115/2015

## Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No 0

Report Number T/20211115/2015

Vide Report Number T/20211114/7010

Date/Time of Report Made 15/11/2021 10:08

Place Report Lodged Traffic Police

Type of Informant Driver

Name of Informant Leong Lai Yin

ID Type / ID No. NRIC NO / S7002509D

Home/Office

Mobile 98500833

Email

Type of Accident Injury / Others

Drink Drive No

Anyone conveyed by ambulance No

Date/Time of Accident 13/11/2021 15:10

Accident Location ANG MO KIO AVENUE 3

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
SKC9645J					Slightly Damaged	0
SLS5628P		NISSAN	NOTE 1.2 DIG-S CVT 2WD LED	White	Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLS5628P	AVIVA LTD	10784474	06/10/2021	06/10/2022

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	TAN YU KIEW		ID No.	S0141305H
Related Vehicle	SKC9645J (Car)		Contact No.	90274622
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave		NIL	Degree of	NIL

Driver				
Name	LEONG LAI YIN	ID No.	S7002509D	
Related Vehicle	SLS5628P (Car)	Contact No.	98500833	
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL	
Date	14/11/2021	Date	14/11/2021	
No. of Days granted Medical Leave	05	Degree of	Serious	

Vehicle Owner				
Name	LEONG LAI YIN	ID No.	S7002509D	
Related Vehicle	NIL	Contact No.	98500833	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL	
Date	NIL	Date	NIL	
No. of Days granted Medical Leave	NIL	Degree of	NIL	





Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**

Brief Details.

I (Leong Lai Yin of SLS 5728P) dropped my daughter off for tuition yesterday around 3.10pm & driving out slowly from car park along Blk 423 Ang Mo Kio Ave 3.

The path catered for '2 way traffic' & I was driving around 10-15km as to exit out from carpark to main road & as to go home.

The weather was sunny.

Suddenly, the driver (Mr Tan Yu Kiew) of Toyota car (SKC 9645J) just drove out from Lot 22 suddenly & hit my left side of car. I was shocked & stepped brake asap. I wanted to drive to the side as not to block any cars moving out from lots or avoid in coming traffic.

Then realized that I can't even drive my car at all & came down to exam my car, saw that my left side tyre was punctured, side skirt was 3/4 dropped off & front part of hood was badly damaged.

The driver admitted that it was his fault as he wanted to park his car properly.

We exchanged details of personal information & after pictures of both cars. I have asked him to sign as I have written a short note.

He told me to file & claim insurance.

Subsequently, he left the scene while I was waiting for my husband & tow truck.

We left the place around 4.15pm.