



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Leong Lai Yin
310A Ang Mo Kio Avenue 1
#23-387
Singapore 561310

*NOT WITHIN
11 Day & 6700k
Repairing After Paint
6 days*

Dear sir
Estimate cost of repair to vehicle no. SLS5628P
To supply

1. Front grille		mgm	276.70nett	✓
2. Front bumper	454.90	Bu	494.30nett	✓
3. Front bumper spoiler		nd/cor	283.80snett	✓
4. Front bumper retainer x2		nd/dis	80.80nett	✓
5. Front bonnet		R	847.80nett	X
6. Front bonnet hinge x2		R	120.80nett	X
7. head lamp	61-1 1614.80	mg Bu	1,776.10nett	✓
8. Front fender	61-1	R	544.40nett	✓
9. Front fender garish		dis	120.20nett	✓
10. front door		R	919.60nett	X
11. Wheel rim	P-1	nd	1,434.50snett	✓ 3500
12. Tyre		Pu	280.00	8000 22450
13. Lower arm		Bu	295.50snett	✓
14. knuckle arm		Bu	328.60snett	✓
15. Bearing		R	134.60snett	✓
16. Shock absorber		Bu	244.80snett	✓
17. Drive shaft		Bu	881.80snett	✓
18. Streeling rack		mgm	1,470.80snett	✓
19. Rocker panel garish		Bu	234.80snett	✓

Labour charges

Towing
Penal bating
Painting
To remove and refit undercarriages
Total *Wheel Alignment*

100.00 *500*
1,800.00 *500*
1,200.00 *800*
580.00 *200*
14,449.90
800

Your faithfully

Albert Poon

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: