

ALG (P/P)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 15.11.2021

Time: 11:07:17

Page: 1

Juman!

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305494441
REGN NO : SHB2989D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 30.04.2019
DATE/TIME IN : 15.11.2021 10:30
ACCIDENT DATE : 12.11.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	de	
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	332.20	ant	
0003	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	ner	
0004	04-01-0104-2532-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64	Xnn	
0005	09-01-0104-2207-G	UNIT ASSY-REAR CORNER RAD	1	1,625.00	20.00	1,300.00	Xnn	932.65
0006	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60	ner	746.12
								SN 50

SUB-TOTAL : 2,111.96 796.12.

JOB NATURE

0000	PB	PANEL BEATING	400.00	350.
0001	SP	SPRAYPAINT CHARGE	400.00	250.
0002	L	REMOVE/REFIX REVERSE SENSOR	50.00	30
0003	L	DIAGNOSE AND RESET FUALT CODE	120.00	Xnn 630

SUB-TOTAL : 970.00

\$1426.12
* 2 days

Tanpin 92415749
WR' 15/11/21 @ 4:05pm
P/P rising before print
2 days
Tanpin Chhant w

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: