

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CC4/AIG21011662/R1PA3Q2

**Date:**

10/01/2022

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700069360

**Claimant Vehicle No :** SHB3245K**Insured Vehicle No :**

SLS5060B

Date of Loss: 15/11/2021

Nature of Claim:

TP

Claim No:

1466897615SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:

**SHB3245K**

Make &amp; Model:

HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No:

D4FDGU707355

Reg. Date:

18/01/2017 (Man. Year: 2016)

Chassis No:

KMHLB41UMHU098347

Colour:

Yellow

Odometer:

573955 km

Engine Capacity:

1685 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

**Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:

205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side:

West Lake 6 mm

Rear Left Side:

West Lake 6 mm

Front Right Side:

West Lake 6 mm

Rear Right Side:

West Lake 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

|                                          | Repairer's      | Adjuster's      | Difference    | Diff %       |
|------------------------------------------|-----------------|-----------------|---------------|--------------|
| Parts                                    | 914.16          | 633.92          | 280.24        | 30.66        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00          |              |
| Labour                                   | 1,440.00        | 880.00          | 560.00        | 38.89        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00          |              |
| Towing                                   | 0.00            | 0.00            | 0.00          |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>2,354.16</b> | <b>1,513.92</b> | <b>840.24</b> | <b>35.69</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>1,200.00</b> |               |              |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| (S\$)                                           | 2,354.16        | 1,200.00        | 1,154.16        | 49.03        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 164.79          | 84.00           | 80.79           | 49.03        |
| <b>Nett Amount (S\$)</b>                        | <b>2,518.95</b> | <b>1,284.00</b> | <b>1,234.95</b> | <b>49.03</b> |
| <b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b> |                 | 150.00          |                 |              |
| <b>+ Car Rental (3.0 x S\$110.67/day) (S\$)</b> |                 | 332.01          |                 |              |
| <b>(S\$)</b>                                    |                 | 1,766.01        |                 |              |
| <b>Liabe Amount (50.00%) (S\$)</b>              |                 | <b>883.01</b>   |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>885.01</b>   |                 |              |
| <b>Global Sum Settlement (S\$)</b>              |                 | <b>880.00</b>   |                 |              |

INSPECTION

Date of Assignment: 16/11/2021

Date Inspected: 16/11/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## Recommended Parts

F=Franchise part. S=SpcNett. L=ListItemDisc.

[https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\\_printprt&caseid=1045987&extid=373651&CFID=91059550&CFTOKEN=df00438f148f0684-972B0A4E-A22E-70DB-6C2426F...](https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=1045987&extid=373651&CFID=91059550&CFTOKEN=df00438f148f0684-972B0A4E-A22E-70DB-6C2426F...) 3/4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                      | Particulars                           | Lab.Type | Repairer's | Amount |
|-------------------------|---------------------------------------|----------|------------|--------|
| <u>Labour Items</u>     |                                       |          |            |        |
| 1                       | PANEL BEATING                         | New      | 600.00     | 280.00 |
| 2                       | SPRAY PAINTING CHARGE -REAR FENDER LH | New      | 600.00     | 500.00 |
| 3                       | WHEEL ALIGNMENT                       | New      | 120.00     | 60.00  |
| 4                       | R/I REVERSE SENSORS                   | New      | 120.00     | 40.00  |
| Gross Labour Cost (S\$) |                                       |          | 1,440.00   | 880.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >