



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN. : MOTOR CLAIMS FAX :			NAME : ADDRESS : TEL :			WIP : 43562 EXCESS : DATE: 15-Nov-21		
VEH NO :	SMR1566D	DATE IN :		CONTACT PERSON :	JESS			
CHASSIS NO :	JM6GL1032K0306839	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM			
MODEL :	MAZDA 6	DATE REG.	21-Dec-19	POLICY NO. :				

NATURE OF WORKS									
NO	DESCRIPTION	QTY	UNIT PRICE	DISC(%)	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER	1	1,099.00	-			MGSK1-50-221ABB		1,099.00
2	TAPE,PROTECTOR	4	8.60	-			MGS1D-50-EM1A		34.40
3	RETAINER S.S ULTRASONIC CENTER	2	15.50	-			MKD45-67-UC5AE4		31.00
4	SENSOR,ULTRASONIC CENTER	1	180.90	-			MGMK6-67-UC1 E4		180.90
5	TAPE SEAL	2	13.70	-			MGSH7-50-2G1		27.40
6	BRACKET CENTER REAR BUMPER	1	5.40	-			MDFR5-50-251		5.40
7	REINFORCEMENT REAR	1	538.30	-			MGHK1-50-260		538.30
8	RIVET	2	9.20	-			MTK21-50-355		18.40
9	FASTENER	6	8.00	-			MEA01-50-037		48.00
10	CLIP	6	3.00	-			MB45A-56-146A		18.00
11	COVER TOWING HOOK REAR LH	1	48.90	-			MGSH7-50-EL1 BB		48.90
12	COVER TOWING HOOK REAR RH	1	46.60	-			MGSH7-50-EK1 BB		46.60
13	GASKET RH TAIL LAMP	1	46.00	-			MGRF5-51-153		46.00
14	GASKET LH TAIL LAMP	1	46.00	-			MGRF5-51-163		46.00
							TOTAL PARTS		2,188.30
							TOTAL PARTS COST		2,188.30

SUPPLEMENTARY									
NO	DESCRIPTION	QTY	UNIT PRICE	DISC(%)	1st	Supp	PARTS NO	REVISED	PRICES
1									
2									
3									
							TOTAL PARTS		-
							TOTAL PARTS COST		-

Labour Description									
								REVISED	PRICES
1		TO REPLACE REAR BUMPER AND REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS.							1,320.00

2		TO RESPRAY REAR BUMPER,REAR REINFORCEMENT AND ALL AREAS AFFECTED BY THE ACCIDENTS.			1,575.00	
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.			660.00	
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			250.00	
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			300.00	
6	MZ-BR-SUNDRI	SUNDRIES.			50.00	
REMARKS: <i>THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING,YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES</i>				TOTAL LABOUR	-	4,155.00
				TOTAL PARTS	-	2,188.30
				TOTAL	-	6,343.30
				LESS EXCESS	-	-
				TOTAL AFTER EXCESS	-	6,343.30
				GST 7%	-	444.03
				GRAND TOTAL	-	6,787.33
SUPPLEMENTARY LABOUR DESCRIPTION						
				REVISED	PRICES	
1		#N/A				
2		#N/A				
REMARKS: <i>THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING,YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES</i>				TOTAL LABOUR	-	-
				TOTAL PARTS	-	-
				TOTAL	-	-
				LESS EXCESS	-	-
				TOTAL AFTER EXCESS	-	-
				GST 7%	-	-
				GRAND TOTAL	-	-

TRANS EUROKARS PTE LTD

 Authorised Signature