



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042

ESTIMATE COST OF REPAIRS

EUROKARS SERVICES

EQ INSURANCE COMPANY LTD

5 Maxwell Road

#17-00 Tower Block

MND Complex, Singapore 069110

ATTN.: MOTOR CLAIMS

FAX :

NAME :

ADDRESS :

TEL :

WIP : 43562

EXCESS :

DATE: 15-Nov-21

VEH NO :	SMR1566D	DATE IN :		CONTACT PERSON :	JESS
CHASSIS NO :	JM6GL1032K0306839	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 6	DATE REG.	21-Dec-19	POLICY NO. :	

NATURE OF WORKS

NO	DESCRIPTION	QTY	UNIT PRICE	DISC(%)	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER <i>de</i>	1	1,099.00	-			MGSK1-50-221ABB		1,099.00
2	TAPE, PROTECTOR <i>u</i>	4	8.60	-			MGS1D-50-EM1A		34.40
3	RETAINER S.S ULTRASONIC CENTER <i>Xan</i>	2	15.50	-			MKD45-67-UC5AE4		31.00
4	SENSOR, ULTRASONIC CENTER <i>Xan</i>	1	180.90	-			MGMK6-67-UC1 E4		180.90
5	TAPE SEAL <i>re</i>	2	13.70	-			MGS7-50-2G1		27.40
6	BRACKET CENTER REAR BUMPER <i>Xan</i>	1	5.40	-			MDFR5-50-251		5.40
7	REINFORCEMENT REAR <i>Xan</i>	1	538.30	-			MGHK1-50-260		538.30
8	RIVET <i>re</i>	2	9.20	-			MTK21-50-355		18.40
9	FASTENER <i>re</i>	6	8.00	-			MEA01-50-037		48.00
10	CLIP <i>re</i>	6	3.00	-			MB45A-56-146A		18.00
11	COVER TOWING HOOK REAR LH <i>Xan</i>	1	48.90	-			MGS7-50-EL1 BB		48.90
12	COVER TOWING HOOK REAR RH <i>Xan</i>	1	46.60	-			MGS7-50-EK1 BB		46.60
13	GASKET RH TAIL LAMP <i>re</i>	1	46.00	-			MGRF5-51-153		46.00
14	GASKET LH TAIL LAMP <i>re</i>	1	46.00	-			MGRF5-51-163		46.00

TOTAL PARTS 2,188.30

TOTAL PARTS COST 2,188.30

SUPPLEMENTARY

NO	DESCRIPTION	QTY	UNIT PRICE	DISC(%)	1st	Supp	PARTS NO	REVISED	PRICES
1									
2									
3									
TOTAL PARTS									-
TOTAL PARTS COST									-

Labour Description

		REVISED	PRICES
1	TO REPLACE REAR BUMPER AND REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS.	660	1,220.00
2	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND ALL AREAS AFFECTED BY THE ACCIDENTS.	630	1,575.00
3	MZ-BR-REVSER TO TRANSFER REVERSE SENSORS.	330	600.00

4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	180	250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250	300.00
6	MZ-BR-SUNDRI	SUNDRIES.	nec	50.00

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES

TOTAL LABOUR	-	4,155.00
TOTAL PARTS	-	2,188.30
TOTAL	-	6,343.30
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	6,343.30
GST 7%	-	444.03
GRAND TOTAL	-	6,787.33

SUPPLEMENTARY LABOUR DESCRIPTION

			REVISED	PRICES
1		#N/A		
2		#N/A		
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES			TOTAL LABOUR	-
			TOTAL PARTS	-
			TOTAL	-
			LESS EXCESS	-
			TOTAL AFTER EXCESS	-
			GST 7%	-
			GRAND TOTAL	-

TRANS EUROKARS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signature


 Hp 90010068
 3 days
 18/11/21 @ 1120
 Resy before paint