

AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS																																
<p>Christopher Tan C/O Infinity Coach & Trading 29 Fervavle Close #02-22 Rivertrees Residences Singapore 797464</p>																																
1	Reference Job Reference No : 21/002323 Claim No : - Claim Type : Third Party Accident Date : 08/06/2021 Survey Date : 09/06/2021 Survey Report Date : 21/06/2021																															
2	Particulars Of Vehicle Vehicle Registration No : SJF7080Y ✓ Make & Model : Mazda 8 2.3L Vehicle Registration Date : 31/12/2012 Chassis No : JM6LY1033D0300346 Engine No : Blocked Colour : Black																															
3	Condition Of Vehicle And Tyres <table border="1"><thead><tr><th><u>Mileage (KM)</u></th><th><u>Brakes</u></th><th><u>Steering</u></th><th><u>Modification</u></th></tr></thead><tbody><tr><td>175170</td><td>Serviceable</td><td>Serviceable</td><td>None</td></tr><tr><th><u>Tyres</u></th><th><u>Make</u></th><th><u>Size</u></th><th><u>Balance (MM)</u></th></tr><tr><td>Front RHS</td><td>Michelin</td><td>215/65R16</td><td>5</td></tr><tr><td>Front LHS</td><td>Michelin</td><td>215/65R16</td><td>5</td></tr><tr><td>Rear RHS</td><td>Michelin</td><td>215/65R16</td><td>6</td></tr><tr><td>Rear LHS</td><td>Michelin</td><td>215/65R16</td><td>6</td></tr></tbody></table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	175170	Serviceable	Serviceable	None	<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Michelin	215/65R16	5	Front LHS	Michelin	215/65R16	5	Rear RHS	Michelin	215/65R16	6	Rear LHS	Michelin	215/65R16	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																													
175170	Serviceable	Serviceable	None																													
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																													
Front RHS	Michelin	215/65R16	5																													
Front LHS	Michelin	215/65R16	5																													
Rear RHS	Michelin	215/65R16	6																													
Rear LHS	Michelin	215/65R16	6																													
4	Description Of Damages The vehicle sustained damages at front left hand portion. (For information of damages please refer to Parts/Labour/Photographs attached)																															
5	Instruction This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																															

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

Ref No : 21/002323

Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
<u>List Items</u>					
1	1	Front bumper	Deformed	1,063.60	1,063.60 845.3
2	1	Front bumper fog lamp cover	Serviceable/reuse	136.90	-
3	1	Front bumper LH side retainer	Broken	52.00	52.00 ✓
4	1	Front bumper LH inner side bracket	Serviceable/reuse	58.00	-
5	1 set	Front bumper clips	Broken/necessary	40.00	40.00 ✓
6	1	LH headlamp (HID)	Broken/cut	2,106.30	2,106.30 1845.3
7	1	Front LH fender	Dented/bent	460.00	460.00 382
8	1	Front LH fender under shield	Serviceable/reuse	232.00	-
9	1 set	Front fender under shield clips	Necessary	40.00	40.00 ✓
				4,188.80	3,761.90
Less discount 20%				837.76	752.38
Total :				3,351.04	3,009.52 ✓
<u>Special Nett Items</u>					
10	1	Front LH sports rims	Dented/warped	550.00	550.00 20 (a) repair 150
11	1	Front LH tyre	Serviceable/reuse	260.00	-
Total :				810.00	550.00 ✓
Total Spare Parts :				4,161.04	3,559.52

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex B

Ref No : 21/002323

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To remove, jack out, straighten, panel beating, align and renew replaced parts.	800.00	500.00 400
2	To putty and respray painting charges.	1,000.00	600.00 400.00 400
3	To check wirings & lightings.	50.00	30.00
4	To conduct computerise wheel alignment test.	80.00	60.00 80.00
5	To supplied and applied anti rust treatments.	50.00	30.00
Total Labour :		1,980.00	1,220.00
Total Spare Parts :		4,161.04	3,559.52
Total Labour :		1,980.00	1,220.00
Total Repair Costs :		6,141.04	4,779.52


Assessor's Recommendation

Repairer Estimate : 6,141.04
Our Adjustment : 4,779.52

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$3,800.00, with a repair period of 4 working days.

Surveyed By:


Lek Boon Hwee
Automobile Appraiser