## **ESTIMATED ACCIDENT REPAIR COST**



CIDENT TIME EPORTED	09:06HRS			BUS REGISTRATION NUMBER	SMB1379L		
ACCIDENT DATE	11-Nov-21			BUS TYPE (SD/DD)	SD		
BUS CAPTAIN NAME	SOO T	ECK LIE		BUS ROUTE NUMBER			
THIRD PARTY CLAIM AGAINST		surance (Singapore) imited.	BUS ADVERTS (Y/I		N		
SECTION 1 : ASSESS	SMENT / REPAIR / SP	RAY PAINT (LABOU	IR COST)				
LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)							TOTAL COST
• REAR CORNER BUMPER repair WORKS:-						\$	650.00 32 5
SPRAY PAINTING:  REAR CORNER BUMPER  the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey						\$	648.00 3 200
SPRAY PAINTING \$640 P	PER PANEL		Parts prices are subject to Third party survey is on a		7% GST	\$	90.30
No illegal modification(s) is allowed     Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Comparing					LABOUR TOTAL COST	\$	1,380.30
	ERY OF ACCIDENT BU	<u>D</u>	ate: TOTAL TOWING COST				
					DATE IN		
					DATE & TIME SURVEY		
		-		1	DATE OUT		
		BUS TYPE (SD / DD)	SD		TOTAL NUMBER OF DAYS		
			LOSS OF USE COST		\$		900.00
*	Zaran				SUMMA	ARY	
110 5,0010068					SECTION NO. COST		COST
Lorant Ap Svowolf Idays					1	\$	1,380.30
		(day)			2	-	
	1.	1/11/21 8	1355		3	\$	900.00
	1	D. S. A.	1355 4 w nagar		TOTAL	\$	2,280.30
		Ford .	,		frae 		PAGE 1