

ESTIMATE TO REPAIR

VEHICLE NO. : SLZ 6904 Z
MAKE : HONDA
MODEL : VEZEL 1.5X CVT
YEAR : 2017
CHASSIS NO : RU11232568

SURVEYOR NAME : *11/21/21*
DATE OF SURVEY : *DRK*
TIME OF SURVEY :

DATE : 16-Nov-21
DATE OF ACCIDENT : 15-Nov-21
THIRD PARTY REF : SJS 6228 C
THIRD PARTY REF : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	o/s rear fender arch garnish				\$ <i>150.20</i> <i>x</i>
1 pc	o/s rear door sticker				\$ <i>28.30</i> <i>✓</i>
	Less 20%				\$ 178.50
					\$ 35.70
				<i>22.64</i>	\$ 142.80
	To putty & spray paint			<i>600.00</i>	\$ 500.00 <i>4000</i>
	To check wheel alignment				\$ <i>80.00</i> <i>x</i>
	Labour charges		<i>PBP</i>	<i>622.64</i>	\$ 300.00 <i>200</i>
TG/VL	TOTAL				\$ 1,022.80

Not Notified
Review After 3 days
14/1/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: