

ASS. REC. BY: Taufikh

REF:

CS/419210116721 Tg, f3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. 2129897303SG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: 456K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SK49877L Yr Regn: 2015, JulyType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mini One SDR C.C. 1198Colour: Red A/C: Insured / Std / NI / NASp. Reading: 14444 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMMWX5120302C7 3272

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 12/11/210 4pmSurvey held at TSL AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh finalised LS \$6500, 6 days. (Red \$16004.06, 71%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 26/07 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Rep. Format: MER-TPLump Sum / H.R. (\$) 6500

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKU9877L Mini Cooper

No	Qty	Parts Description		Estimated Parts Price
1	1	Rear bumper (upper)	850	\$ 1,251.80 <i>de</i>
2	1	Rear bumper (lower)	425	\$ 874.40 <i>de</i>
3	1	Rear bumper lower cover		\$ 659.50 <i>xnn</i>
4	2	Rear bumper retainer		\$ 184.20 <i>de</i>
5	2	Rear bumper bracket		\$ 126.80 <i>de</i>
6	1	Rear bumper tow cover		\$ 68.60 <i>de</i>
7	1	Rear left bumper inner side trim		\$ 91.60 <i>x</i>
8	1	Rear right bumper inner side trim		\$ 91.60 <i>x</i>
9	1	Rear left bumper side protector		\$ 160.60 <i>x</i>
10	1	Rear right bumper side protector		\$ 160.60 <i>x</i>
11	1	Rear bumper reinforcement		\$ 520.80 <i>bt</i>
12	1	Rear bumper center sponge		\$ 178.50 <i>xnn</i>
13	1	Rear bumper centre reflector	182	\$ 225.80 <i>cut</i>
14	1 set	Rear bumper fog lamp garnish		\$ 155.80 <i>de</i>
15	1	Rear tailgate assy	960	\$ 1,617.40 <i>bt</i>
16	1	Rear tailgate centre logo	65	\$ 158.80 <i>de</i>
17	1	Rear tailgate 'one' emblem	70	\$ 151.10 <i>ur</i>
18	1	Rear tailgate 'cooper' emblem	75	\$ 160.10 <i>ur</i>
19	1	Rear tailgate outer garnish		\$ 277.80 <i>xnn</i>
20	2	Rear tailgate number plate lamps		\$ 128.80 <i>xnn</i>
21	1	Rear tailgate inner trim board	250	\$ 379.30 <i>cut</i>
22	1	Rear tailgate lock		\$ 182.50 <i>bt</i>
23	1	Rear tailgate lock catch		\$ 68.20 <i>xnn</i>
24	2	Rear tailgate hinges		\$ 185.80 <i>xnn</i>
25	1	Rear tailgate weatherstrip	180	\$ 195.40 <i>cut</i>
26	1 set	Rear tailgate rubber stopper		\$ 68.80 <i>xnn</i>
27	2	Rear tailgate dampers		\$ 585.80 <i>xnn</i>
28	1	Rear left taillamp	340	\$ 899.70 <i>cut</i>
29	1	Rear right taillamp	340	\$ 899.70 <i>cut</i>
30	1	Rear left taillamp protector	105	\$ 156.60 <i>cut</i>
31	1	Rear right taillamp protector	105	\$ 156.60 <i>cut</i>
32	1	Rear left taillamp outer garnish		\$ 123.10 <i>x</i>
33	1	Rear right taillamp outer garnish		\$ 123.10 <i>x</i>
34	1	Rear right fender		\$ 1,022.50 <i>x</i>
35	1	Rear left fender protector		\$ 187.50 <i>de</i>
36	1	Rear right fender protector		\$ 187.50 <i>de</i>
37	1	Rear left fender inner shield		\$ 269.90 <i>x</i>
38	1	Rear right fender inner shield		\$ 269.90 <i>x</i>
39	1	Rear left fender inner garnish		\$ 396.30 <i>x</i>
40	1	Rear right fender inner garnish		\$ 396.30 <i>x</i>
41	1	Rear wiper blade		\$ 88.80 <i>x</i>
42	1	Rear wiper motor		\$ 253.40 <i>x</i>

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKU9877L Mini Copper

No	Qty	Parts Description	Estimated Parts Price
43	2	Rear air duct ventilator	\$ 180.10 <i>de ✓</i>
44	1	Rear end lower panel	500 \$ 1,256.30 <i>W ✓</i>
45	1	Rear end lower panel top garnish	288 \$ 388.90 <i>de ✓</i>
46	1	Rear exhaust muffler assy	\$ 1,400.50 <i>R x 9W 150</i>
47	2	Rear exhaust muffler rubber mountings	\$ 68.80 <i>x un</i>
48	1	Rear exhaust muffler heat shield	\$ 179.90 <i>W ✓</i>
49	1	Rear windscreen glass moulding	168 \$ 288.80 <i>un ✓</i>
50	1	Rear right quarter glass moulding	\$ 188.80 <i>x un</i>
			6876.70 \$ 18,293.40
		less 10%	6189.03 \$ 1,829.34
			<u>\$ 16,464.06</u>

Special Nett Items

1	10	Rear bumper clips (upper)	\$ 60.00 <i>30 un ✓</i>
2	10	Rear bumper clips (lower)	\$ 60.00 <i>20 un ✓</i>
3	8	Rear bumper lower cover clips	\$ 40.00 <i>x un</i>
4	4	Rear left bumper side protector clips	\$ 30.00 <i>x un</i>
5	4	Rear right bumper side protector clips	\$ 30.00 <i>x un</i>
6	8	Rear tailgate inner trim board clips	\$ 40.00 <i>20 un ✓</i>
7	4	Rear tailgate outer garnish clips	\$ 30.00 <i>x un</i>
8	1	Rear right fender sealant	\$ 100.00 <i>x un</i>
9	6	Rear left fender protector clips	\$ 35.00 <i>lower</i>
10	6	Rear right fender protector clips	\$ 35.00 <i>lower</i>
11	6	Rear left fender inner shield clips	\$ 40.00 <i>x un</i>
12	6	Rear right fender inner shield clips	\$ 40.00 <i>x un</i>
13	8	Rear left fender inner garnish clips	\$ 50.00 <i>x un</i>
14	8	Rear right fender inner garnish clips	\$ 50.00 <i>x un</i>
15	1	Rear end lower panel sealant	\$ 140.00 <i>40 un ✓</i>
16	6	Rear end lower panel top garnish clips	\$ 40.00 <i>20 un ✓</i>
17	4	Rear bumper reverse sensor	\$ 1,200.00 <i>200 un ✓</i>
18	1	Rear no plate with garnish	\$ 100.00 <i>x un</i>
19	1	Rear windscreen glass sealant	\$ 100.00 <i>50</i>
20	1	Rear right quarter glass sealant	\$ 80.00 <i>x un</i>
			<u>\$ 2,300.00</u> <i>390</i>

Total parts

\$ 18,764.06

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SKU9877L Mini Cooper

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,400.00 6.00
2	To putty and spray painting rear portion.	\$ 1,400.00 6.00
3	To check rear lighting and wiring.	\$ 30.00 ✓
4	To remove and install rear tailgate lock mechanism.	\$ 60.00 ✓
5	To remove and install rear exhaust muffler assy.	\$ 100.00 60 ✓
6	To remove and install rear fuel tank to facilitate the repair.	\$ 150.00 x un.
7	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 60.
8	To apply anti rust proofing to rear affected area.	\$ 120.00 30.
9	To remove and install rear bumper reverse sensor.	\$ 60.00 30.
10	To remove and install rear windscreen glass to facilitate the repair.	\$ 120.00 ✓
11	To remove and install rear right quarter glass.	\$ 80.00 x un
12	Towing service.	\$ 80.00 1. un
Total labour :		\$ 3,740.00 1590

Total parts : \$ 18,764.06

Total labour : \$ 3,740.00

Total repair cost : \$ 22,504.06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6189.03

390

1590

8169.03

4/5 \$ 6500

06 days *