

MBM WHEELPOWER PTE LTD

Your Ref: SLN5644T3
Our Ref: SMN1818Z

To: CHINA TAIPING

CC

Fax

Date: 15/11/2021
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: B.M.W X1
Chassis No.: WBAJG120505N07088
Engine No.: 38975588B3B15A
Year of Make: 2019
Accident Date: 14 November 2021

ESTIMATE FOR VEHICLE NO.: SMN1818Z

DESCRIPTION	QTY	List Price
REAR WINDSCREEN MOULDING	1	\$ 120.00 X
TAIL GATE 1410.35	1	\$ 1,584.00 ✓
TAIL GATE HINGE LH	1	\$ 130.00 X
TAIL GATE HINGE RH	1	\$ 130.00 X
TAIL GATE WEATHERSTRIP	1	\$ 200.00 X
REAR BUMPER 1191.60	1	\$ 1,339.00 ✓
REAR BUMPER LOWER COVER 368.85	1	\$ 400.00 ✓
REAR BUMPER LOWER TRIM	1	\$ 247.00 ✓
REAR BUMPER RH TOW COVER	1	\$ 60.00 X
REAR BUMPER CENTER MOUNTING	1	\$ 65.00 X
REAR BUMPER LH RETAINER	1	\$ 210.00 X
REAR BUMPER RH RETAINER	1	\$ 210.00 X
REAR BUMPER LH CARRIER	1	\$ 226.00 X
REAR BUMPER RH CARRIER 162.25	1	\$ 226.00 ✓
REAR REINFORCEMENT	1	\$ 629.00 ✓
REAR EXHAUST HEAT SHIELD	1	\$ 105.00 ✓
END PANEL	1	\$ 650.00 X
BUMPER CLIPS	10	\$ 60.00 ✓
DISTANCE SENSOR @ \$250 EACH	2	\$ 500.00 X
Total: \$		6,971.00
LESS 10%		(697.10)
Parts Total: \$		6,273.90

Tailgate X1 emblem

4 spare in 75.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/NETT:

WINDSCREEN SEALANT
REAR NUMBER PLATE & HOLDER

1 \$
1 \$

nn 4012 60.00
sn 50.00 X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO
KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$ 1,000.00 *500*

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

\$ *nn* 300.00 X

TO REMOVE & REPLACE REAR WINDSCREEN

\$ *120* 150.00

TO APPLY ANTI RUST COATING

\$ 150.00 *30*

TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS

\$ *60* 150.00

TO REMOVE & REPLACE BUMPER SENSORS

\$ 60.00 ✓

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$ 80.00 *20*

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ *660* 1,000.00

Total: \$ 9,273.90

7% GST: \$ 649.17

Grand Total: \$ 9,923.07

9402.60

Mbm **wheelpower** pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t 62628888 f 64525333

Company Registration Number : 200204110W