

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21011679/R1UF3N2**Date:** 23/11/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ004578		
Claimant Vehicle No :	SHA8271G	Insured Vehicle No :	GBJ7799G		
Date of Loss:	15/11/2021	Nature of Claim:	TP	Claim No:	M2105313

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA8271G	Engine No:	2ZRS050373
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Chassis No:	JTDKB3FU403559323
Reg. Date:	12/07/2017 (Man. Year: 2017)	Odometer:	594327 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,428.20	1,502.00	2,926.20	66.08
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,000.00	1,480.00	520.00	26.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,439.20	2,993.00	3,446.20	53.52
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	6,439.20	2,400.00	4,039.20	62.73
+ GST 7.00/7.00% (S\$)	450.74	168.00	282.74	62.73
Nett Amount (S\$)	6,889.94	2,568.00	4,321.94	62.73

INSPECTION

Date of Assignment:	16/11/2021		
Date Inspected:	16/11/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2021)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA8271G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER ASSY	Torn	499.90 FL	-	*499.90 FL
2	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*HEADLAMP ASSY LH	Serviceable	2,637.60 FL	-	*- FL
4	1		*FRT FENDER LH	Buckled	945.30 FL	-	*945.30 FL
5	1		*FRT BUMPER SIDE BRACKET LH	Cracked	82.30 FL	-	*82.30 FL
6	1		*FRT DOOR ASSY	Repair	1,264.00 FL	-	*- FL
7	1		*FRT FENDER EMBLEM LH	Necessary	86.50 FL	-	*86.50 FL
8	1		*FRT DOOR COMFORTDELGRO LOGO	Necessary	75.00 F	-	*75.00 FS
9	1		*ADVERTISEMENT LOGO - FRT FENDER	Necessary	100.00 F	-	*100.00 FS
10	1		*ADVERTISEMENT LOGO - FRT DOOR	Necessary	100.00 F	-	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,812.60	1,911.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,384.40	409.00
Total Parts (\$\$)	4,428.20	1,502.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,100.00	700.00
2	SPRAYPAINT	New	800.00	750.00
3	CHECK WIRING	New	50.00	0.00
4	TUFF KOTE	New	50.00	30.00
Gross Labour Cost (\$\$)			2,000.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >