



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/Chua Teck Yong, Daniel (cai Der</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMJ1769C / 25/02/201</td></tr> <tr> <td>Date In/Mileage</td><td>17/11/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MK5009871</td></tr> <tr> <td>Engine No</td><td>G4FGJH702498</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>SWP SNOW WHITE PEAR/ WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Chua Teck Yong, Daniel (cai Der	Reg No/Reg Date	SMJ1769C / 25/02/201	Date In/Mileage	17/11/2021/ 0	Chassis No	KNAF3416MK5009871	Engine No	G4FGJH702498	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK
Cust No/Name	/Chua Teck Yong, Daniel (cai Der														
Reg No/Reg Date	SMJ1769C / 25/02/201														
Date In/Mileage	17/11/2021/ 0														
Chassis No	KNAF3416MK5009871														
Engine No	G4FGJH702498														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	16/11/2021/ 15:17	BLK	282 / Kevin Leong	42596			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER PANEL, REINFORCEMENT & AFFECTED AREA					400	800.00		
E PNT98000 PAINT WORK ON FRT BUMPER PANEL						350.00		
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA						40.00		
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM						30.00		
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM						120.00		
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME						50.00		
M SUNDRY SUNDRIES					20	40.00		
M LAMP ASSY-HEAD,RH					1.00	1219.00	20.00	975.20
M ORNAMENT-KIA NO.115					1.00	32.00	20.00	25.60
M COVER-FR BUMPER					1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER					1.00	262.00	20.00	209.60
M GRILLE ASSY-RADIATOR					1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE					1.00	38.00	20.00	30.40
M MOULDING-FRONT BUMPER,RH					1.00	36.00	20.00	28.80
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	20.00	67.20
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	22.00	20.00	17.60
M BEAM COMPLETE-FR BUMPER					1.00	497.00	20.00	397.60
Steve (LKK) 17/11/21, 12:30pm								
00-M AL Excess? P/P My BIL sy								
LKK Auto Consultants hence notify the Repairer of the following: • To rectify before start of repair painting • To display the repairer's name and rectify • To display the repairer's name and rectify								
3 days								
7% GST on								
3950.80								
Total Payable								
3,950.80								
276.56								
4,227.36								
Confirm & accepted by								
Acknowledged by Repairer								
Signature:								
Authorized signatory and company stamp								

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.