



A Subsidiary Of Autobacs Seven Co Ltd. Japan
 8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
 Tel : 6702 1555 Fax : 6702 1444 (Co Reg. No. 201500047H)
 Email : tohguan@skauto.com.sg

TO	: CHINA TAIPING (SKK4793E)	DATE	: 15-Nov-21
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX671A		
VEHICLE DETAILS			
VEHICLE NO.	: SMG973B		
MODEL / MAKE	: MERC BENZ C180		
CHASSIS NO.	: WDD2040452A275679		
ACCIDENT DETAIL			
DATE	: 6-Nov-21		
TIME	: 17:00HRS	CONTACT PERSON	: MR. WINSON 91866680

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT HEADLAMP LH <i>Get</i>	1	\$ 1,100.00	\$ 1,100.00
2	FRONT HEADLAMP LOWER BRACKET LH <i>Bent</i>	1	\$ 305.00	\$ 305.00
3	FRONT FENDER BLUE EFFICIENCY EMBLEM LH <i>new</i>	1	\$ 109.00	\$ 109.00
4	FRONT FENDER INNER SHIELD FRONT LH <i>new</i>	1	\$ 230.00	\$ 230.00
5	FRONT FENDER INNER SHIELD REAR LH <i>new</i>	1	\$ 150.00	\$ 150.00
6	FRONT BUMPER <i>Reh-d</i>	1	\$ 1,400.00	\$ 1,400.00
7	FRONT BUMPER CHROME MOLDING LH/RH <i>new</i>	2	\$ 120.00	\$ 240.00
8	FRONT BUMPER SIDE RETAINER LH/RH <i>new</i>	2	\$ 25.00	\$ 50.00
9	FRONT BUMPER INNER SPONGE <i>new</i>	1	\$ 195.00	\$ 195.00
TOTAL PRICE				\$ 3,779.00
LESS -10%				\$ (377.90)
SUB TOTAL PRICE				\$ 3,401.10

3154
 2838.60

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT FENDER INNER SHIELD CLIPS SET LH <i>new</i>	1	\$ 60.00	\$ 60.00
2	FRONT BUMPER CLIPS SET <i>new</i>	1	\$ 80.00	\$ 80.00
3	FRONT BUMPER LED FOG LAMP SET <i>new</i>	1	\$ 780.00	\$ 780.00

TOTAL

\$ 920.00

30

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,000.00	300	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 750.00	4500	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 95.00	X	
TO PERFORM LIGHTING & WIRING CHECK	\$ 120.00	30	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 350.00	X	

TOTAL

\$ 2,315.00

830

Admin LG
2/s 16/11/21.
04 Days

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 4,321.10
TOTAL LABOUR COST	:	\$ 2,315.00
TOTAL REPAIR COST	:	\$ 6,636.10

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS

REPAIR UNDER : PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY :

SURVEYED BY / FROM :

CONTACT NUMBER / EMAIL ADD. :

DATE / TIME OF RE-SURVEY :

EXCESS :

total: 3698.60
1/s: 2.9K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: