

Date: 15.11.2021

Vehicle No: SLG6933P

Model: MAZDA 3 4-DOOR SEDAN 1.5L

Chassis: JM6BM42A8G0344556

Reg.Year: 2016

Third Party Insurer: AIG

Third Party Veh No: GBA4510P

Date of Accident: 15.11.2021

Estimator: VICTOR

Surveyor: KENNETH

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	Part Mfg	\$900.00
2	FRONT FENDER LH	1	Part	\$380.00
3	HEADLAMP LH	1	Part	\$1,090.00
4	FRONT GRILLE	1		\$165.00
5	FRONT GRILLE CHROME LH	1	Part	\$195.00
6	FRONT GRILLE TOP GARNISH	1	Part	\$380.00
7	FRONT LOWER GRILLE COVER LH	1	Part	\$50.00
8	FOG LAMP (TURN LIGHT) LH	1	Part	\$85.00
9	FOG LAMP COVER LH	1	Part	\$65.00
10	FRONT DOOR LH	1	Part	\$850.00
11	FRONT DOOR HINGE LH	2	Upper Div	\$65.00
12	FRONT DOOR PROTECTOR	1	Part	\$150.00
13	FRONT DOOR CHROME TRIM LH	1		\$220.00
14	FRONT DOOR CHECKER LH	1		\$150.00
15	FRONT DOOR CHECKER RUBBER LH	1		\$90.00
16	REAR DOOR LH	1	Part	\$850.00
17	REAR DOOR PROTECTOR LH	1	Part	\$150.00
18	SIDE MIRROR COVER LH	1	Part	\$100.00
19	FRONT INNER SHIELD LH	1	Part	\$160.00
20	FRONT SIDE RETAINER LH	1	Part	\$45.00
21	FRONT RIM LH	1	Part	\$900.00
22	FRONT ABSORBER RLH	1		\$385.00
23	FRONT KNUCKLE ARM LH	1	Part	\$425.00
24	FRONT LOWER ARM LH	1		\$390.00
25	FRONT WHEEL BEARING RH	1	Part	\$260.00
26	FRONT STABILIZER LINK RH	1		\$140.00
27	FRONT TIE ROD LH	1		\$110.00
28	FRONT TIE ROD END LH	1		\$110.00
29	STEERING RACK	1		\$1,300.00
30	DRIVESHAFT LH	1		\$740.00
31	BONNET	1		REPAIR
SUB TOTAL				\$10,965.00
LESS 20%				-\$2,193.00
PARTS TOTAL				\$8,772.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 15.11.2021
Vehicle No: SLG6933P
Model: MAZDA 3 4-DOOR SEDAN 1.5L
Chassis: JM6BM42A8G0344556
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: GBA4510P
Date of Accident: 15.11.2021
Estimator: VICTOR
Surveyor: KENNETH

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		80.00
2	FRONT INNER SHIELD CLIPS	1		60.00
3	FRONT TYRE 16 INCH	1		450.00
S/N TOTAL				\$590.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREA.	\$1,200.00	800
LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.	\$1,600.00	1400
LABOUR CHARGES TO DISMANTLE AND INSTALL FRONT MECHANISM/GLASS	\$200.00	60
LABOUR CHARGES TO DISMANTLE AND INSTALL REAR MECHANISM/GLASS	\$200.00	60
LABOUR CHARGES TO DISMANTLE AND RE-INSTALL UNDERCARRIAGE.	\$250.00	200
TO CONDUCT WHEEL ALIGNMENT	\$150.00	60
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$150.00	30
TO DAIGNOSIS FAULT CODE & RESET MEMORY.	\$150.00	7
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00	90

LABOUR TOTAL \$4,020.00

TOTAL \$13,882.00

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature for Insurance Claims
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 688047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Head office
8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554800
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

