

Date: 15.11.2021

Vehicle No: SLG6933P

Model: MAZDA 3 4-DOOR SEDAN 1.5L

Chassis: JM6BM42A8G0344556

Reg.Year: 2016

Third Party Insurer: AIG

Third Party Veh No: GBA4510P

Date of Accident: 15.11.2021

Estimator: VICTOR

Surveyor: KENNETH

Not Authorized
6/11/2021 8:45 AM
Running After Rain
8 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	<i>Not mfg</i>	\$900.00
2	FRONT FENDER LH	1	<i>R</i>	\$380.00
3	HEADLAMP LH	1	<i>BU</i>	\$1,090.00
4	FRONT GRILLE	1	<i>R</i>	\$165.00
5	FRONT GRILLE CHROME LH	1	<i>R</i>	\$195.00
6	FRONT GRILLE TOP GARNISH	1	<i>R</i>	\$380.00
7	FRONT LOWER GRILLE COVER LH	1	<i>CM</i>	\$50.00
8	FOG LAMP (TURN LIGHT) LH	1	<i>R</i>	\$85.00
9	FOG LAMP COVER LH	1	<i>CM</i>	\$65.00
10	FRONT DOOR LH	1	<i>R</i>	\$850.00
11	FRONT DOOR HINGE LH	2	\$65.00	\$130.00
12	FRONT DOOR PROTECTOR	1	<i>NSP</i>	\$150.00
13	FRONT DOOR CHROME TRIM LH	1	<i>DI</i>	\$220.00
14	FRONT DOOR CHECKER LH	1	<i>DI</i>	\$150.00
15	FRONT DOOR CHECKER RUBBER LH	1	<i>R</i>	\$90.00
16	REAR DOOR LH	1	<i>R</i>	\$850.00
17	REAR DOOR PROTECTOR LH	1	<i>NSP</i>	\$150.00
18	SIDE MIRROR COVER LH	1	<i>Not mfg</i>	\$100.00
19	FRONT INNER SHIELD LH	1	<i>DI</i>	\$160.00
20	FRONT SIDE RETAINER LH	1	<i>CM</i>	\$45.00
21	FRONT RIM LH	1	<i>DI</i>	\$900.00
22	FRONT ABSORBER RLH	1	<i>R</i>	\$385.00
23	FRONT KNUCKLE ARM LH	1	<i>R</i>	\$425.00
24	FRONT LOWER ARM LH	1	<i>DI</i>	\$390.00
25	FRONT WHEEL BEARING RH	1	<i>R</i>	\$260.00
26	FRONT STABILIZER LINK RH	1	<i>DI</i>	\$140.00
27	FRONT TIE ROD LH	1	<i>DI</i>	\$110.00
28	FRONT TIE ROD END LH	1	<i>DI</i>	\$110.00
29	STEERING RACK	1	<i>DI/TM</i>	\$1,300.00
30	DRIVESHAFT LH	1	<i>R</i>	\$740.00
31	BONNET	1		REPAIR
SUB TOTAL				\$10,965.00
LESS 20%				-\$2,193.00
PARTS TOTAL				\$8,772.00

Date: 15.11.2021
Vehicle No: SLG6933P
Model: MAZDA 3 4-DOOR SEDAN 1.5L
Chassis: JM6BM42A8G0344556
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: GBA4510P
Date of Accident: 15.11.2021
Estimator: VICTOR
Surveyor: KENNETH

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		Per \$80.00
2	FRONT INNER SHIELD CLIPS	1		Per \$60.00
3	FRONT TYRE 16 INCH	1	750N	Per \$450.00
				250
			S/N TOTAL	\$590.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREA. 8001 \$1,200.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA. 14001 \$1,600.00

LABOUR CHARGES TO DISMANTLE AND INSTALL FRONT MECHANISM/GLASS 200.00 601

LABOUR CHARGES TO DISMANTLE AND INSTALL REAR MECHANISM/GLASS 200.00 601

LABOUR CHARGES TO DISMANTLE AND RE-INSTALL UNDERCARRIAGE. 250.00 2001

TO CONDUCT WHEEL ALIGNMENT 150.00 601

TO CHECK WIRING & ELECTRICAL SYSTEM. 150.00 301

TO DAIGNOSIS FAULT CODE & RESET MEMORY. 150.00 8

TO TUFF KOTE & UNDERSEAL MATERIALS. 120.00 901

LABOUR TOTAL \$4,020.00

TOTAL \$13,882.00

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company