

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011689/RPA3Q2**Date:** 11/10/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210034602
Claimant Vehicle No :	SHA4406L	Insured Vehicle No :	GBE3718T
Date of Loss:	15/11/2021	Nature of Claim:	TP
		Claim No:	8369407137SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4406L	Engine No:	G4LEGU329719
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVHU022788
Reg. Date:	17/03/2017 (Man. Year: 2017)	Odometer:	569182 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,549.40	4,254.36	2,295.04	35.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,520.00	500.00	24.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,569.40	5,774.36	2,795.04	32.62
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	8,569.40	4,600.00	3,969.40	46.32
+ GST 7.00/7.00% (S\$)	599.86	322.00	277.86	46.32
Nett Amount (S\$)	9,169.26	4,922.00	4,247.26	46.32
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	16/11/2021	
Date Inspected:	16/11/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	459.40 FL	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	55.80 FL	*- FL
4	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	138.10 FL	*- FL
7	1		*REAR BUMPER REFLECTOR LAMP RH	Cracked	41.45 FL	*41.45 FL
8	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
9	1		*LICENCE LAMP	Not Necessary	85.30 FL	*- FL
10	1		*BOOTLID	Bent	2,480.40 FL	*2,480.40 FL
11	1		*BOOTLID HYUNDAI PLATE	Necessary	24.30 FL	*24.30 FL
12	1		*EMBLEM HYBRID	Necessary	24.30 FL	*24.30 FL
13	1		*EMBLEM -IONIQ	Necessary	31.30 FL	*31.30 FL
14	1		*BOOTLID LAMP RH	Broken	794.40 FL	*794.40 FL
15	1		*TAIL LAMP RH	Broken	870.40 FL	*870.40 FL
16	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	180.00 FS	*- FS
17	1		*REAR FENDER RH	Repair	1,768.30 FL	*- FL
18	1		*BOOTLID COMFORT LOGO & TEL NO STICKER	Necessary	65.00 FS	*65.00 FS
19	1		*BOOTLID APP STICKER	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,118.00	5,294.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,568.60	1,039.84
Total Parts (\$\$)	6,549.40	4,254.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,050.00	700.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	40.00
4	CHECK ALL LIGHTING	New	60.00	30.00
5	SPRAY PAINT REAR FENDER RH	New	250.00	250.00
			Gross Labour Cost (\$\$)	2,020.00
				1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >