

# Kf Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

YP74735

TP/CHINA

*Can I get Kennel?*

M/S : CHINA TAIPING INSURANCE (S) PTE LTD  
 3 ANSON ROAD  
 16-00 SPRINGLEAF TOWER  
 SINGAPORE 079909

TEL: 63896111 FAX: 62221033

ATTN: Motor Claim Department *Not Authorized*

WS Ref: TP/CHINA

Claim Type: Third Party

Accident Date: 13/11/2021

TP Veh Reg No: XE5385X

*L1 Rep &  
 Recovery After Paint  
 28 days*

Claim No: ES2191155

Estimate No: ES2191155/YISHUN

Date: 16 Nov 2021

Policy No: SI21V12977/VCH/R03

Veh Reg No: YP7473S

Make/Model: HINO HINO XZU710R  
 14FT 5T AT

Chassis No: JHHUCS3H00K022989

Engine No: N04CUS35016

Reg. Date: 26/10/2017

## Estimate Repair Cost to Vehicle No : YP7473S

Description	U/Price	Quantity	Cost	Amount
			SS	SS
<b>Cost Plus</b>				
1 CABIN REAR PANEL	900.00	1 PC	900.00	✓
2 CABIN REAR PANEL LOWER INNER BEAM	180.00	1 PC	180.00	✓
3 CABIN REAR PANEL INNER SIDE PANELS	60.00	2 PCS	120.00	✓
4 REAR WINDSCREEN GLASS RUBBER	80.00	1 PC	80.00	✓
5 FRONT WINDSCREEN GLASS MOULDING	145.00	1 PC	145.00	✓
6 TOP ROOF PANEL	480.00	1 PC	480.00	✓
7 TOP ROOF PANEL INNER BEAM 1	70.00	1 PC	70.00	✓
8 TOP ROOF PANEL INNER BEAM 2	120.00	1 PC	120.00	✓
9 TOP ROOF LINING	1,100.00	1 PC	1,100.00	✓
10 METER OUTER COVER	140.00	1 PC	140.00	✓
11 CABIN REAR LH PILLAR OUTER	490.00	1 PC	490.00	✓
12 CABIN REAR LH PILLAR INNER	100.00	1 PC	100.00	✓
13 CABIN REAR LH PILLAR TOP INNER	290.00	1 PC	290.00	✓
14 FRT LH WHEEL ARP TOP GARNISH	105.00	1 PC	105.00	✓
15 CABIN REAR LH LOCK	400.00	1 PC	400.00	✓
16 CABIN REAR LH LOCK LATE	120.00	1 PC	120.00	✓
17 CABIN REAR LH LOCK SENSOR	250.00	1 PC	250.00	✓
18 CABIN REAR LH INNER GARNISH	298.00	1 PC	298.00	✓
19 TAILLAMPS	100.00	2 PCS	200.00	✓
20 AIR FILTER HOUSING	395.00	1 PC	395.00	✓
				5,983.00
<b>Special Net</b>				
21 STICKER - 7 PAX	10.00	1 PC	10.00	✓
22 STICKER - 60KM/H	10.00	1 PC	10.00	✓
23 REAR LH MUD GUARD	220.00	1 PC	220.00	✓
24 REAR NUMBER PLATE	18.00	1 PC	18.00	✓
25 REAR SAFETY BAR	480.00	1 PC	480.00	✓

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

M/S : CHINA TAIPING INSURANCE (S) PTE LTD  
 3 ANSON ROAD  
 16-00 SPRINGLEAF TOWER  
 SINGAPORE 079909  
 TEL: 63896111 FAX: 62221033  
 ATTN: Motor Claim Department

Claim No: ES2191155  
 Estimate No: ES2191155/YISHUN  
 Date: 16 Nov 2021  
 Policy No: SI21V12977/VCH/R03  
 Veh Reg No: YP7473S  
 Make/Model: HINO HINO XZU710R  
 14FT 5T AT  
 Chassis No: JHHUCS3H00K022989  
 Engine No: N04CUS35016  
 Reg. Date: 26/10/2017

WS Ref: TP/CHINA  
 Claim Type: Third Party  
 Accident Date: 13/11/2021  
 TP Veh Reg No: XE5385X

## Estimate Repair Cost to Vehicle No : YP7473S

Description	U/Price	Quantity	Cost	Amount
			SS	SS
26 REAR LH TYRE	350.00	1 PC	350.00	708.00
27 FRONT WINDSCREEN GLASS GUM	80.00	1 PC	80.00	40.00
28 REAR MAIN WOODEN CHASSISS	450.00	2 PCS	900.00	—
29 REAR STEP WOODEN BAR	120.00	1 PC	120.00	—
30 REAR CROSS WOODEN MEMBER	280.00	10 PCS	2,800.00	?
31 REAR WOODEN BOARD	350.00	10 PCS	3,500.00	?
				8,488.00
<b>Labour</b>				
32 TOWING (BY OWNER)	100.00	1 LA	100.00	✓
33 REMOVE AND REFIX REAR WINDSCREEN GLASS	60.00	1 LA	60.00	✓
34 REMOVE & REFIX TOP ROOF LINING,SEAT,CARPET,GARNISH,ETC	100.00	1 LA	100.00	✓
35 REMOVE AND REFIX FRONT WINDSCREEN GLASS	150.00	1 LA	150.00	120.00
36 REMOVE & REFIX CABIN FRT BUMPER ASSY,KNOCK & REPAIR FRT RH DOOR,TO STRAIGHTEN CABIN STRUCTURE,CUT,WELD & RENEW CABIN REAR PANEL,REAR PANEL INNER BEAM & SIDE BEAM,CABIN REAR LH PILLAR, TO BE CONTINUED...	3,200.00	1 LA	3,200.00	2800.00
37 TO CUT,WELD & RENEW CABIN TOP ROOF PANEL & INNER BEAM,KNOCK & REPAIR FRT LH WHEEL PANEL,CABIN REAR FLOOR BOARD PANEL,REMOVE & REFIX CABIN ASSY,REALIGN STRUCTURE & CABIN POSITION	0.00	1 LA	0.00	
38 PUTTY & RESPRAY ON CABIN TOP ROOF PANEL,REAR PANEL,REAR LH PILLAR,LH WHEEL ARP PANEL,FLOOR BOARD PANEL,FRT BUMPER,FRT LH DOOR & ALL AFFECTED AREAS	1,500.00	1 LA	1,500.00	1300.00
39 REMOVE & REFIX DASHBOARD,GARNISH,METER & CHECK WIRING	250.00	1 LA	250.00	✓
40 PUTTY & RESPRAY ON REAR CANOPY	1,500.00	1 LA	1,500.00	1350.00
41 TO REWRITE ADVERTISEMENT	1,300.00	1 LA	1,300.00	?

( Bill )

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

M/S : CHINA TAIPING INSURANCE (S) PTE LTD  
 3 ANSON ROAD  
 16-00 SPRINGLEAF TOWER  
 SINGAPORE 079909  
 TEL: 63896111 FAX: 62221033  
 ATTN: Motor Claim Department

WS Ref: TP/CHINA  
 Claim Type: Third Party  
 Accident Date: 13/11/2021  
 TP Veh Reg No: XE5385X

Claim No: ES2191155  
 Estimate No: ES2191155/YISHUN  
 Date: 16 Nov 2021  
 Policy No: SI21V12977/VCH/R03  
 Veh Reg No: YP7473S  
 Make/Model: HINO HINO XZU710R  
 14FT 5T AT  
 Chassis No: JHHUCS3H00K022989  
 Engine No: N04CUS35016  
 Reg. Date: 26/10/2017

## Estimate Repair Cost to Vehicle No : YP7473S

Description	U/Price	Quantity	Cost	Amount
			SS	SS
42 TO REMOVE ALUMINIUM BOX ;TO REPLACE WOODEN PLATFORM PLANK AND WOODEN CROSS MEMBER	4,500.00	1 LA	4,500.00	4000
43 TO REMOVE ALUMINIUM BOX DAMAGE PARTS & ATTACHMENT, WELD AND STRAIGHTEN ALUMINIUM STRUCTURE , REPLACE ALUMINIUM PANEL ALIGN IN BOX IN POSITION	6,200.00	1 LA	6,200.00	5800
44 TO REMOVE ALL THE DAMAGED WOODEN PLATFORM AND REBUILD REAR WOODEN TRUCK INCLUDING SUPPLY ALL NECESSARY MATERIAL	1,800.00	1 LA	1,800.00	1600
45 TO SUPPLY ALL NECESSARY MATERIAL FOR REBUILD REAR ALUMINIUM BOX,LABOUR TO REMOVE REAR ALUMINIUM BOX,ALL DAMAGED PART & RE-STRAIGHTEN ALUMINIUM STRUCTURE BOX AND CHECK LEAKING	7,500.00	1 LA	7,500.00	6800
				28,160.00
			Total	SS 42,631.00
			Add GST @ 7%	2,984.17
			Total Amount payable	SS 45,615.17

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

For Cheng Hoe Motor Pte Ltd

  
 AUTHORISED SIGNATURE