

Kf
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

YP7473S
TP/CHINA

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62221033
ATTN: Motor Claim Department

WS Ref: TP/CHINA
Claim Type: Third Party
Accident Date: 13/11/2021
TP Veh Reg No: XE5385X

Claim No: ES2191155
Estimate No: ES2191155/YISHUN
Date: 16 Nov 2021
Policy No: SI21V12977/VCH/R03
Veh Reg No: YP7473S
Make/Model: HINO HINO XZU710R
14FT 5T AT
Chassis No: JHHUCS3H00K022989
Engine No: N04CUS35016
Reg. Date: 26/10/2017

Not authorize
L1 Sum @ 24,850k
Money thru Paint
28 days

Estimate Repair Cost to Vehicle No : YP7473S

| Description | U/Price | Quantity | Cost | Amount |
|--------------------------------------|----------|----------|----------|----------|
| | | | SG\$ | SG\$ |
| Cost Plus | | | | |
| 1 CABIN REAR PANEL | 900.00 | 1 PC | 900.00 | ✓ |
| 2 CABIN REAR PANEL LOWER INNER BEAM | 180.00 | 1 PC | 180.00 | ✓ |
| 3 CABIN REAR PANEL INNER SIDE PANELS | 60.00 | 2 PCS | 120.00 | ✓ |
| 4 REAR WINDSCREEN GLASS RUBBER | 80.00 | 1 PC | 80.00 | ✓ |
| 5 FRONT WINDSCREEN GLASS MOULDING | 145.00 | 1 PC | 145.00 | ✓ |
| 6 TOP ROOF PANEL | 480.00 | 1 PC | 480.00 | ✓ |
| 7 TOP ROOF PANEL INNER BEAM 1 | 70.00 | 1 PC | 70.00 | ✓ |
| 8 TOP ROOF PANEL INNER BEAM 2 | 120.00 | 1 PC | 120.00 | ✓ |
| 9 TOP ROOF LINING | 1,100.00 | 1 PC | 1,100.00 | ✓ |
| 10 METER OUTER COVER | 140.00 | 1 PC | 140.00 | ✓ |
| 11 CABIN REAR LH PILLAR OUTER | 490.00 | 1 PC | 490.00 | ✓ |
| 12 CABIN REAR LH PILLAR INNER | 100.00 | 1 PC | 100.00 | ✓ |
| 13 CABIN REAR LH PILLAR TOP INNER | 290.00 | 1 PC | 290.00 | ✓ |
| 14 FRT LH WHEEL ARP TOP GARNISH | 105.00 | 1 PC | 105.00 | ✓ |
| 15 CABIN REAR LH LOCK | 400.00 | 1 PC | 400.00 | ✓ |
| 16 CABIN REAR LH LOCK LATE | 120.00 | 1 PC | 120.00 | ✓ |
| 17 CABIN REAR LH LOCK SENSOR | 250.00 | 1 PC | 250.00 | ✓ |
| 18 CABIN REAR LH INNER GARNISH | 298.00 | 1 PC | 298.00 | ✓ |
| 19 TAILLAMPS | 100.00 | 2 PCS | 200.00 | ✓ |
| 20 AIR FILTER HOUSING | 395.00 | 1 PC | 395.00 | ✓ |
| | | | | 5,983.00 |
| Special Net | | | | |
| 21 STICKER - 7 PAX | 10.00 | 1 PC | 10.00 | ✓ |
| 22 STICKER - 60KM/H | 10.00 | 1 PC | 10.00 | ✓ |
| 23 REAR LH MUD GUARD | 220.00 | 1 PC | 220.00 | ✓ |
| 24 REAR NUMBER PLATE | 18.00 | 1 PC | 18.00 | ✓ |
| 25 REAR SAFETY BAR | 480.00 | 1 PC | 480.00 | ✓ |

50 1
51 1
52 1

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
 3 ANSON ROAD
 16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
TEL: 63896111 **FAX:** 62221033
ATTN: Motor Claim Department

WS Ref: TP/CHINA
Claim Type: Third Party
Accident Date: 13/11/2021
TP Veh Reg No: XE5385X

Claim No: ES2191155
Estimate No: ES2191155/YISHUN
Date: 16 Nov 2021
Policy No: SI21V12977/VCH/R03
Veh Reg No: YP7473S
Make/Model: HINO HINO XZU710R
 14FT 5T AT
Chassis No: JHHUCS3H00K022989
Engine No: N04CUS35016
Reg. Date: 26/10/2017

Estimate Repair Cost to Vehicle No : YP7473S

| Description | U/Price | Quantity | Cost | Amount |
|---|-----------------|----------|------------|------------|
| | | | <u>S\$</u> | <u>S\$</u> |
| 26 REAR LH TYRE | 245.00 | 1 PC | 350.00 | 700.00 |
| 27 FRONT WINDSCREEN GLASS GUM | 80.00 | 1 PC | 80.00 | 40.00 |
| 28 REAR MAIN WOODEN CHASSIS | 450.00 | 2 PCS | 900.00 | — |
| 29 REAR STEP WOODEN BAR | 120.00 | 1 PC | 120.00 | — |
| 30 REAR CROSS WOODEN MEMBER | 280.00 | 10 PCS | 2,800.00 | 2,000.00 |
| 31 REAR WOODEN BOARD | 350.00 | 10 PCS | 3,500.00 | 2,900.00 |
| | | | | 8,488.00 |
| Labour | | | | |
| 32 TOWING (BY OWNER) | 100.00 | 1 LA | 100.00 | ✓ |
| 33 REMOVE AND REFIX REAR WINDSCREEN GLASS | 60.00 | 1 LA | 60.00 | ✓ |
| 34 REMOVE & REFIX TOP ROOF LINING, SEAT, CARPET, GARNISH, ETC | 100.00 | 1 LA | 100.00 | ✓ |
| 35 REMOVE AND REFIX FRONT WINDSCREEN GLASS | 150.00 | 1 LA | 150.00 | 120.00 |
| 36 REMOVE & REFIX CABIN FRT BUMPER ASSY, KNOCK & REPAIR FRT RH DOOR, TO STRAIGHTEN CABIN STRUCTURE, CUT, WELD & RENEW CABIN REAR PANEL, REAR PANEL INNER BEAM & SIDE BEAM, CABIN REAR LH PILLAR, TO BE CONTINUED... | 3,200.00 | 1 LA | 3,200.00 | 2,800.00 |
| 37 TO CUT, WELD & RENEW CABIN TOP ROOF PANEL & INNER BEAM, KNOCK & REPAIR FRT LH WHEEL PANEL, CABIN REAR FLOOR BOARD PANEL, REMOVE & REFIX CABIN ASSY, REALIGN STRUCTURE & CABIN POSITION | 0.00 | 1 LA | 0.00 | |
| 38 PUTTY & RESPRAY ON CABIN TOP ROOF PANEL, REAR PANEL, REAR LH PILLAR, LH WHEEL ARP PANEL, FLOOR BOARD PANEL, FRT BUMPER, FRT LH DOOR & ALL AFFECTED AREAS | 1,500.00 | 1 LA | 1,500.00 | 1,300.00 |
| 39 REMOVE & REFIX DASHBOARD, GARNISH, METER & CHECK WIRING | 250.00 | 1 LA | 250.00 | ✓ |
| 40 PUTTY & RESPRAY ON REAR CANOPY | 1,500.00 | 1 LA | 1,500.00 | 1,350.00 |
| 41 TO REWRITE ADVERTISEMENT | (Bill) 1,300.00 | 1 LA | 1,300.00 | 1,150.00 |

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
 3 ANSON ROAD
 16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
TEL: 63896111 **FAX:** 62221033
ATTN: Motor Claim Department

Claim No: ES2191155
Estimate No: ES2191155/YISHUN
Date: 16 Nov 2021
Policy No: SI21V12977/VCH/R03
Veh Reg No: YP7473S
Make/Model: HINO HINO XZU710R
 14FT 5T AT
Chassis No: JHHUCS3H00K022989
Engine No: N04CUS35016
Reg. Date: 26/10/2017

WS Ref: TP/CHINA
Claim Type: Third Party
Accident Date: 13/11/2021
TP Veh Reg No: XE5385X

Estimate Repair Cost to Vehicle No : YP7473S

| Description | U/Price | Quantity | Cost | Amount |
|---|----------|----------------|-----------|---------------------|
| | | | SS | SS |
| 42 TO REMOVE ALUMINIUM BOX ;TO REPLACE WOODEN PLATFORM PLANK AND WOODEN CROSS MEMBER | 4,500.00 | 1 LA <i>nu</i> | 4,500.00 | <i>X</i> |
| 43 TO REMOVE ALUMINIUM BOX DAMAGE PARTS & ATTACHMENT, WELD AND STRAIGHTEN ALUMINIUM STRUCTURE , REPLACE ALUMINIUM PANEL ALIGN IN BOX IN POSITION | 6,200.00 | 1 LA <i>nu</i> | 6,200.00 | <i>X</i> |
| 44 TO REMOVE ALL THE DAMAGED WOODEN PLATFORM AND REBUILD REAR WOODEN TRUCK INCLUDING SUPPLY ALL NECESSARY MATERIAL | 1,800.00 | 1 LA | 1,800.00 | <i>1600</i> |
| 45 TO SUPPLY ALL NECESSARY MATERIAL FOR REBUILD REAR ALUMINIUM BOX,LABOUR TO REMOVE REAR ALUMINIUM BOX,ALL DAMAGED PART & RE-STRAIGHTEN ALUMINIUM STRUCTURE BOX AND CHECK LEAKING | 7,500.00 | 1 LA | 7,500.00 | <i>1800</i> |
| | | | | 28,160.00 |
| Total | | | | SS 42,631.00 |
| Add GST @ 7% | | | | 2,984.17 |
| Total Amount payable | | | | SS 45,615.17 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

[Handwritten Signature]

 AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

Suppl

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
 3 ANSON ROAD
 16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
 TEL: 63896111 FAX: 62221033
 ATTN: Motor Claim Department


Claim No: ES2191155
 Estimate No: ES2191155 /YISHUN
 Date: 09 Dec 2021
 Policy No: SI21V12977/VCH/R03
 Veh Reg No: YP7473S
 Make/Model: HINO HINO XZU710R
 14FT 5T AT
 Chassis No: JHHUCS3H00K022989
 Engine No: N04CUS35016
 Reg. Date: 26/10/2017

WS Ref: TP/CHINA
 Claim Type: Third Party
 Accident Date: 13/11/2021
 TP Veh Reg No: XE5385X

Estimate Repair Cost to Vehicle No : YP7473S

| Description | U/Price | Quantity | Cost | Amount |
|--|---------|----------|----------------------|-------------|
| | | | SS | SS |
| Supplementary 1 | | | | |
| Cost Plus | | | | |
| 1 FRONT LH DOOR | 980.00 | 1 PC | R 980.00 | ✓ |
| 2 FRONT LH DOOR INNER RUBBER | 100.00 | 1 PC | GA 100.00 | ✓ |
| 3 FRONT LH DOOR INNER LOCK | 210.00 | 1 PC | Red 210.00 | ✓ |
| 4 DRIVER INJECTION | 950.00 | 1 PC | Red 950.00 | ✓ |
| 5 STEERING RELAY TILT CAB CONTROL | 480.00 | 1 PC | By 480.00 | ✓ |
| 6 CABIN REAR CROSSBAR BRIDGE | 690.00 | 1 PC | By 690.00 | ✓ |
| 7 CABIN REAR LH PANEL INNER | 175.00 | 1 PC | By 175.00 | ✓ |
| | | | | 3,585.00 |
| Labour | | | | |
| 8 TO REMOVE AND REFIT DRIVER INJECTION,STEERING RELAY TILT CAB CONTROL AND RESET SYSTEM. | 200.00 | 1 LA | 200.00 | 15d |
| 9 TO REMOVE AND REFIT CABIN REAR CROSS BAR BRIDGE AND REALIGN THE SAME. | 200.00 | 1 LA | 200.00 | 15d |
| | | | | 400.00 |
| | | | Total | SS 3,985.00 |
| | | | GST Amount | SS 278.95 |
| | | | Total Amount payable | SS 4,263.95 |

For Cheng Hoe Motor Pte Ltd


 AUTHORISED SIGNATURE