



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT21003459	Page	1
	64 CECIL STREET	Date	: 15. Nov 2021		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZ1007		
	SINGAPORE 049711	Svc Advisor	: SUHELMI		
Registration No	: SMX8751H	Engine No	: R16B25520616		
Chassis No	: MRHFC5650LT000489	Date Time	: 15. Nov 2021 11:26:38 AM		
Model	: CIVIC 1.6 VTI YM2020	Surveyor Name	:		
Owner's Name	: TAN SIAYOK HIM	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 14/11/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TAN SIAYOK HIM						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 14/11/2021						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL						
	TP VEH: SLS8096D						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>✓ ll</i>	1	617.20 ✓	25	462.90 ✓	32.40	495.30
71510-TEA-T50	GARNISH ASSY,RR.BUMPER LOWER <i>✓ NN</i>	1	128.50	25	96.37	6.75	103.12
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER <i>✓ BT</i>	1	188.00 ✓	25	141.00 ✓	9.87	150.87
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE <i>✓ de</i>	1	2.60 ✓	25	1.95 ✓	0.14	2.09
71508-TEA-T00	GARNISH,L.RR.BUMPER SIDE <i>✓ NN</i>	1	8.90	25	6.67	0.47	7.14
33555-TEA-T01	REFLECTOR ASSYL.RR. <i>✓ NN</i>	1	8.20	25	6.15	0.43	6.58
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>✓ acc</i>	1	11.50 ✓	25	8.62 ✓	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE <i>✓ acc</i>	1	11.50 ✓	25	8.62 ✓	0.60	9.22
91505-TM8-003	CLIP,BUMPER <i>✓</i>	7	2.30 16.1	25	12.07 ✓	0.84	12.91
66100-TEC-307ZZ	PANEL SETRR. <i>✓ Blue</i>	1	277.50 ✓	25	208.12 ✓	14.57	222.69
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE <i>✓ NN nec</i>	1	30.50 ✓	25	22.87 ✓	1.60	24.47
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE <i>✓ NN nec</i>	1	30.50 ✓	25	22.87 ✓	1.60	24.47
84640-TEA-Z01ZA	LINING ASSYRR.PANEL <i>✓ Re</i>	1	50.30 ✓	25	37.72 ✓	2.64	40.36
68500-TEA-N00ZZ	LID COMP TRUNK <i>✓</i>	1	554.90 ✓	25	416.17 ✓	29.13	445.30
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE <i>✓ Re</i>	1	114.80 ✓	25	86.10 ✓	6.03	92.13
75701-TBA-A10	EMBLEM,H-MARK <i>✓ acc</i>	1	14.00 ✓	25	10.50 ✓	0.74	11.24
90301-ST0-003	NUT,PUSH 3MM <i>✓</i>	2	2.10 4.2	25	3.15 ✓	0.22	3.37
74851-TEA-003	LOCK ASSYTRUNK <i>✓ BT</i>	1	84.90 ✓	25	63.67 ✓	4.46	68.13
34155-TEX-Y01	LIGHT ASSYL.LID <i>✓ NN</i>	1	139.60	25	104.70	7.33	112.03

Printed on 15/11/2021 1:38:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT21003459	Page	2
	64 CECIL STREET	Date	: 15. Nov 2021		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZ1007		
	SINGAPORE 049711	Svc Advisor	: SUHELMI		
Registration No	: SMX8751H	Engine No	: R16B25520616		
Chassis No	: MRHFC5650LT000489	Date Time	: 15. Nov 2021 11:26:38 AM		
Model	: CIVIC 1.6 VTI YM2020	Surveyor Name	:		
Owner's Name	: TAN SIAYOK HIM	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 14/11/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
33550-TEA-T01	TAILLIGHT ASSYL. / CR CRA	1	321.10	✓ 25	240.82 ✓	16.86	257.68
38387-TZ5-A01	ANTENNA ASSYL.F. X NN	1	63.20	25	47.40	3.32	50.72
74940-SZW-003	BUZZER ASSYSMART X NN	1	65.40	25	49.05	3.43	52.48
39680-TEX-Y41ZT	SENSOR ASSY,PARKING X NN	3	155.40	25	349.65	24.48	374.13
75722-TBA-A00	EMBLEM SETRR. / MCL	1	13.40	✓ 25	10.05 ✓	0.70	10.75
75725-TEA-T01	EMBLEMRR. / MCL	1	12.50	✓ 25	9.37 ✓	0.66	10.03
BO-NUM-COMP-OPC-L	NUMBER PLATE WITH CASING-OPC-L / MCL	1	45.00	✓	45.00 ✓	3.15	48.15
Sum Item					2471.56	173.02	2,644.58
					-25%: 1811.57		
BO-NUM-SEAL	SEAL NUMBER PLATE. / MCL	1	80.00	✓	80.00 ✓	5.60	85.60
Sum Ext. Service					80.00	5.60	85.60
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	150	180.00	12.60	192.60
BOJSE	BODY JOINT SEALANT.	1	100.00	✓	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	180	250.00	17.50	267.50
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	200.00	150	200.00	14.00	214.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	250	450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	350	450.00	31.50	481.50
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	450.00	350	450.00	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	250	450.00	31.50	481.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	550	3300.00	2600	3300.00	231.00	3531.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	520	3400.00	2600	3400.00	238.00	3638.00
Sum Labor					9380.00	656.60	10,036.60
					7300		

Survey By

Gino R. Amp - 8288 0282

Printed on 15/11/2021 1:38:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMX8751H
Chassis No : MRHFC5650LT000489
Model : CIVIC 1.6 VTI YM2020
Owner's Name : TAN SIAYOK HIM
Ins Policy No. :
Date of Accident : 14/11/2021

Document No. : SQT21003459 **Page** 3
Date : 15. Nov 2021
Customer No. : WZI007
Svc Advisor : SUHELMI
Engine No : R16B25520616
Date | Time : 15. Nov 2021 11:26:38 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time	22/11/21						
Excess							
Status							
Signature							
					Total Amount	11,931.56	12,766.78
					Total (Inclusive of GST)		12,766.78
						9191.57	

7 Days
before part photos.

LKK Auto Consultants hence notify
the repairer of the following:

- To resurvey the car painting
- To display the car for resurvey
- Parts provided for confirmation
- Third parties on a "Without Prejudice" basis
- No other conditions are allowed
- Surveys must be resurveyed and
is subject to the insurance company

Acknowledged by Repairer
Signature:
Date:

Printed on 15/11/2021 1:38:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.