

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET
IOB BUILDING SINGAPORE 049711

ATTENTION :

CONTACT : 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ007033

DATE : 13/12/2021
ACCIDENT DATE : 09/11/2021
VEHICLE NO : SMD5299Y
CHASSIS/ENG.NO : KMHC41BTKU440059
VEHICLE MODEL : HYUNDAI ACCENT
CLAIM NO : MFL2021D0004961/SN
POLICY NO :
REMARK : 5299INDIA TP AGST
PC6603R

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER <i>de</i>	418.60	20	334.88	334.88
2	1	PC	REAR BUMPER RETAINER LH <i>X</i>	23.20	20	18.56	18.56 <i>X</i>
3	1	PC	REAR BUMPER REINFORCEMENT <i>? X</i>	376.50	20	301.20	301.20 <i>X</i>
4	10	PC	REAR BUMPER CLIPS <i>re</i>	4.90	20	3.92	39.20
5	1	PC	REAR BOOT LID <i>repair</i>	1,223.90	20	979.12	979.12 <i>X</i>
6	1	PC	REAR BOOT EMBLEM <i>re</i>	27.50	20	22.00	22.00
7	1	PC	REAR BOOT ACCENT LOGO <i>re</i>	29.80	20	23.84	23.84
SUB-TOTAL:							1,718.80

**** WORK LABOUR ****

TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS

TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS

TO CHECK WIRING

TO APPLY ANTI RUST COATING

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Any damaged item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

730	{	400.00	300	400.00
		500.00	400	500.00
		30.00		30.00
		30.00	nn X	30.00

		SUB-TOTAL		960.00

SAM

SUB-TOTAL : S\$ 2,678.80
ADD 7% GST. S\$ 187.52
GRAND TOTAL : S\$ 2,866.32

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

AXA Ref :
Date : 18/12/2021

ATTN:THE MOTOR CLAIMS DEPT
INDIA INTERNATIONAL INSURANCE

SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No. SMD5299Y
Date of Accident 09-Nov-21
Type of Claim TP INDIA
Survey By _____

Model / Year HYUNDAI ACCENT
Policy No. _____
Prepared By SHARON
Chassis No. _____

S/NO	Description	Qty	Cost Price	Amount
1	TO DIAGNOSE & RESET nec ✓	1	\$ 180.00	\$ 180.00 150