

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms Lonpac Insurance Bhd

Date 16/11/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLJ6458D

Chassis No: NKE1657138878

MAKE / MODEL : Toyota Corolla Axio Hybrid 1.5 Auto

DATE OF ACCIDENT: 14/11/2021

YOUR INSURED VEHICLE NUMBER: GX8227B

MILEAGE: 364827 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear boot <i>bt</i>	1PC	\$1,632.00	\$1,632.00 <i>821</i>
2	Rear boot Toyota logo <i>ne</i>	1PC	\$60.00	\$60.00 ✓
3	Rear boot Hybrid emblem <i>ne</i>	1PC	\$50.00	\$50.00 ✓
4	Rear boot AXIO emblem <i>ne</i>	1PC	\$45.00	\$45.00 ✓
5	Rear boot COROLLA emblem <i>ne</i>	1PC	\$50.00	\$50.00 ✓
6	Rear boot weatherstrip <i>ne</i>	1PC	\$270.00	\$270.00 <i>187</i>
7	Rear boot lock <i>bt</i>	1PC	\$420.00	\$420.00 <i>105</i>
8	Rear boot lock catch <i>bt</i>	1PC	\$60.00	\$60.00 ✓
9	Rear end panel top cover/garnish <i>de</i>	1PC	\$342.00	\$342.00 <i>166</i>
10	Rear end panel <i>bt</i>	1PC	\$792.00	\$792.00 <i>682</i>
11	Rear bumper <i>de</i>	1PC	\$912.00	\$912.00 <i>780</i>
12	Rear bumper RH side retainer <i>can X</i>	1PC	\$138.00	\$138.00 X
13	Rear bumper LH side retainer <i>can</i>	1PC	\$138.00	\$138.00 <i>116</i>
14	Rear bumper LH reflector X	1PC	\$100.00	\$100.00 X
15	R/L taillamp <i>can</i>	1PC	\$850.00	\$850.00 <i>546</i>
16	R/R taillamp <i>can</i>	1PC	\$850.00	\$850.00 <i>546</i>
17	Rear silencer X	1PC	\$890.00	\$890.00 X

LIST TOTAL S\$: \$7,599.00

25.00% DISCOUNT S\$: \$1,899.75

\$5,699.25

4214
259
3160.50

SPECIAL NETT

1	Rear bumper clips <i>ne</i>	1 SET	\$80.00 <i>30</i>
2	Body sealant <i>ne</i>	1SET	\$200.00 <i>60</i>
3	Reverse sensor <i>ne</i>	1SET	\$260.00 <i>200</i>
4	End panel garnish clips <i>ne</i>	1 SET	\$100.00 <i>30</i>
5	Rear exhaust mounting X	1PC	\$150.00 X <i>MM</i>

Special Nett Total S\$: \$790.00

320

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms Lonpac Insurance Bhd

Date 16/11/2021

Attn : **MOTOR CLAIMS DEPT**

ESTIMATE SUPPLEMENTARY

VEHICLE NO: SLJ6458D

Chassis No: NKE1657138878

MAKE / MODEL : Toyota Corolla Axio Hybrid 1.5 Auto

DATE OF ACCIDENT: 14/11/2021

YOUR INSURED VEHICLE NUMBER: GX8227B

MILEAGE: 364827 km

<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1 Rear spare tyre top board <i>de</i>	1PC	\$465.00	\$465.00
		LIST TOTAL S\$:	\$465.00
		25.00% DISCOUNT S\$:	\$116.25
			\$348.75

240
25%
180

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR CHARGES

- 1 To labour charge for removing rear bumper, rear boot, rear end panel inner and outer out to facilitate repairs and replacement of damaged parts. \$1,250.00 ~~900~~
- 2 To respray rear boot, rear bumper, end panel inner and outer panel, spare tyre panel \$1,200.00 ~~1000~~
- 3 To deactivate and activate high voltage battery as a safety precautions \$300.00 ~~200~~ X 1111
- 4 To conduct standard of operating procedures post repairs diagnostic scan test as a requirement for hybrid cars upon completion of collision repairs \$300.00 X 111
- 5 Transfer tailgate mechanism \$100.00 ~~60~~

LABOUR TOTAL S\$: \$3,150.00

TOTAL S\$: \$9,639.25

7% GST \$674.75

GRAND TOTAL S\$: \$10,314.00

1960

3160.50

320.00

180.00

1960.00

5620.50

20%

4496.40

L/S - \$,4500

Repair

Hp 900 10068

8 days

48

19/11/21 @ 1540

Repair after repair