

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

17/11/2021 10:41

OWNER'S PARTICULARS

JOB-NO: 85008888

NAME: DIGILIFE TECHNOLOGIES LIM

CONTACT:

Page 1 of 2

ADDRESS: 152 UBI AVENUE 4
SINGAPORE (408826)

rakshan-rai@sev.com.sg

VEHICLE DETAILS

LICENSE NO: SLV1791K

TRANS: AUTO

CHASSIS: LC0CE4DB3H1026329

MAKE / MODEL: BYD / e6

ENGINE: BYD TYC90B117003106

OWNER'S INSURER: ALLIANZ GLOBAL CORPORATE & SPECIALT

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,600.00	0.00	1,600.00	600 -	Y	
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	180.00	0.00	180.00	30 -	Y	
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	300.00	0.00	300.00	X	Y	
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	280.00	0.00	280.00	100 -	Y	
5 TO TRANSFER OF BOTH FRONT AND REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	1.00	260.00	0.00	260.00	100 -	Y	
6 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	160.00	0.00	160.00	60 -	Y	
7 TO CHECK AND REPAIR WIRE HARNESS	1.00	170.00	0.00	170.00	X	Y	
8 TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	200 -	Y	
9 TO RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	X	Y	
10 TO RESPRAY REAR QUARTER PANEL	1.00	250.00	0.00	250.00	200 -	Y	
11 TO RESPRAY REAR DOOR PANEL	1.00	250.00	0.00	250.00	200 -	Y	
12 TO RESPRAY FRONT DOOR PANEL	1.00	250.00	0.00	250.00	200 -	Y	
13 TO RESPRAY SIDE SKIRT RH	1.00	250.00	0.00	250.00	200 -	Y	
14 TO RESPRAY FRONT RH SIDE MIRROR	1.00	250.00	0.00	250.00	50 -	Y	
TOTAL:		4,700.00	0.00	4,700.00			

MATERIALS

1 FRONT RH DOOR PANEL	1.00	104.13	0.00	104.13	L	Y	1291.39
2 FRONT RH SIDE MIRROR ASSY	1.00	558.31	0.00	558.31	L	Y	525.32
3 FRONT RH DOOR GLASS	1.00	149.76	0.00	149.76	L	Y	
4 FRONT RH OUTER DOOR HANDLE	1.00	403.20	0.00	403.20	L	Y	
5 FRONT RH DOOR LOCK	1.00	160.13	0.00	160.13	L	Y	
6 FRONT RH DOOR UPPER WINDOW FRAME BLACK FILM	1.00	16.13	0.00	16.13	L	Y	
7 FRONT RH POWER WINDOW REGULATOR ASSY	1.00	269.57	0.00	269.57	L	Y	
8 FRONT RH DOOR B-PILLAR BLACK FILM	1.00	16.13	0.00	16.13	L	Y	
9 FRONT RH OUTER DOOR HANDLE BASE	1.00	0.00	0.00	0.00	L	Y	
10 SIDE SKIRT RH	1.00	92.16	0.00	92.16	L	Y	
11 FRONT RH OUTER DOOR WEATHERSTRIP MOULDING	1.00	145.15	0.00	145.15	L	Y	
12 FRONT RH OUTER DOOR HANDLE COVER	1.00	0.00	0.00	0.00	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
13 FRONT RH POWER WINDOW REGULATOR MOTOR	X 1.00 nn	0.00	0.00	0.00	L	X Y	
14 REAR RH DOOR PANEL	1.00	0.00	1013.76	0.00	912.28	L - Y	1223.42
15 REAR RH UPPER DOOR HINGE	X 1.00 nn	0.00	16.13	0.00	14.51	L X Y	
16 REAR RH LOWER DOOR HINGE	X 1.00 nn	0.00	16.13	0.00	14.51	L X Y	
17 REAR RH DOOR CHECK	X 1.00 nn	0.00	47.23	0.00	42.51	L X Y	
18 REAR RH POWER WINDOW REGULATOR	X 1.00 nn	0.00	259.20	0.00	233.1	L X Y	
19 REAR RH POWER WINDOW REGULATOR MOTOR	X 1.00 nn	0.00	0.00	0.00	L	X Y	
20 REAR RH DOOR GLASS	X 1.00 nn	0.00	147.46	0.00	132.71	L X Y	
21 FRONT RH DOOR FRAME WEATHERSTRIP	X 1.00 nn	0.00	396.29	0.00	356.66	L X Y	
22 REAR RH DOOR FRAME WEATHERSTRIP	X 1.00 nn	0.00	555.03	0.00	499.53	L X Y	
23 REAR RH DOOR B-PILLAR BLACK FILM	1.00	0.00	13.82	0.00	12.44	L - Y	
24 REAR RH DOOR UPPER WINDOW FRAME BLACK FILM	1.00	0.00	13.82	0.00	12.44	L - Y	
25 REAR RH DOOR REAR FRAME SECTION BLACK FILM	1.00	0.00	13.82	0.00	12.44	L - Y	
26 REAR RH OUTER DOOR WEATHERSTRIP MOULDING	X 1.00 nn	0.00	177.41	0.00	159.67	L X Y	
27 REAR RH TYRE RIM	X 1.00 R - CUT	0.00	564.48	0.00	508.03	L 80 - net	
28 REAR RH DOOR GLASS RUN	X 1.00 nn	0.00	106.44	0.00	95.80	L X Y	
29 REAR BUMPER COVER	X 1.00 R	0.00	315.76	0.00	284.18	L X Y	
30 REAR RH BUMPER REFLECTOR	X 1.00 nn	0.00	27.65	0.00	24.88	L X Y	
31 FRONT RH DOOR GLASS WINDOW UPPER GUIDE CHANNEL	X 1.00 nn	0.00	35.14	0.00	31.63	L X Y	
32 REAR BUMPER CLIP SET	1.00	70.00	0.00	70.00	S	Y	
33 REAR RH DOOR STICKER	1.00	250.00	0.00	250.00	S	Y	
34 FRONT RH DOOR STICKER	1.00	250.00	0.00	250.00	S	Y	
35 SIDE SKIRT CLIP SET	1.00	60.00	0.00	60.00	S	Y	
36 DOOR MOULDING CLIP SET	X 1.00 nn	55.00	0.00	55.00	X S	Y	
TOTAL:		685.00	0.00	685.00			
TOTAL PARTS & LABOUR :		5,385.00	0.00	5,385.00			

EXCESS/LOADING:\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$ \$ _____

DATE OF SURVEY: ____ / ____ / ____

SURVEYED BY: _____

CONTACT NO: _____

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL: _____

FAX: _____

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

G-STAR-WI-ET-00 -02-Rev00

Steve (LKK) MR PL
17/11/21, 11 Mon P/P

Ry BLSy
5 days

DING AUTO PTE LTD

Vehicle:	SLV1791K
Model:	BYD E6
Chassis:	LC0CE4DB3H1026329

PARTS SUPPLEMENTARY & QUOTATION FORM

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	UPPER FRONT GLASS GUIDE CHANNEL ASSY, FRONT WINDOW, R	1	\$ 35.14	10%	\$ 31.63	— BT
				PARTS	\$ 31.63	