

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21011697/UVF3E2
Date: 07/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210011681
Claimant Vehicle No :	SJF8248A	Insured Vehicle No :	SDT9144G
Date of Loss:	12/11/2021	Nature of Claim:	TP
		Claim No:	5930841346SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF8248A	Engine No:	HR15244980A
Make & Model:	NISSAN LATIO, 1.5 L T (A)	Chassis No:	JN1BAAC11Z0007742
Reg. Date:	12/06/2008 (Man. Year: 2007)	Odometer:	232252 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,760.40	3,404.36	356.04	9.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	2,050.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,810.40	5,454.36	356.04	6.13
Global Sum Settlement (S\$)		4,300.00		

INSPECTION

Date of Assignment:	17/11/2021		
Date Inspected:	17/11/2021	Inspected At:	Evergum Auto Services (HQ) BLK 3022A Ubi Road 1, #01-51 Singapore 408716
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	850.90 F	*850.90 FL
2	1		*BOOTLID REAR LOGO	Necessary	45.80 F	*45.80 FL
3	1		*BOOTLID LATIIO EMBLEM	Necessary	62.80 F	*62.80 FL
4	1		*BOOTLID OUTER CHROME (NPA)	Not Necessary	0.00 F	*- FL
5	1		*BOOTLID INNER LOCK	Bent	99.90 F	*99.90 FL
6	1		*BOOTLID HINGES (NPA)	Repair	0.00 F	*- FL
7	1		*BOOTLID WEATHERSTRIP	Twisted	89.20 F	*89.20 FL
8	1		*REAR BUMPER	Torn	532.40 F	*532.40 FL
9	1		*REAR BUMPER LOWER SKIRTING	Torn	480.00 F	*480.00 FL
10	2		*REAR BUMPER SIDE RETAINERS	Bent	50.00 F	*50.00 FL
11	2		*REAR BUMPER DAMPERS	Dented	190.00 F	*190.00 FL
12	1		*REAR BUMPER SPONGE	Torn	45.80 F	*45.80 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
14	1		*REAR END PANEL	Badly Dented	434.40 F	*434.40 FL
15	1		*REAR END PANEL TOP GARNISH	Cracked	92.40 F	*92.40 FL
16	1		*REAR FLOOR PANEL TOP BOARD (WARPED) (NPA)	Not Changed	0.00 F	*- FL
17	1		*REAR FENDER (NPA)	Repair	0.00 F	*- FL
18	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
19	1		*REAR LICENCE PLATE (BENT) (NPA)	Not Changed	0.00 F	*- FL
20	2		*TAILLAMPS	Broken	556.80 F	*556.80 FL
21	2		*TAILLAMP HOUSING PANEL (NPA)	Repair	0.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,760.40	3,760.40
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	356.04
Total Parts (\$\$)	3,760.40	3,404.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	20.00	20.00
2	TO R&R REAR REVERSE SENSOR	New	50.00	50.00
3	TO R&R CUSHION UPHOLSTERY	New	60.00	60.00
4	TO R&R BOOTLID MECHANISM	New	60.00	60.00
5	TO SPRAY RUST PROOFING	New	60.00	60.00
6	LABOUR FOR PANEL BEATING	New	800.00	800.00
7	SPRAY PAINTING	New	1,000.00	1,000.00
			Gross Labour Cost (\$\$)	2,050.00
				2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >