

116981Ag

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

16-Nov-21

Our ref : TP/5052/21

Han Bing

TP Chinn

Uelia

NISP1707044132

RE : estimate cost for vehicle no : SLM 5344P

1 pc	tailgate <i>Distard</i>	\$	1,132.20 ✓
1 pc	tailgate logo <i>new</i>		72.20 ✓
1 pc	tailgate lock <i>Repd</i>		467.00 ✓ <i>372</i>
1 pc	tailgate outer garnish <i>Repld</i>		283.00 ✓
1 pc	tailgate inner handle <i>new</i>		30.20 ✓
1 pc	tailgate w/strip <i>cut</i>		385.00 ✓
2 pcs	tailgate reflector <i>lit cut</i>		669.00 <i>334.50</i>
1 pc	tailgate trimboard <i>new</i>		138.00 ✓
2 pcs	rear no plate lamp <i>new</i>		128.20 ✓
2 pcs	taillamp <i>lit cut</i>		1,029.60 <i>514.80</i>
1 pc	rear bumper <i>Repld</i>		418.20 ✓
2 pcs	rear bumper retainer <i>new</i>		141.00 ✓
2 pcs	rear bumper holder <i>new</i>		120.00 ✓
2 pcs	rear bumper pad rh lh <i>cut</i>		258.20 ✓
1 pc	rear bumper centre pad <i>Repld</i>		190.00 ✓
1 pc	rear bumper tow hook cover <i>cut</i>	<i>5969</i>	32.00 ✓
2 pcs	rear bumper reflector <i>new</i>		119.60 ✓
4 pcs	rear bumper clips <i>new</i>	<i>4476.75</i>	20.00 ✓
1 pc	tool box <i>Repld</i>		432.40 ✓ <i>371</i>
1 pc	key lock sensor <i>Repd</i>		135.00 ✓
<i>photo</i> 1 pc	end panel <i>Repld</i>		890.20 ✓ <i>686</i>
1 pc	end panel inner garnish <i>Repld</i>		147.50 ✓
1 pc	spare tyre cardboard <i>Repld</i>		466.40 ✓
			<hr/> 7,704.90
		less 25%	<hr/> 1,926.23
			<hr/> 5,778.67
1 pc	rear w/screen gum <i>new</i>		50.00 <i>snett</i> ✓
1 pc	rear w/screen seal <i>new</i>	<i>320</i>	30.00 ✓
1 pc	reverse sensor <i>Repd</i>		250.00 <i>200</i>
1 pc	camera <i>new</i>		400.00 ✓
1 pc	rear no plate <i>Repld</i>		40.00 ✓
	Panel beating.		1,000.00 <i>900</i>
	Spray painting.		1,000.00 <i>800</i>
			<hr/> 8,548.67

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : SLM 5344P

Bal brought forward: \$ 8,548.67

Wiring.	30.00 ✓
Rust proofing.	80.00 ⁶⁰
Upholstery.	120.00 80 ✓
Transfer tailgate fitting.	80.00 ✓
Remove & refit rear w/screen.	120.00 ✓

8,978.67

Plus 7% GST

628.51

9,607.18

2070

SD : Nine thousand six hundred seven & cents eighteen only.

Adrian Lj

L/S 16/11/21

06 Days

total: 6866.75

L/S: \$5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: