

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Nov 2021 13:33	<b>CIm Veh Model Changed</b>		[ ] Merimen Administrator
2	15 Nov 2021 13:33	<b>CIm Created</b>	Reg No: SMP5965U. Policy No: 1900171694-01. Acct Date: 2021/11/12. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R21BF0002	[I] Merimen Administrator
3	17 Nov 2021 10:03	<b>CIm Registration Modified</b>	Setl.Type:3->0. Claim Type:SC->OD.	[ ] NA MENG YAN
4	17 Nov 2021 10:03	<b>Adj CIm Retrieved</b>	Adj: LKK Auto Consultants Pte Ltd (HQ)	[ ] NA MENG YAN
5	17 Nov 2021 10:03	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):	[A] NA MENG YAN
6	17 Nov 2021 10:03	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2021/11/26	[A] NA MENG YAN
7	17 Nov 2021 10:03	<b>Adj Mandate Set</b>	Approved:0.00.Reinsp:Adj decides.	[A] NA MENG YAN
8	17 Nov 2021 10:03	<b>CIm Registration Modified</b>	Rep:1137->200611.	[A] NA MENG YAN
9	17 Nov 2021 10:03	<b>CIm Veh Model Changed</b>	(206496) AUDI A5 2.0 SB TFSI S TRONIC (DESIGN) (A).	[A] NA MENG YAN
10	17 Nov 2021 10:03	<b>Adj Adjuster Assigned</b>	[None] -> ADRIAN LING	[A] NA MENG YAN
11	17 Nov 2021 11:09	<b>Adj Rpt Initiated</b>		[A] HUEY YON
12	17 Nov 2021 11:09	<b>CIm Dtl Modified</b>	Claim Conclusion: -> 3.	[A] HUEY YON
13	17 Nov 2021 11:09	<b>CIm Dtl Modified</b>	JPJ Reg. Date: -> 2019/09/30.	[A] HUEY YON
14	17 Nov 2021 11:09	<b>CIm Details Notified</b>		[A] HUEY YON
15	17 Nov 2021 11:39	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2021/11/26	[A] Tan Hui Zhen
16	17 Nov 2021 11:40	<b>Adj Mandate Request</b>	Cur.Req:15571.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REP AIR.	[A] Tan Hui Zhen
17	17 Nov 2021 16:28	<b>CIm Registration Modified</b>	Init.Est.->5,000 - 6,000. Excess: -> 1600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Hor, Yinrul
18	18 Nov 2021 10:10	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2021/11/26. Mandate Remarks: Vehicle may commence repair - proper documentation of survey photos and repair process require Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency.	[I] Lim, Kok-Chong
19	18 Nov 2021 10:10	<b>Adj Mandate Set</b>	Approved:14949.00:Vehicle may commence repair - proper documentation of survey photos and repair process require Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW	[I] Lim, Kok-Chong

Date From  Date To  Audit Type

ACTIVITY
No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2741560	17 Nov 2021 11:09:40	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMP5965U		11.00

