



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5965 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	1000 ✓
4	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND LHS FRONT FENDER.	\$ 3,500.00	1650 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 7,772.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5965 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Delud</i>	1	\$ 2,251.00	✓ 1,800.80
2	FRONT BUMPER FIXING PARTS <i>3 new</i>	1	\$ 407.00	+
3	FRONT BUMPER SECURING STRIP <i>2 new</i>	2	\$ 71.00	+
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 196.00	+
5	FRONT BUMPER CLOSING ELEMENT LOWER - CENTER <i>new</i>	1	\$ 228.00	+
6	FRONT BUMPER AIR GUIDE - LH <i>new</i>	1	\$ 63.00	+
7	RADIATOR GRILLE <i>new</i>	1	\$ 2,326.00	+
8	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>3 new</i>	2	\$ 102.00	+
9	FRONT RADIATOR GRILLE UPPER BRACKET <i>new</i>	1	\$ 189.00	+
10	FRONT AIR GUIDE - LH <i>new</i>	1	\$ 474.00	+
11	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 124.00	+
12	FRONT BUMPER REINFORMENT BEAM <i>new</i>	1	\$ 845.00	+
13	FRONT BUMPER GUIDE SECTION - LH <i>?</i>	1	\$ 36.00	✓ 28.72
14	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 127.00	+
15	"CAUTION" STICKER <i>new</i>	1	\$ 14.00	+
16	AIRCON STICKER <i>new</i>	1	\$ 8.00	+
17	FRONT BUMPER LOCK CARRIER <i>new</i>	1	\$ 137.00	+
18	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2	\$ 58.00	+
19	HORN - LH <i>new</i>	1	\$ 126.00	+
20	HORN BRACKET - LH <i>new</i>	1	\$ 29.00	+
SUB TOTAL SPARE PARTS		:	\$ 7,811.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5965 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT PARKING AID SENSOR	1	TBC		X
22	FRONT PARKING AID SENSOR SEAL RING	4	\$	14.00	X
23	FRONT FENDER - LH <i>Dented</i>	1	\$	1,060.00	✓ 848.00
24	FRONT FENDER ATTACHEMENT PARTS <i>new</i>	1	\$	53.00	+
25	FRONT FENDER CLOSING ELEMENT - LH <i>new</i>	1	\$	74.00	✓ 59.04
26	FRONT FENDER BRACKET CENTER - LH <i>new</i>	1	\$	35.00	✓ 27.92
27	POP RIVET ?	5	\$	17.00	?
28	FRONT FENDER BRACE - LH ?	1	\$	118.00	✓ 94.40
29	FRONT FENDER BRACKET - LH ?	1	\$	49.00	?
30	FRONT FENDER TRIM - LH <i>new</i>	1	\$	164.00	✓ 130.80
31	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$	275.00	X
32	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS <i>new</i>	1	\$	169.00	+
33	FRONT WHEEL SPOILER - LH ?	1	\$	73.00	+
34	FRONT SPOILER - LH ?	1	\$	35.00	+
35	FRONT FENDER FLEDGE COVER - LONG ?	1	\$	36.00	?
36	FRONT FENDER FLEDGE COVER - SHORT ?	1	\$	16.00	✓ 12.24
37	BONNET <i>Repair</i>	1	\$	3,312.00	X
38	CAP NUT <i>Not new</i>	6	\$	24.00	+
39	BONNET ATTACHEMENT PARTS ?	1	\$	123.00	X
40	BONNET HINGE - LH / RH ?	2	\$	838.00	X
SUB TOTAL SPARE PARTS			:	\$ 6,485.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5965 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>NP</i>	3	\$	84.00	<i>+</i>
42	BONNET STRIKER <i>NP</i>	1	\$	50.00	<i>+</i>
43	BONNET LOCK <i>NP</i>	1	\$	214.00	<i>+</i>
44	HEADLIGHT - LH <i>cut</i>	1	\$	7,902.00	<i>✓</i> 6,321.60
45	HEADLIGHT CONTROL UNIT <i>NP</i>	1	\$	751.00	<i>+</i>
46	HEADLIGHT POWER MODULE <i>NP</i>	1	\$	758.00	<i>+</i>
47	HEADLIGHT HEAT SINK - LH <i>NP</i>	1	\$	1,153.00	<i>+</i>
48	HEADLIGHT SPACER <i>NP</i>	3	\$	122.00	<i>+</i>
49	LIFT CYLINDER - LH <i>NP</i>	1	\$	198.00	<i>+</i>
50	LIFT CYCLINER HOSE <i>NP</i>	1	\$	86.00	<i>+</i>
51	FRONT NO PLATE <i>NP</i>	S/N	\$	60.00	<i>+</i>
52	SUNDRIES <i>?</i>		\$	350.00	<i>✓</i> 13.20
TOTAL SPARE PARTS		:	\$	26,024.00	
TOTAL LABOUR CHARGES		:	\$	7,772.00	
GRAND TOTAL		:	\$	33,796.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King.
SURVEYED DATE : 16/11/21.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 04 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: