

Car-in

wip: 53471

13/12/21

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIQ - Hui Zhen.   
- 4 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5965 U

| S/N                          | PARTS DESCRIPTION                                       | QTY | DAMAGED PARTS & PRICES |                    | REMARKS |
|------------------------------|---|-----|------------------------|--------------------|---------|
|                              |   |     | S                      | NETT               |         |
| 1                            | FRONT BUMPER <i>Repld</i>                               | 1   | S                      | 2,251.00           | ✓       |
| 2                            | FRONT BUMPER FIXING PARTS <i>3 new</i>                  | 1   | S                      | 407.00             | +       |
| 3                            | FRONT BUMPER SECURING STRIP <i>2 new</i>                | 2   | S                      | 71.00              | +       |
| 4                            | FRONT BUMPER GRILLE - CENTER <i>new</i>                 | 1   | S                      | 196.00             | +       |
| 5                            | FRONT BUMPER CLOSING ELEMENT LOWER - CENTER <i>new</i>  | 1   | S                      | 228.00             | +       |
| 6                            | FRONT BUMPER AIR GUIDE - LH <i>new</i>                  | 1   | S                      | 63.00              | +       |
| 7                            | RADIATOR GRILLE <i>new</i>                              | 1   | S                      | 2,326.00           | +       |
| 8                            | FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>2 new</i> | 2   | S                      | 102.00             | +       |
| 9                            | FRONT RADIATOR GRILLE UPPER BRACKET <i>new</i>          | 1   | S                      | 189.00             | +       |
| 10                           | FRONT AIR GUIDE - LH <i>new</i>                         | 1   | S                      | 474.00             | +       |
| 11                           | FRONT BUMPER FOAM FILLER PIECE <i>new</i>               | 1   | S                      | 124.00             | +       |
| 12                           | FRONT BUMPER REINFORMENT BEAM <i>new</i>                | 1   | S                      | 845.00             | +       |
| 13                           | FRONT BUMPER GUIDE SECTION - LH <i>Repld</i>            | 1   | S                      | 36.00              | ✓       |
| 14                           | FRONT BUMPER TOP COVER <i>new</i>                       | 1   | S                      | 127.00             | +       |
| 15                           | "CAUTION" STICKER <i>new</i>                            | 1   | S                      | 14.00              | +       |
| 16                           | AIRCON STICKER <i>new</i>                               | 1   | S                      | 8.00               | +       |
| 17                           | FRONT BUMPER LOCK CARRIER <i>new</i>                    | 1   | S                      | 137.00             | +       |
| 18                           | FRONT BUMPER SUPPORT - LH / RH <i>new</i>               | 2   | S                      | 58.00              | +       |
| 19                           | HORN - LH <i>new</i>                                    | 1   | S                      | 126.00             | +       |
| 20                           | HORN BRACKET - LH <i>new</i>                            | 1   | S                      | 29.00              | +       |
| <b>SUB TOTAL SPARE PARTS</b> |   |     | <b>:</b>               | <b>\$ 7,811.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5965 U

| S/N                          | PARTS DESCRIPTION                                      | QTY | DAMAGED PARTS & PRICES |                 |
|------------------------------|--|-----|------------------------|-----------------|
|                              |  |     | S/NETT                 | REMARKS         |
| 21                           | FRONT PARKING AID SENSOR <i>3 new</i>                  | 1   | TBC                    | x               |
| 22                           | FRONT PARKING AID SENSOR SEAL RING                     | 4   | \$                     | 14.00 x         |
| 23                           | FRONT FENDER - LH <i>Dented</i>                        | 1   | \$                     | 1,060.00 ✓      |
| 24                           | FRONT FENDER ATTACHEMENT PARTS <i>new</i>              | 1   | \$                     | 53.00 +         |
| 25                           | FRONT FENDER CLOSING ELEMENT - LH <i>new Dented</i>    | 1   | \$                     | 74.00 ✓         |
| 26                           | FRONT FENDER BRACKET CENTER - LH <i>new Dented</i>     | 1   | \$                     | 35.00 ✓         |
| 27                           | POP RIVET ?  | 5   | \$                     | 17.00 ?         |
| 28                           | FRONT FENDER BRACE - LH <i>Best.</i>                   | 1   | \$                     | 118.00 ✓        |
| 29                           | FRONT FENDER BRACKET - LH <i>Dented</i>                | 1   | \$                     | 49.00 ✓         |
| 30                           | FRONT FENDER TRIM - LH <i>new</i>                      | 1   | \$                     | 164.00 ✓        |
| 31                           | FRONT WHEEL HOUSING LINER - LH <i>new</i>              | 1   | \$                     | 275.00 x        |
| 32                           | FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS <i>new</i> | 1   | \$                     | 169.00 +        |
| 33                           | FRONT WHEEL SPOILER - LH <i>new</i>                    | 1   | \$                     | 73.00 +         |
| 34                           | FRONT SPOILER - LH <i>new</i>                          | 1   | \$                     | 35.00 +         |
| 35                           | FRONT FENDER FLEDGE COVER - LONG ?                     | 1   | \$                     | 36.00 ?         |
| 36                           | FRONT FENDER FLEDGE COVER - SHORT <i>delivered.</i>    | 1   | \$                     | 16.00 ✓         |
| 37                           | BONNET <i>Repair</i>                                   | 1   | \$                     | 3,312.00 x      |
| 38                           | CAP NUT <i>Not new</i>                                 | 6   | \$                     | 24.00 +         |
| 39                           | BONNET ATTACHEMENT PARTS ?                             | 1   | \$                     | 123.00 x        |
| 40                           | BONNET HINGE - LH / RH <i>Not new</i>                  | 2   | \$                     | 838.00 ✓        |
| <b>SUB TOTAL SPARE PARTS</b> |  | :   | \$                     | <b>6,485.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

*Adrian Lij*  
*Reneyed.*  
*[Signature]*